

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#4172/#5837C16393201021001L	1/12/2010	Deductible	\$ 500.00	Insured-cash			
#4172/#5837C16393201021001L	1/12/2010	Estimate	\$ 531.88	Nationwide-1/12/2010			
#4172/#5837C16393201021001L	1/22/2010	Supplement 1	\$ 36.57	Nationwide-1/22/2010			
#4172/#5837C16393201021001L	1/22/2010	Crawford's Estimates	7 55.61		\$ 1,224.75	\$ 156.30	refinishing mat'l required (new part); allied mat'l required (new part)
#4350/#014882351-01	5/20/2010	Deductible	\$ 100.00	Insured-check			
#4350/#014882351-01	3/20/2010	Estimate	\$ 2.591.05				
#4350/#014882351-01	9/30/2010	Supplement 1		Liberty-10/1/2010			
#4350/#014882351-01	10/8/2010	Supplement 2	\$ 1,101.55				
#4350/#014882351-01	10/27/2010	Supplement 3	\$ 270.69				
#4350/#014882351-01	10/27/2010	Prelim Supp 4	\$ 756.42	Liberty-7/1/2011			
#4350/#014882351-01	10/29/2010	Crawford's Estimates			\$ 10,496.56	5 1,344.74	windshield, shaded (sublet repair); panel, bodyside otr rt (blend refinish); mldg, front door sca lt (new part); pnl, rear door outer lt (blend refinish); bandle, rr door oute lt (R&I assembly); w/strip, glass panel (R&I assembly); back glass, heated (sublet repair); panel, quarter lt (repair); n/plate, deck lid (new part); lens, tail lamp outer lt (R&I assembly); rear bumper assy R&I (addnl labor oper); supt, rr bumper cove lt (R&I assembly); supt, rr bumper cove rt (R&I assembly); corrosion protection (economy part); roof seal underside (refinish); hood seal underside (refinish); decklid seal underside (refinish) roof underside (refinish); rewrite inspection st (sublet repair); layback left s/airbag (addnl labor oper); layback right s/airbag (addnl labor oper); it upr rail/outer (repair); rt upr rail/outer (repair); reweld roof reinf (addnl labor oper); prewash to refinish (addnl labor oper); refinishing mat'l required (new part); allied mat'l required (new part)
#4390/#38-M007-97501	10/18/2010	Estimate	\$ 1,431.42	Insured-10/29/2010			
#4390/#38-M007-97501	10/22/2010	Supplement 1	\$ 381.50	Insured-10/29/2010			
#4390/#38-M007-97501	11/4/2010	Supplement 2	\$ 14.31	State Farm-11/3/2010			
#4390/#38-M007-97501	10/29/2010	Crawford's Estimates			\$ 2,260.30	\$ 433.07	panel, bodyside trim It (R&I assembly); glass, quarter shade It (R&I assembly); color tint (refinish); clean for delivery (addnl labor oper); disconnect battery (addnl labor oper); masking for primer (economy part); reset electrical comp (addnl labor oper); mask jams (addnl labor oper); clr/snd/buff l.qtr.pnl (addnl labor oper); prewash to refinish (addnl labor oper); allied mat as req (economy part); ref.mat.as req (economy part)
#4326/#0214866680000000006001	11/19/2010	Deductible	\$ 500.00	Insured-11/19/2010			
#4326/#0214866680000000006001	8/20/2010	Estimate	\$ 16,523.23			1	
#4326/#0214866680000000006001	10/21/2010	Supplement 1	\$ 677.80	State Farm-10/25/2010		1	
#4326/#0214866680000000006001	11/2/2010	Supplement 2	\$ 1,784.05	State Farm-11/3/2010			
#4326/#0214866680000000000001	11/2/2010	Prelim Prior Estimate	\$ 2,321.47	State Farm-11/9/2010		-	
#4326/#021486668000000006001	11/5/2010	Supplement 3	\$ 28.40	State Farm-11/9/2010		1	
#4326/#0214866680000000006001	11/10/2010	Supplement 4	\$ 250.75	State Farm-11/17/2010			

A 441.66 end, iter ond outer If (rees part); prift, retainer (new part); the bomper cover ret (rees part); barry to the, floating many it referred (rees part); barry to the, floating many it referred (rees part); barry (float somethy); barry (float somethy); candidate (reap part); barry (float somethy); candidate (float somethy); candidate (float somethy); candidate (float somethy); barry (float somethy); candidate (float somethy); barry (float somethy);

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 3 of 23 PageID 1950

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payn	nent made	Paid by	Cra	wford's total	Sho	ortfall	Shortfall Itemization
#4451/#38M072147	1/20/2011	Deductible	\$	500.00	Insured-2/4/2011					
#4451/#38M072147	1/20/2011	Estimate	\$	2,277.92	State Farm-1/20/2011					
#4451/#38M072147	1/26/2011	Supplement 1	\$	549.50	State Farm-1/26/2011					
#4451/#38M072147	2/3/2011	Supplement 2	\$	106.27	State Farm-2/3/2011					
#4451/#38M072147	2/15/2011	Supplement 3	\$	5.15	State Farm-2/16/2011					
#4451/#38M072147	2/4/2011	Crawford's Estimates				\$	3,900.14	\$	466.45	shell, tailgate (repair); glass, tailgate heated (sublet repair); mldg, t/gate garnish (R&I assembly); panel, rear body (repair); bulb, license lamp It (new part); bulb, license lamp rt (new part); tape, rear bumper (new part); refinishing mat'l requ (new part);
#4509/#018372075-01		Deductible	\$	1.000.00	Insured-4/26/2011					
#4509/#018372075-01		Estimate	\$		Liberty-4/8/2011					
#4509/#018372075-01	4/6/2011	Supplement 1	\$	(203.97)	/ / - /			t		
#4509/#018372075-01	4/25/2011	Supplement 2	\$		Liberty-4/26/2011					
#4509/#018372075-01	4/26/2011	Crawford's Estimates				\$	9,962.69	\$	1,081.28	brkt, rad supt lower It (repair); cover,front bumper (new part); latch, hood panel It (new part); latch, hood panel rt (new part); ret, hood lock cable It (new part); ret. hood lock cable It (new part); ret. hood lock cable rt (new part); crsmbr, rad panel upr (new par); brkt, rad supt lower It (refinish); brkt, rad pnl mounti It (new part); fan assy, eng cooling (R&I assembly); skirt, inner fender It (R&I assembly); skirt, inner fender It (R&I assembly); seal, inner fender It (new part); mldg, rocker panel It (R&I assembly); mldg, rocker panel rt (R&I assembly); setup & measure (repair); unibody - frame alignment (repair); color, sand & buff (refinish); vanity plate mldg (new part); glovebox ins. #203680002 (new part); refinishing mat'l require (new part); allied mat'l required (new part); glovebox ins. #203680002 (new part); resenup for delivery (addnI labor oper); masking for primer (economy part); layback harness (addnI labor oper); cover for overspray (new part); reset elecrical comp. (addnI labor oper); check and diagnose fans (addnI labor oper) install glove box gear (addnI labor oper); dress welds (addnI labor oper); dress pinch welds (refinish); mask jams (addnI labor oper)
#4366/#38-L980-44001	11/2/2011	Deductibe	\$		Insured-5/27/2011					
#4366/#38-L980-44001	11/2/2011	Estimate	\$	5,132.52	State Farm-11/3/2010					

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 4 of 23 PageID 1951

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Paym	ent made	Paid by	Crawfo	rd's total	Shortfa	all	Shortfall Itemization
#4366/#38-L980-44001	1/6/2011	Supplement 1	\$	958.11	State Farm-1/6/2011					
#4366/#38-L980-44001	3/15/2011	Supplement 2	\$	110.89	Pending					
#4366/#38-L980-44001	4/4/2011	Supplement 3	\$	217.27	State Farm-4/5/2011					
#4366/#38-L980-44001	4/14/2011	Supplement 4	\$	145.58	State Farm-4/15/2011					
#4366/#38-L980-44001	5/27/2011	Crawford's Estimates				\$	8,438.14	\$ 1,		panel, hood (refinish); w/strip, hood panel It (R&I assembly); w/strip, hood panel rt (R&I assembly); brkt, front fender rt (refinish); windshield, shaded (sublet repair), frame, windshield upr (refinish); frame, windshield up It (repair); frame, windshield up It (refinish); panel assy, body sid rt (refinish); panel, innder cowl tr rt (R&I assembly); front door R&I rt (R&I assembly); w/strip, front door It (R&I assembly); w/strip, front door rt (R&I assembly); pnl lock trim rt (R&I assembly); color sand & buf f(addnl labor oper); disconnect battery (addnl labor oper); differential noise (repair); collision access labor (addnl labor oper); masking for primer (economy part); refinishing mat'l require (new part); allied mat'l required (new part)
#4543/#38-M145-433	6/13/2011	Deductible								
#4543/#38-M145-433	6/13/2011	Estimate	\$	1,883.19	State Farm-6/14/2011					
#4543/#38-M145-433	6/21/2011	Supplement 1	\$	201.01	State Farm-6/22/2011					
#4543/#38-M145-433	6/22/2011	Crawford's Estimates				\$	2,412.59	\$		mldg, rear door side It (refinish); mldg, rear door side It (R&I assembly); mask jams (addnl labor oper); masking for primer (economy part); 3M heavy steam sealer (new part); refinishing mat'l required (new part); allied mat'l required (new part); cover car exterior (sublet repair); cleanup for delivery (addnl labor oper); reset electrical comp (adnl labor oper); disconnect battery (addnl labor oper); sound deadner material (economy part)
#4609/#000214712135B03	8/25/2011	Deductible								
#4609/#000214712135B03 #4609/#000214712135B03	8/25/2011	Estimate	\$	7 869 14	Allstate-9/8/2011	+				
#4609/#000214712135B03 #4609/#000214712135B03	9/12/2011	Supplement 1			Allstate-9/12/2011	+				
#4609/#000214712135B03	9/26/2011	Supplement 2	+		Allstate-9/26/2011	1				
,	-, -0, -011	1 P P	Ÿ	_,	50000 5, = 5, 2011	1		1		
#4609/#000214712135B03	10/6/2011	Supplement 3	\$	2,903.63	Allstate-10/6/2011					

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 5 of 23 PageID 1952

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Paymen	t made	Paid by	Craw	ford's total	Sho	rtfall	Shortfall Itemization
#4609/#000214712135B03	10/12/2011	Crawford's Estimates				\$	17,164.58	<u> </u>	1,372.32	switch sliding door rt (R&I assembly); pnl assembly, inr fn rt (refinish); reinf, inner fender rt (refinish); cradle, engine (new part); manifold, exhaust (R&I assembly); suspension align, frt (addnl labor oper); suspension R&I lt I/f (addnl labor oper); disc, front brake lt (R&I assembly); arm, lower control I/f (R&I assembly); vent gls assembly, f rt (new part); vent gls assembly); vent gls assembly, f rt (new part); vent gls assembly, f rt (sublet repair); gusset, hinge pillar rt (refinish); pnl, rckr & plr, cent rt (refinish); mldg, rear door scalr/r (repair); tape, rear door rt (repair); striker, rear lock rt (R&I assembly); w/strip, roof rt (R&I assembly); tire, rf, balance (sublet repair); michelin primacy MXV5 rf (new part); remove adh on w/strip (addnl labor oper); retape w/o mldg (economy part); remove tape door applique (addnl labor oper); fabrication plates (addnl labor oper); disconnect battery (addnl labor oper); masking for primer (economy part); reset electrical comp (addnl labor oper); retape 2 mlgs (addnl labor oper); masking for pinch welds (addnl labor oper)
Repair Order #/Ins. Co. Claim #	Invoice date	Invoice tune	Invoice t	etal	Paid by	Cum	ulativa tatal	Cho	rt fall	Shortfall Itemization
Repair Order #/ins. Co. Claim #	invoice date	Invoice type	Invoice t	otai	Paid by	Cumi	ulative total	Sno	гстан	Snortrail itemization
#4637/#5837E37832910021101P/R1	10/4/2011	Deductible		500.00	Insured-10/20/2011					
#4637/#5837E37832910021101P/R1	10/4/2011	Estimate		006.58	Nationwide-10/4/2011					
#4637/#5837E37832910021101P/R1	10/11/2011	Supplement 1	\$ 2	250.58	Nationwide-10/11/2011	ļ		ļ.,		
#4637/#5837E37832910021101P/R1	10/20/2011	Crawford's Estimates				\$	2,495.24	\$		corrosion protection (new part); color tint (refinish); color sand & buff (repair); cleanup for delivery (addnl labor oper); disconnect battery (addnl labor oper); masking for primer (economy part); reset electrical comp (addnl labor oper); mask jams (addnl labor oper); door shell, front (repair)
					1 0/16/5					
#4573/#5837E26675007071101M/S1		Deductible	<u> </u>	250.00	Insured-9/16/2011	<u> </u>		ļ		
#4573/#5837E26675007071101M/S1		Estimate	\$ 5,4	199.73	Nationwide-7/11/2011	L		1		

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 6 of 23 PageID 1953

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payr	ment made	Paid by	Craw	ford's total	Sh	ortfall	Shortfall Itemization
#4573/#5837E26675007071101M/S1 7	7/11/2011	Supplement 1	\$	369.32	Nationwide-7/11/2011					
#4573/#5837E26675007071101M/S1 7	7/28/2011	Supplement 2	\$	2,014.38	Nationwide-7/29/2011					
#4573/#5837E26675007071101M/S1	8/19/2011	Supplement 3	\$	633.44	Nationwide-8/22/2011					
#4573/#5837E26675007071101M/S1	8/29/2011	Supplement 4	\$	319.37	Nationwide-8/29/2011					
#4573/#5837E26675007071101M/S1	9/16/2011	Supplement 5	\$	1,386.25	Nationwide-9/16/2011					
	9/16/2011	Crawford's Estimates				\$	16,914.81	\$		frt bumper cvr overhaul (addnl labor opera); cover, front bumper (refinish); w/strip, grille upper (R&I assembly); headlamps aim (addnl labor opera); lamp assembly, fog lt (R&I assembly); lamp assembly, fog rt (R&I assembly); panel, hood (salvage part); panel, hood (refinish); hood panel R&I (R&I assembly); label, radiator support (19257194 GM part); hsg, blower (R&I assembly); fender, front rt (refinish); windshield, tinted (sublet repair); panel assy, body sid lt (repair); panel assy, body sid lt (repair); panel assy, body sid lt (refinish); grille, inst pnl spkr (R&I assembly); compt, glove box (R&I assembly); duct, air inlet (R&I assembly); duct, air inlet lt (R&I assembly); outlet, air vent duct (R&I assembly); panel, instrument (R&I assembly); pnl, inst cluster (R&I assembly); bezel, instrument pnl (R&I assembly); control unit, radio (R&I assembly); amplifier, radio (R&I assembly); display unit, inst pnl (R&I assembly); frame, rear seat rt (R&I assembly); frame, front seat lt (R&I assembly); frame, front seat rt (R&I assembly); pnl lt (R&I assembly); frame, front seat rt (R&I assembly); frame, front seat lt (R&I assembly); applique, frt door f lt (20917056 GM part); glass, front door t lt (15947875 GM part); sound deadner pad (economy part); rear door R&I lt (R&I assembly); mldg, rear door uppel/f (R&I assembly); mldg, rear door belt lt (R&I assembly); applique assy, rear lt (20917054 GM part); panel, roof (15950275 GM part); repair new oem roof pa (repair); refinish inside roof p (refinish); back glass,

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 7 of 23 PageID 1954

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
							heated (sublet repair); panel, quarter It (repair); panel, quarter rt (blend refinish); lid, rear deck (refinish); mldg, deck lid (R&I assembly); n/plate, deck lid (20762641 GM part); n/plate, deck lid (25979750 GM part); taillamp assembly It (R&I assembly); taillamp assembly rt (R&I assembly); lamp, license It (R&I assembly); lamp, license It (R&I assembly); lamp, license rt (R&I assembly); rear bumper cover R&I (addnl labor opera); cover, rear bumper (refinish); brkt, rear bumper mt It (R&I assembly); brkt, rear bumper mt rt (R&I assembly); harness, rear bumper (R&I assembly); snsr, obstacle warn It (R&I assembly); snsr, obstacle warn It (R&I assembly); snsr, obstacle warn It (R&I assembly); cover car exterior (economy part); clean for delivery (addnl labor opera); color, sand & buff (repair); cover car interior (economy part); dis/rec e-harness (addnl labor opera); allied mat'l required (new part); cavity wax (economy part); mask jams (addnl labor opera); masking for primer (economy part); bonding kit (economy part); roof rib adhesive (economy part); wax (addnl labor opera); license plate (R&I assembly); refinishing mat'l requ (new part); refinish inner roof pa (refinish); d&r steering column (addnl labor opera); cover for overspray (new part); disconnect battery (addnl labor opera); engine compartment mas (addnl labor opera); rerpaired (R&I assembly); roof seam sealer (addnl labor opera); cleanup broken glass (addnl labor opera); retape hood ornaments (economy part); prefit welded panel (addnl labor opera); key (new part); labor to program key (sublet repair)

Case 6:14-cv-06016-GAP-TBS Document $\frac{137-5}{20121}$ Filed 08/26/14 Page 8 of 23 PageID 1955

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall itemization
#4702/#38-067F-69901	12/14/2011	Deductible					
#4702/#38-067F-69901	12/14/2011	Estimate	\$ 4,604.99	State Farm-2/17/2012			
#4702/#38-067F-69901	1/10/2012	Supplement 1	\$ 442.59	State Farm-2/17/2012			
#4702/#38-067F-69901	1/23/2012	Supplement 2	\$ (76.76				
#4702/#38-067F-69901	2/17/2012	Crawford's Estimates			\$ 6,669.51	\$ 1,621.63	fender front (new part); mount, engine rear (R&I assembly); mount, engine rear (R&I assembly); suspension align, frt (addnl labor oper);flex additive (economy part); corrosion protection (new part); tire, rf, balance (sublet repair); clean for delivery (addnl labor oper); color, sand, buff (addnl labor oper); remove tape adhesive (addnl labor oper); hazardous waste disposal (sublet repair); reset electrical comp (addnl labor oper); retape mldgs (economy part); tire disposal (sublet repair); touch up bolts (addnl labor oper); tire turanza el42 (new part); clean-up grease @ axle (addnl labor oper); engine cradle diagnose (addnl labor oper); set-up on jack stands (addnl labor oper); mask jams (addnl labor oper); mount, engine rear (R&I assembly); mount, engine rear (R&I assembly); suspension align, frt (addnl labor oper); flex additive (economy part); corrosion protection (new part); tire, rf, balance (sublet repair); clean for delivery (addnl labor oper); color, sand, buff (addnl labor oper); remove tape adhesive (addnl labor oper); hazardous waste dispos (sublet repair); reset electrical comp (addnl labor oper); retape mldgs (economy part); tire disposal (sublet repair); touch up bolts (addnl labor oper); tire turanza el42 (new part); clean-up grease @ axle (addnl labor oper); engine cradle diagnose (addnl labor oper); tow veh for s/f inspec (sublet repair); I front wheel & tire (R&I assembly); set up on jack stands (addnl labor oper); disconnect battery (addnl labor oper); mask jams (addnl labor oper)
#4782/#38-0Z03-88901	5/4/2012	Estimate	\$ 1,000.00	Insured-6/20/2012			
#4782/#38-0Z03-88901	5/4/2012	Estimate		State Farm-5/10/2012			
#4782/#38-0Z03-88901	6/5/2012	Supplement 1		State Farm-6/5/2012			
#4782/#38-0Z03-88901	6/13/2012	Supplement 2		State Farm-6/14/2012			

Case 6:14-cv-06016-GAP-TBS Document $\frac{137-5}{20120}$ Filed 08/26/14 Page 9 of 23 PageID 1956

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall itemization
#4782/#38-0Z03-88901	6/20/2012	Crawford's Estimates			\$ 5,099.74	\$ 795.56	w/strip, belt outer rt (R&I assembly); panel, bedside inner rt (repair); pnl, wheelhouse inne rt (repair); panel, bed front (repair); inside bed panel (refinish); remove adhesive @ gate (addnl labor oper); remove tape @ gate spoile (addnl labor oper); remove tape @ mldg (addnl labor oper); remove adh @ door (addnl labor oper); retape side mldg (addnl labor oper); masking for primer (economy part); weld thu primer (economy part); mask jams (addnl labor oper); refinishing mat'l require (new part) allied mat'l required (new part); cover & mask bed (addnl labor oper); pnl, wheelhouse inne rt (refinish); shall, tailgate (repair); panel, bed front (refinish); stoneguard (economy part); corrosion protection (economy part); glass install. kit (economy part); clean for delivery (addnl labor oper); color, sand, buff (addnl labor oper); cover for overspray (economy part); layback wiring harness (repair); retape spoiler (addnl labor oper); refinish inside bed ledge (refinish); disconnect battery (addnl labor oper); seam sealer (economy part)
#4908/#5837B61800211151201S/H1	11/21/2012	Deductible					
#4908/#5837B618002111512015/H1	11/21/2012	Estimate	¢ 1 E24 00	Nationwide-11/21/2012			
#4908/#5837B618002111512015/H1	11/30/2012	Supplement 1	\$ 1,824.49	Nationwide-11/21/2012			
#4908/#5837B618002111512015/H1	11/30/2012	Supplement 1		Nationwide-11/30/2012			
#4908/#5837B618002111512015/H1	12/5/2012	Crawford's Estimates	2.55.61	11/30/2012	\$ 2,441.74	\$ 617.25	clean for delivery (addnl labor oper); color, sand, buff (addnl labor oper); disconnect battery (addnl labor oper); mask jams (addnl labor oper); masking for primer (economy part); reset electrical comp. (addnl labor oper); test drive (addnl labor oper); refinishing mat'l require (new part); allied mat'l required (new part); cover, front bumper (new part); cover, front bumper (refinish); panel, hood (blend refinish); fender, front rt (new part); pnl, front door oute rt (blend refinish); handle, front door ort (R&I assembly); corrosion protection (economy part); cover car exterior (economy part)
#4866/#5837B50857109121201M/S1	9/20/2012	Deductible	\$ 500.00	Insured-12/8/2012			
#4866/#5837B50857109121201M/S1	9/20/2012	Estimate	\$ 6,496.55	Nationwide-9/28/2012			
#4866/#5837B50857109121201M/S1	10/4/2012	Supplement 1	\$ 3,415.08	Nationwide-10/4/2012			
#4866/#5837B50857109121201M/S1	10/9/2012	Supplement 2	\$ 1,168.10	Nationwide-10/12/2012			
#4866/#5837B50857109121201M/S1	10/19/2012	Supplement 3	\$ 1,143.24				
#4866/#5837B50857109121201M/S1	11/1/2012	Supplement 4	\$ 816.87	Nationwide-11/2/2012			
#4866/#5837B50857109121201M/S1	11/14/2012	Supplement 5	\$ 1,598.83				
#4866/#5837B50857109121201M/S1		Supplement 6	\$ -				
#4866/#5837B50857109121201M/S1	12/3/2012	Supplement 7	\$ 1,004.94	Nationwide-12/4/2012			

Case 6:14-cv-06016-GAP-TBS Document $\frac{137-5}{2012}$ Filed 08/26/14 Page 10 of 23 PageID 1957

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall itemization
#4866/#5837B50857109121201M/S1	11/16/2012	Crawford's Estimates			\$ 20,561.24		unibody frame inc setu (repair); cover front bumper (repair); module hdlmp contro rt (33119STKA01); module, hdlmp contro rt (R&I assembly); panel hood (blend refinish); panl assembly inr fn rt (repair); pnl assembly inr fn rt (refinish); reinf inner fender rt (60614STKA00ZZ); reinf inner fender rt (refinish); fender front rt (60211STKA90ZZ); fender front rt (refinish); skirt inner fender rt (74101STKA00); wheel front rt (salvage part); bracket tire indica rt (R&I assembly); suspension align frt (addnl labor opera); hub front wheel It (44600STKA10); diagnose r/f bearing (addnl labor opera); bearing front wheel It (44300STK951); knuckle steering r/f (51211STKA01); arm lower control r/f (51350STKA03); strut assembly fron rt (51601STKA07); link kit front stab rt (51320STKA03); strut assembly fron rt (51601STKA07); link kit front stab rt (51320STKA01); gear assy steering (53601STKA04); cover steering column (R&I assembly); end tie rod outer r/f (R&I assembly); end tie rod inner l/f (R&I assembly); end tie rod inner l/f (R&I assembly); rein tie rod inner r/f (53010STKA01); end tie rod inner l/f (R&I assembly); panel, hinge pillar rt (repair); panel hinge pillar rt (refinish); pillar hinge rt (refinish); panel, bodyside fron rt (part/partial repl); mldg w/s garnish rt (R&I assembly); pnl rckr & plr cent rt ((abor/part1 repla); pnl rckr & plr cent rt (refinish); plate front sill rt (R&I assembly); pnl rckr & plr cent rt (refinish); plate front sill rt (R&I assembly); pnl center plr trim rt (R&I assembly); door shell front rt (refinish); pnl gfront door tow rt (refinish); pnl grear door outer rt (blend refinish); mldg rear door shell rear rt (refinish); pnl rear door outer rt (blend refinish); mldg rear door belt rt (R&I assembly); mldg rear door outer rt (blend refinish); mldg rear door lower rt (refinish); pnl inner door trim rt (R&I assembly); mldg rear door lower rt (refinish); pnl rear door outer rt (blend refinish); mldg rear door lower rt (refinish); pnl rear door outer rt (R&I assembly); mldg rear door lower rt

Case 6:14-cv-06016-GAP-TBS Document $\frac{137-5}{2012}$ Filed 08/26/14 Page 11 of 23 PageID 1958

Repair Order #/Ins. Co. Claim # Estimate d	date Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall itemization
						laddil labor opera); RR Dumper cvr overhaul (addil labor opera); cover rear bumper (repair); cover rear bumper (refinish); flex additive (economy part); undercoating (new part); tire, rf balance (sublet repair); color sand buff (repair); caulk (economy part); tover car interior (economy part); a/m tire 235/55R18 (economy part); rt roof rail (blend refinish); cover for overspray (economy part); rt roof rail (blend refinish); cover for overspray (economy part); reses welds (addnl labor opera); dress pinch welds (refinish); chipguard (economy part); resetup charge (repair); 2nd setup necessary to ins co. scheduling; adj weld zone at inside rocker flip side; inside rocker (refinish); center pillar (repair); center pillar refinish (refinish); remove personal prop (addnl labor opera); rope-off windshield (addnl labor opera); underside frt wheelhou (repair); ref under wheelhouse (refinish); sound deadner pad (economy part); cavity wax (economy part); refinishing mat'l requ (new part); allied mat'l required (new part); diagnose steering gear (repair); 2nd test drive (addnl labor opera); diagnose failed parts (addnl labor opera); cleanup for delivery (addnl labor opera); disconnect battery (addnl labor opera); masking for primer (economy part); reset electrical comp (addnl labor opera); masking for primer (economy part); reset electrical comp (addnl labor opera); mldg w/garnish (R&I assembly); rt front w/strip (R&I assembly); test drive (addnl labor opera)

Case 6:14-cv-06016-GAP-TBS Document $\frac{1}{2013}$ Filed 08/26/14 Page 12 of 23 PageID 1959

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#4941/#8000886504-1-1	1/2/2013	Deductible		Insured-2/12/2013			
#4941/#8000886504-1-1	1/2/2013	Estimate	\$ 4,370.40	21st Century-1/2/2013			
#4941/#8000886504-1-1	1/25/2013	Supplement 1		21st Century-1/28/2013			
#4941/#8000886504-1-1	2/15/2013	Supplement 2	\$ 2,902.55	21st Century-pd in 3 installments			
				(2/12; 2/15; 3/26)			
#4941/#8000886504-1-1	3/20/2013	Supplement 3	\$ 133.89	21st Century-3/20/2013			
#4941/#8000886504-1-1	2/12/2013	Crawford's Estimates			\$ 10,086.00	\$ 321.18	sheet metal; mech/elec; frame; refinish
#4966/#5837C85958201311301R/R1	2/6/2013	Deductible		Insured-cash			
#4966/#5837C85958201311301R/R1	2/6/2013	Estimate		Nationwide-2/6/2013			
#4966/#5837C85958201311301R/R1	2/22/2013	Supplement 1		Nationwide-2/25/2013			
#4966/#5837C85958201311301R/R1	2/22/2013	Supplement 2	\$ 56.20	Nationwide-2/25/2013			
#4966/#5837C85958201311301R/R1	2/22/2013	Crawford's Estimates			\$ 4,175.25	3 330.20	w/strip, belt outer It (new part); w/strip, belt outer It (R&I assembly); corrosion protection (new part); color tint (refinish); clean for delivery (repair); color, sand, buff (repair); reseal fender foam (economy part); refinishing material required (new part); allied material required (new part); disconnect battery (addnl labor oper); engine compartment masking (addnl labor oper); mask jams (addnl labor oper); masking for primer (economy part); test panel spray out (refinish); foam sealer 3M#8463 (economy part); test drive (addnl labor oper)
HADDA (HIDD DEAC EAADA	2/27/2012	Deductible	ć 530.45	Language 4 / C / 2042			
#4981/#38-2F46-51101 #4981/#38-2F46-51101	2/27/2013 2/27/2013	Estimate	-	Insured-4/6/2013 State Farm-2/28/2013			
#4981/#38-2F46-51101 #4981/#38-2F46-51101	3/5/2013		,	State Farm-2/28/2013 State Farm-3/5/2013			
· · · · · · · · · · · · · · · · · · ·		Supplement 1					
#4981/#38-2F46-51101	3/13/2013	Supplement 2		State Farm-3/14/2013			
#4981/#38-2F46-51101	3/27/2013	Supplement 3		State Farm-3/28/2013			
#4981/#38-2F46-51101	4/3/2013	Supplement 4	\$ 87.01	State Farm-4/5/2013			

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 13 of 23 PageID 1960

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#4981/#38-2F46-51101	4/6/2013	Crawford's Estimates			\$ 12,688.65	\$ 2,514.30	grille, frt bmpr cvr lt (R&I assembly); hose, front brake
							rt (R&I assembly); arm, lower control r/f (new part);
							blade assembly, wipe It (R&I assembly); blade
							assembly, wipe rt (R&I assembly); screen, cowl (R&I
							assembly); rod, front door chec rt (R&I assembly);
							rear door R&I rt (addnl labor oper); color, sand & buff
							(refinish); layback radiator, D&R wiring harness, bleed
							brake system w/ABS, diagnose r/f sus damage (addnl
							labor oper); remove adh @ rr dr mldg (repair);
							remove adh @ rr dr panel (repair); retape rr dr side
							mldg (economy part); dress welds (addnl labor oper);
							dress pinch welds (refinish); masking pinch weld
							repair (addnl labor oper); retape l/side grille
							(economy part); remove tape adh @ rf mldg (addnl
							labor oper); retape r/f door mldg (addnl labor oper);
							lkq changeover applique (R&I assembly); lkq
							changeover belt mldg (R&I assembly); lkq changeover
							scalp mldg (R&I assembly); lkg changeover lowestrip
							(R&I assembly); lkq changeover door handl (R&I
							assembly); Ikq changeover trim panel (R&I assembly);
							lkq changeover glass (R&I assembly); lkq changeover
							motor/reg (R&I assembly); lkg changeover speaker
							(R&I assembly); lkg changeover r/channel (R&I
							assembly); lkq changeover lock (R&I assembly); prep
							lkq door (repair); cover for overspray (new part);
							engine compartment masking (addnl labor oper); rope
							windshield (addnl labor oper); rope back glass (addnl
							labor oper); test drive (addnl labor oper); weld thu
							primer (new part); remove adh @ l/f door (repair);
							remove adh @ I/f mldg (repair); retape I/f mldg
							(economy part); prefit r/f door (addnl labor oper); r/
							& I/ wheel remove (addnl labor oper); r/ & I/ wheel
							install (addnl labor oper)
#5011/#13-1914136-01	4/3/2013	Deductible	\$ 500.00	Insured-paid only partial (\$392.63)			
#5011/#13-1914136-01	4/3/2013	Estimate		Progressive-4/3/2013			
#5011/#13-1914136-01	4/8/2013	Supplement 1		Progressive-4/8/2013			
#5011/#13-1914136-01	4/13/2013	Supplement 2		Progressive-4/12/2013			
#5011/#13-1914136-01	4/26/2013	Supplement 3		Progressive-4/26/2013			
#5011/#13-1914136-01	5/1/2013	Supplement 4	\$ 423.54	Progressive-5/1/2013			
#5011/#13-1914136-01	5/1/2013	Crawford's Estimates			\$ 16,779.78	\$ 615.86	sheet metal; mech/elec; frame; refinish
#5010/#38-2J39-70001	4/3/2013	Deductible	\$ 500.00	Insured-5/10/2013			
#5010/#38-2J39-70001	4/3/2013	Estimate		State Farm-4/4/2013			
#5010/#38-2J39-70001	4/8/2013	Supplement 1		5 State Farm-4/11/2013			

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 14 of 23 PageID 1961

#5010/#38-2J39-70001	
#5010/#38-2J39-70001	
#5010/#38-2J39-70001 5/10/2013 Crawford's Estimates \$ 17,358.92 \$ 4,059.72 unibody frame setup (repair); align, 4 wheel (addnl labor op	
align, 4 wheel (addnl labor op	
(addnl labor oper); color, san oper); kensun, HID coversion compartment mas (addin lab (addnl labor oper); dress pinc harness (new part); disconne oper); shipping HID covers (st harness replace (sublet repail 4/8/13, 4/12/13, 4/23/13 (su) apron section (addnl labor oper); prefix-measure welded (addn (economy part); prefix-measur	per); clean for delivery dand buff (addnl labor (economy part); engine or oper); dress welds the welds (refinish); engine or oper); dress welds the welds (refinish); engine or oper); dadnl labor ublet repair); engine r); tow receipts 4/3/13, ablet repair); separate per); separate per); separate rail weld damage (refinish); all labor oper); cavity wax ure welded (addnl labor part); masking for thu primer (economy ir); tow to sloans #78771 #7884 (sublet repair); b; test panel spray out
#5157/#5873E37832911081301P/R1 12/13/2013 Deductible \$ 500.00	
#5157/#5873E37832911081301P/R1 11/13/2013 Estimate \$ 3,715.79 Nationwide-11/13/2013	
3517/15073E3710013017/11 11/13/2013 Stillate 7 3/13/73 NationWide 11/13/2013	
#5157/#5873F37832911081301P/R1	
#5157/#5873E37832911081301P/R1	

Case 6:14-cv-06016-GAP-TBS Document $\frac{137-5}{2013}$ Filed 08/26/14 Page 15 of 23 PageID 1962

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5157/#5873E37832911081301P/R1	12/13/2013	Crawford's Estimates			\$ 7,583.54	\$ 1,778.57	paint materials capped (refinish); 2nd car cover (new
							part); addt'l paint materials (addnl labor oper);
							absorber, front bumper (new part); hinge, hood panel
							rt (new part); hinge, hood panel rt (refinish); panel
							assembly, rad supt (economy part); brkt, radiator
							mount rt (new part); airbag sensor, front lt (R&I
							assembly); airbag sensor, front rt (R&I assembly); a/c
							evacuate and recharge (addnl labor oper); refrigerant
							rcvry setup (addnl labor oper); fender, front rt
							(refinish); duct, air intake (new part); reservoir, w/s
							washer (R&I assembly); mldg, roof drip rt (new part);
							mldg, roof drip rt (R&I assembly); glass, quarter tinte
							rt (sublet repair); pnl, quarter trim up rt (R&I
							assembly); pnl, qtr trim lower rt (R&I assembly); rear
							bumper cover R&I (addnl labor oper); color, sand and
							buff (repair); cleanup for delivery (addnl labor oper);
							engine compartment masking (addnl labor oper);
							featheredge sand and bloc (addnl labor oper); mask
							jams (addnl labor oper); masking for primer (economy
							part); rope windshield (addnl labor oper); test panel
							spray out (refinish); test drive (addnl labor oper)
#5158/#5837U01199511081301C/F1	12/20/2013	Deductible	\$ 750.00	Insured-12/20/2013			
#5158/#5837U01199511081301C/F1	11/13/2013	Estimate	\$ 5,670.00	Nationwide-11/14/2013			
#5158/#5837U01199511081301C/F1	11/26/2013	Supplement 1	\$ 1,626.08	Nationwide-11/26/2013			
#5158/#5837U01199511081301C/F1	12/19/2013	Supplement 2	\$ 1,520.88	Nationwide-12/20/2013			

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 16 of 23 PageID 1963

5 12,815.97 5 3.244.61 Color tinet (excomorny party), sight shield (new part); it regulator (Risk assembly); the regulator (Risk assembly); part); condenses AV (encomorny part); core crossing (Risk assembly); pared install representations of the regulator (Risk assembly); the condense of the regulator (Risk assembly); the regulator (Ri	Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
			•	Payment made	Paid by			color tint (economy part); sight shield (new part); It Iwr ctr pillar trim (R&I assembly); It regulator (R&I assembly); It door check (R&I assembly); It pressure vent (R&I assembly); label install (addnl labor oper); glove box black (R&I assembly); cover front bumper (new part); brkt front bumper m It (new part); panel hood (refinish); hinge hood panel It (new part); hinge hood panel rt (new part); panel hood panel rt (new part); panel assembly, rad supt (new part); cover rad supt panel (new part); condenser A/C (eonomy part); fender front It (refinish); label engine (new part); steering column O/H (R&I assembly); windshield shaded (sublet repair); mldg assy w/s reveal (new part); arm wiper blade It (R&I assembly); arm wiper blade rt (R&I assembly); console center (R&I assembly); panel instrument (R&I assembly); radio, am/fm w/cd (R&I assembly); pnl, rckr and plr, cent It (refinish); plate front sill It (R&I assembly); plate front sill rt (R&I assembly); plate front sill rt (R&I assembly); mldg front sill t (R&I assembly); plate front sill rt (R&I assembly); mldg front door sca It (new part); glass front door t It (R&I assembly); w/strip belt outer It (R&I assembly); mldg front door sca It (new part); glass front door t It (R&I assembly); rear door It (R&I assembly); silker rear lock It (R&I assembly); rear door R&I It (addnl labor oper); switch rear door It (R&I assembly); stiker rear lock It (R&I assembly); rear door R&I It (addnl labor oper); switch rear door It (R&I assembly); stiker rear lock It (R&I assembly); rear door R&I It (addnl labor oper); switch rear door It (R&I assembly); stiker rear lock It (R&I assembly); rear door R&I It (addnl labor oper); switch rear door It (R&I assembly); stiker rear lock It (R&I assembly); mask part); color sand and buff (repair); glass cleanup (addnl labor oper); freon and oil 134A (economy part); cleanup for delivery (addnl labor oper); seam seal hood (economy part); layback wiring harness (repair); engine compartment maskin (addnl labor oper); test drive (addnl labor

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 17 of 23 PageID 1964

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5183/#5837E3994912011301C/M1	12/23/2013	Deductible					
#5183/#5837E3994912011301C/M1	12/23/2013	Estimate		Nationwide-1/2/2014			
#5183/#5837E3994912011301C/M1 #5183/#5837E3994912011301C/M1	1/23/2014	Supplement 1 Crawford's Estimates	\$ 694.09	Nationwide-1/23/2014	\$ 5,493.63	\$ 1,690.88	front bumper cover R&I (addnl labor opera); pnl center plr trim lt (R&I assembly);
							pnl inner qtr trim It (R&I assembly); color sand buff (repair); test drive (addnl labor oper); prefit I/f door (addnl labor oper); cover for overspray (economy part); featheredge sand and bloc (addnl labor opera); mask james (addnl labor oper); masking for primer (economy part); reset electrical comp (addnl labor oper); test panel spray out (refinish) refinishing mat'l require (new part); allied mat'l required (new part); front fender R&I It (R&I assembly); speaker front door It (R&I assembly); handle rr door oute It (repair); shield quarter inne It (R&I assembly); pnl quarter trim up It (R&I assembly); cleanup for delivery (addnl labor oper); seam seal tape I/r door (economy part); rope back glass (addnl labor oper); rope windshield (addnl labor oper); glass kit (economy part)
						_	
#5172/#13-1753284-01		Deductible		Insured-1/7/2014			
#5172/#13-1753284-01		Estimate	\$ 1,040.69	Progressive-12/13/2013			
#5172/#13-1753284-01		Supplement 1	\$ 91.37	Progressive-12/13/2013			
#5172/#13-1753284-01		Supplement 2	\$ 318.93	Progressive-12/13/2013			
#5172/#13-1753284-01	12/13/2013	Supplement 3	\$ 1,549.47	Progressive-12/13/2013			
#5172/#13-1753284-01	12/24/2013	Supplement 4	\$ 481.13	Progressive-12/24/2013			
#5172/#13-1753284-01	12/31/2013	Supplement 5	\$ 404.93	Progressive-12/31/2013			
#5172/#13-1753284-01	1/7/2014	Crawford's Estimates			\$ 5,130.85	\$ 1,144.43	cvr, front bumper upr (new part); cvr, front bumper lwr (new part); panel, radiator supt (new part); fender, front rt (refinish); color,sand & buff (addnl labor oper); cleanup for delivery (addnl labor oper); raw bumper prep (refinish); mask jams (addnl labor oper); reset electrical comp (addnl labor oper); cover for overspray (economy part); masking for primer (economy part)
#5208/#0372514770101103-01	1/23/2014	Estimate	\$ 1,013.57	GEICO/Deductible-2/10/2014			
#5208/#0372514770101103-01	2/19/2014	Supplement 1	\$ 755.78	Geico-2/19/2014			
#5208/#0372514770101103-01	2/20/2014	Crawford's Estimates			\$ 2,084.07	\$ 314.72	brkt, front bumper m lt (R&I assembly); brkt, front bumper m rt (R&I assembly); panel, hood (new part); color, sand & buff (repair); cleanup for delivery (addnl labor oper); disconnect battery (addnl labor oper); masking for primer (economy part); reset electrical comp. (addnl labor oper); test drive (addnl labor oper); cover for overspray (new part); seam seal hood (economy part)

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 18 of 23 PageID 1965

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5209/#0372514770101095-01	1/23/2014	Estimate	\$ 611.16	GEICO/Deductible-2/20/2014			
#5209/#0372514770101095-01	2/19/2014	Supplement 1		Geico-2/19/2014			
#5209/#0372514770101095-01	2/20/2014	Crawford's Estimates			\$ 2,640.26	\$ 202.61	cover, tow hook access (repair); cover, tow hook access (refinish); headlamp assy, halog It (new part); headlamp assy, halog rt (R&I assembly); headlamps aim (addnl labor oper); duct, air intake (R&I assembly); corrosion protection (new part); color, sand & buff (repair); cleanup for delivery (addnl labor oper); cover for overspray (new part); raw bumper set-up (addnl labor oper); disconnect battery (addnl labor oper); reset electrical comp (addnl labor oper); test panel spray out (refinish);
#5258/#14-4518010-01	5/7/2014	Deductible	\$ 750.00	Insured-5/9/2014	1		
#5258/#14-4518010-01	4/18/2014	Estimate	\$ 990.41	Progressive-4/18/2014	1		
#5258/#14-4518010-01	5/1/2014	Supplement 1	\$ 264.06	Progressive-5/1/2014	1		
#5258/#14-4518010-01	5/7/2014	Crawford's Estimates			\$ 2,874.52	\$ 870.05	cover, front bumper (refinish); cradle, engine (salvage part); shield, heat (new part); shield, engine lower (new part); rear bumper cover R&I (addnl labor oper); clean for delivery (addnl labor oper); color, sand & buff (repair); suspension alignment (sublet repair); diagnose undercarriage (addnl labor oper); paid out chgs & scotthond (sublet repair); allied mat'l required (new part); disconnect battery (addnl labor oper); raw bumper set up (addnl labor oper); reset electrical comp (addnl labor oper)
#E240/#70264472 DE 044	2/4/2014	D - d - still -	\$ 500.00	In accord 2 /4 /2014			
#5218/#Z0261472 DE-011 #5218/#Z0261472 DE-011	3/4/2014 2/14/2014	Deductible		Insured-3/4/2014			
#5218/#20261472 DE-U11	2/14/2014	Estimate	\$ 5,964.77	Encompass-pd in 2 parts \$5,946.77 on 2/14/2014			
				\$18.00 on 3/5/2014			
#5218/#Z0261472 DE-011	2/27/2014	Supplement 1	\$ 1,364.51	Encompass-2/27/2014			
#5218/#Z0261472 DE-011	3/4/2014	Crawford's Estimates			\$ 9,980.39	\$ 2,151.11	suspension align, frt (addnl labor oper); arm, rear suspension lt (new part); cover, front bumper (refinish); fender, front lt (blend refinish); fender, front rt (refinish); seal, front fender lt (R&I assembly); seal, fender-hood lt (R&I assembly); seal, fender-hood lt (R&I assembly); skirt, inner fender lt (R&I assembly); mldg, rocker panel lt (R&I assembly); mldg, rocker panel lt (R&I assembly); mldg, rocker panel rt (R&I assembly); mldg, rocker panel rt (B&I assembly); mldg, rocke
#5232/#14-3504937-01	3/12/2014	Deductible					
	2/25/2014	Estimate	¢ 2724.40	Progressive-2/25/2014	+		
#5232/#14-3504937-01 #5232/#14-3504937-01					+		
#3432/#14-330493/-01	3/13/2014	Supplement 1	φ 18b.15	Progressive-3/13/2014		<u> </u>	

Case 6:14-cv-06016-GAP-TBS Document 137-5, Filed 08/26/14 Page 19 of 23 PageID 1966

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5232/#14-3504937-01	3/12/2014	Crawford's Estimates			\$ 4,609.18		paint and materials (new part); add'l paint and materials (new part); pillar, windshield It (blend refinish); panel, bodyside otr It (blend refinish); speaker, rear door It (R&I assembly); door shell, front It (refinish); mldg, front door low It (R&I assembly); rear door R&I It (addnI labor oper); pnl, rear door outer It (refinish); mldg, rear door lowe It (R&I assembly); pnl, inner door trim It (R&I assembly); reg, rear door glass It (R&I assembly); rail, luggage rack (R&I assembly); panel quarter It (refinish); rear bumper cover R&I (addnI labor oper); corrosion protection (new part); clean for delivery (addnI labor oper); I quarter rivets 4@1.07 (new part); alloy wheel (repair); clean and polish I/r wheel (addnI labor oper); mask jams (addnI labor oper); masking for primer (economy part); reset electrical comp (addnI labor oper); test drive (addnI labor oper); refinishing mat'l require (new part); allied mat'l required (new part)
#5247/#029302898-01	4/3/2014	Deductible	\$ 500.00	Insured-4/5/2014			
#5247/#029302898-01	3/19/2014	Estimate	\$ 2,902.13	Liberty-3/20/2014			
#5247/#029302898-01	4/8/2014	Supplement 1	\$ 335.67	• • •			
#5247/#029302898-01	4/3/2014	Crawford's Estimates			\$ 4,223.01	\$ 820.88	cover, front bumper (new part); headlamps aim (addnl labor oper); reinf, inner fender lt (repair); reinf, inner fender lt (refinish) pnl, inner door trim lt (R&I assembly); mirror, outer r/c lt (R&I assembly); flex additive (new part); color tint (refinish) clean for delivery (repair); cover for overspray (new part); disconnect battery (addnl labor oper); engine compartment masking (addnl labor oper); masking for primer (economy part); prewash to repair (addnl blabnor oper); reset electrical copm (assnl labor oper) chemically strip lkq fend (repair); prep lkq fender (repair); test drive (addnl labor oper); test panel spray out (refinish); refinishing mat'l required (new part); allied mat'l required (new part); lamp assembly, fog lt (economy part); ret, radiator support (new part); fender, front lt (economy part); fender, front lt (refinish); retainer, front fend lt (new part)
#5182/#477533255002-202	4/11/2014	Deductible	\$ 500.00	Insured-4/11/2014			
#5182/#477533255002-202	. , -	Original Ins Amt		Insured-4/11/2014			
#5182/#477533255002-202	3/19/2014	Supplement 2		Safeco-3/20/2014			
#5182/#477533255002-202	4/11/2014	Supplement 3		Safeco-4/14/2014			

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 20 of 23 PageID 1967

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5182/#477533255002-202	41740	Crawford's Estimates			\$ 8,705.82	\$ 1,208.24	midg, fender lower it (R&I assembly); midg, fender lower rt (R&I assembly); w/strip, frt door bo it (R&I assembly); w/strip, frt door bo it (R&I assembly); w/strip, frt door bo it (R&I assembly); insert frt sill pnl (R&I assembly); paint supplies (refinish); cover air cleaner (R&I assembly); insert frt sill pnl (R&I assembly); surroof midg (R&I assembly); rt w/s piller trim (R&I assembly); bumper cover clip (new part); rope glass (repair); leak and wind test (addnl labor oper); mask for hardern (addnl labor oper); mask jambs (addnl labor oper); mask for hardern (addnl labor oper); mask jambs (addnl labor oper); mldg, flare it (R&I assembly); panel hood (new part); panel, hood (refinish); scoop, hood panel (refinish); scoop, hood panel (R&I assembly); nozzle, w/s washer it (R&I assembly); nozzle, w/s garnish it (R&I assembly); nozzle, w/s
Repair Order #/Ins. Co. Claim #	Invoice date	Invoice type	Invoice total	Paid by	Cumulative total	Short fall	Final Invoice Shortfall
#5250/#0319891640101075	4/15/2014	Deductible					
#5250/#0319891640101075	3/28/2014	Estimate		Geico-3/29/2014			
#5250/#0319891640101075	4/18/2014	Supplement 1	\$ 1,331.10	Geico-4/18/2014			
#5250/#0319891640101075	4/15/2014	Crawford's Estimates			\$ 4,989.69	\$ 995.87	door shell, front it (repair); cover, rear bumper (repair); "H" emblem (economy part); allied materials required (new part); headlamp assy, halog it (R&I assembly); wheel, rear it (repair); door shell, front it (refinish); rear door R&I it (addnl labor oper); door shell, rear it (repair); applique assy, rear it (repair); rear vent glass it (R&I assembly); striker, rear lock it (R&I assembly); midg, roof drip it (R&I assembly); talliamp assembly, o it (R&I assembly); rear bumper cover R&I (addnl labor oper); cover, rear bumper (refinish); color tint (refinish); clean for delivery (addnl labor opera); color sand and buff (refinish); seam sealer (repair); it door shell rear (refinish); door skin bonding kit (new part); masking for primer (economy part); reset electrical comp (addnl labor oper); test drive (addnl labor oper); fuel door (refinish) decal & dogleg (new part); retape applique (economy part); door elec harness (R&I assembly); remove stripe adhesive (addnl labor oper); back tape rear glass (addnl labor oper); back tape rear glass (addnl labor oper); back tape rear glass (addnl labor oper); refinishing mat'l requ (new part); sound deadner material (economy part); refinish r/rear wheel (refinish); r/rear wheel masking (repair); R&I tire and wheel (addnl labor oper); masking for seam seale (addnl labor oper)

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 21 of 23 PageID 1968

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5238/#38-3v3948401	4/18/2014	Deductible	\$ 500.00	State Farm-2/24/2014		-	
#5238/#38-3v3948401 #5238/#38-3v3948401	2/24/2014	Estimate		State Farm-2/21/2014			
#5238/#38-3v3948401 #5238/#38-3v3948401	3/7/2014					-	
		Supplement 1	. ,			-	
#5238/#38-3v3948401 #5238/#38-3v3948401	3/17/2014 4/18/2014	Supplement 2		State Farm-3/18/2014 State Farm-4/22/2014		+	
		Supplement 3	\$ 251.14	State Farm-4/22/2014	ć 11.2F0.14	ć F 021 70	tano year dagg et (nous part), clip (nous part), pol ate en pap et (nous part), etc
#5238/#38-3v3948401	6/26/2014	Crawford's Estimates Deductible			\$ 11,250.14	5 5,931.79	tape, rear door rt (new part); cilp (new part); nl, qtr-rr pan rt (new part); qtr glass R&I (R&I assembly); collision pull (addnl labor oper); panel assy, body sid rt (refinish); panel, bodyside fron rt (refinish); door shell, rear rt (blend refinish); reinf, tllmp opening lt (refinish); pnl, wheelhouse oute rt (refinish); chg to re-key supp 3 (addnl labor oper); panel, bodyside otr rt (repair); panel, bodyside otr rt (refinish); panel, rocker rt (refinish); plate, front sid rt (R&I assembly); switch, frt door otter rt (blend refinish); w/strip, rr door low rt (R&I assembly); prl, rear door outer rt (blend refinish); w/strip, rr door low rt (R&I assembly); prl, quarter inner rt (repair); reinf, quarter inner rt (refinish); pnl, qtr-rr pan rt (repair); reinf, qtr panel upp rt (repair); reinf, tllmp opening lt (repair); setn, qtr whl opening rt (refinish); extn, qtr whl opening rt (refinish); extn, qtr whl opening rt (refinish); pnl, qtr-rrim lower ltr (R&I assembly); pnl, qtr trim lower ltr (R&I assembly); pnl, qtr trim lower ltr (R&I assembly); pnl, qtr trim lower rt (R&I assembly); pnl, qtr trim lower rtrim lower rt
#5292/#603990-GA-1							
#5292/#603990-GA-1 #5292/#603990-GA-1	5/29/2014	Estimate	\$ 6,504.66	Nationwide-6/10/2014			
		Estimate Supplement 1	<u> </u>	Nationwide-6/10/2014 Nationwide-6/10/2014			

Case 6:14-cv-06016-GAP-TBS Document 137-5, Filed 08/26/14 Page 22 of 23 PageID 1969

bibor opert, cover engine compartment (feld assembly); mell, with print (Feld assembly); mell, mel	Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5204/#000309921079D01 1/15/2014 Estimate \$ 2,035.73 Allstate-1/6/2014	#5292/#603990-GA-1	6/26/2014	Crawford's Estimates			\$ 13,328.32	\$ 4,467.45	headliner clip (new part); windshield (R&I assembly); insert, rr sill plat it (addnl labor oper); cover engine compartment (R&I assembly); mldg, w/s garnish it (R&I assembly); mldg, w/s garnish rt (R&I assembly); mldg, w/s garnish rt (R&I assembly); mldg, w/s garnish it (R&I assembly); mldg, w/s garnish it (R&I assembly); mldg, w/s garnish it (R&I assembly); masking to cs&b (addnl labor oper); reset airbag code (sublet repair); grille, frt bmpr cvr (R&I assembly); headlamp assy, halog it (R&I assembly); headlamps aim (addnl labor oper); panel, hood (new part); panel, hood (refinish); pad, insulator hood (R&I assembly); fender, front it (refinish); fender, front rt (blend refinish); mldg, w/s reveal sid it (R&I assembly); panel assy, body sid it (refinish); panel assy, body sid it (refinish); panel assy, body sid rt (refinish); headliner R&I (R&I assembly); pnl, center plr trim rt (R&I assembly); w/strip, front door it (R&I assembly); w/strip, rear door it (R&I assembly); w/strip, rear door rt (R&I assembly); w/strip, rear door rt (R&I assembly); m/strip, rear door rt (R&I assembly); m/strip, rear door rt (R&I assembly); cover, sliding roof inr (R&I assembly); shield, quarter inne lt (R&I assembly); gutter, tailgate (refinish); gutter, tailgate rt (refinish); pnl, quarter trim up lt (R&I assembly); hnl, quarter trim up rt (R&I assembly); hnl, quarter trim up rt (R&I assembly); handle, tailgate outer (R&I assembly); mlg, tailgate lower (R&I assembly); handle, tailgate outer (R&I assembly); brkt, rear bumper mt lt (R&I assembly); brkt, rear bu
#5204/#000309921079D01 1/24/2014 Supplement 1 \$ 807.55 Allstate-1/24/2014 \$ \$ 3,722.11 \$ 778.83 electric harness @ jets (R&i assembly); cleanup for delivery (addnl labor oper); disconnect battery (addnl labor oper); reset electrical comp (addnl labor oper); test drive (addnl labor oper); refinishing mat'l require (new part)	#5204/#000309921079D01	1/31/2014	Deductible	\$ 100.00	Insured-1/31/2013			
#5204/#000309921079D01 1/31/2014 Crawford's Estimates \$ 3,722.11 \$ 778.83 electric harness @ jets (R&I assembly); cleanup for delivery (addnl labor oper); disconnect battery (addnl labor oper); reset electrical comp (addnl labor oper); test drive (addnl labor oper); refinishing mat'l require (new part) #5303/#14-5926477-02 6/10/2014 Estimate \$ 2,312.81 Progressive-6/10/2014								
disconnect battery (addnl labor oper); reset electrical comp (addnl labor oper); test drive (addnl labor oper); refinishing mat'l require (new part) #5303/#14-5926477-02 6/10/2014 Estimate \$ 2,312.81 Progressive-6/10/2014	#5204/#000309921079D01	1/24/2014	Supplement 1	\$ 807.55	Allstate-1/24/2014			
	#5204/#000309921079D01					\$ 3,722.11	\$ 778.83	disconnect battery (addnl labor oper); reset electrical comp (addnl labor oper);
	#5303/#14-5926477-02	6/10/2014	Estimate	\$ 2312.81	Progressive-6/10/2014			
#5303/#14-5926477-02 6/30/2014 Supplement 1 \$ 354.36 Progressive-6/30/2014							-	

Case 6:14-cv-06016-GAP-TBS Document 137-5 Filed 08/26/14 Page 23 of 23 PageID 1970

Repair Order #/Ins. Co. Claim #	Estimate date	Payment basis	Payment made	Paid by	Crawford's total	Shortfall	Shortfall Itemization
#5303/#14-5926477-02	7/1/2014	Crawford's Estimates			\$ 3,508.02	\$ 840.85	midg assy wheel opn it (R&I assembly); midg pillar finish it (R&I assembly); door shell front it (new part); door shell front it (refinish); midg front door low it (new part); door shell rear it (blend refinish); midg rear door belt it (R&I assembly); midg rear door side it (R&I assembly); corrosion protection (new part); color sand and buff (repair); prefit/measure bolted pni (addni labor oper); reset electrical comp (addni labor oper); refinishing matl require (new part); allied matl required (new part); it front fender (blend refinish)
WE 200 /W76277826E002	6/11/2014	Estimate	ć 7.507.30	Safaca 6/12/2014			
#5299/#763778265002 #5299/#763778265002	6/11/2014 7/17/2014	Estimate Supplement 1	-	Safeco-6/12/2014 Safeco-7/19/2014		-	
#5299/#763778265002	7/8/2014	Crawford's Estimates			\$ 12,611.38	\$ 2,064.89	brkt headlamp upper It (new part); seat assembly drive It (R&I assembly); lupper ctr pir trim (R&I assembly); I lower ctr pir trim (R&I assembly); add't clearcoat (refinish); add't paint materials (new part); recovery add for ac option (addnl labor oper); cover front bumper (new part); cover front bumper (refinish); reinf front bumper (new part); absorber front energy (new part); emblem grille (new part); brkt headlamp mtg rt (new part); panel hood (new part); panel hood (refinish); catch hood safety (new part); hinge hood panel It (refinish); hinge hood panel rt (refinish); panel assembly rad supt (new part); panel assembly rad supt (refinish); radiator (new part); condenser a/c (new part); label a/c condenser (new part); hose a/c (new part); extension side memb rt (new part) fender front It (refinish); side member assembl rt (refinish) horn low note (R&I assembly); horn high note (new part); sensor oxygen (new part); reservoir w/s washer (R&I assembly); module airbag control (new part); seatbelt front It (new part); door shell front It (blend refinish) housing mirror oute It (R&I assembly); supt frt door handl rt (R&I assembly); supt frt door handl rt (R&I assembly); two tone paint (refinish); corrosion protection (new part); set-up and measure (addnl labor oper); clean for delivery (addnl labor oper)
#5328/#3000912354-1	7/17/2014	Estimate	\$ 1,523.43	21st Century-7/18/14 [payment of			
				\$1534.03]	ļ.	1.	
#5328/#3000912354-1	7/25/2014	Crawford's Estimates			\$ 1,966.68	\$ 432.65	retainer rear bumpe It; retainer rear bumpe rt; mldg rear bumper co rt; flex additive (new part); color tint (refinish); clean for delivery (addnl labor oper); nib sand and polish (repair); admin charge est (addnl labor oper)