

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
7304/33-356G-25702	10/15/2013	Original estimate	\$ 7,406.01				
		Supplement 1	\$ 1,452.39				
	11/14/2013	Supplement 2	\$ 241.50				
	11/20/2013	K & M estimates		State Farm Insurance Companies	\$ 12,478.98	\$ 3,379.08	Rear Body Floor Pan; Rear Floor Pan; Cover Steering Wheel, Seats and Floor; Pre-Measure Unibody; Pre-Measure Suspension; Structural Damage Diagnostics; Additional EVO Setup; SUPPLEMENTAL ANCHORING REQUIRED TO PULL; Pinch Welds (Clamp Damage); EVO Mount Locations; Inspect SRS Components Per OE Requirement; 3M Weld Wrap; Protect Interior From Welding Damage; Weld Thru Primer; Epoxy Primer; Sheild Corrosion Protection System; Seam Sealer Kent KT12401 2@96.74; Wiring; Electronic Modules/Components in Trunk; Reset Electronic Memory Functions; Road Test and Normalize Functions; 4 Wheel Alignment; Transport To/From Alignment; Wash/Tack after Repair; Wash/Tack after Blocking; Trim Trunk Attachment Bolts; Cover Car For Repairs; Cover Car For Paint; Cover Car For Buffing/Polishing; Hand Glaze After Buffing; Clean Repair Debris From Vehicle/Final Wash; Paint/Materials.
7376/42-377W-37602	12/6/2013	Original estimate	\$ 3,157.50				
		Supplement 1	\$ 1,783.20				
		Supplement 2	\$ 85.00				
		Supplement 3	\$ 305.62				
	3/13/2014	Supplement 4	\$ 262.82				
		K & M estimates		State Farm Insurance Companies	\$ 7,270.90	\$ 669.81	L Rear Door Weatherstrip; Pre-Wash and Degrease Vehicle; Adhesive Removal (Stipe); Adhesive Removal (Labels); Pre-Measure Unibody; D & R Battery; Road Test Vehicle/Check for Wind Noise; 4 Wheel,ODS Check per Honda,Scan Clear C; Transport To/From Auto Fitness; Reprogram Power Window Memory; Air Bag/SRS/Seat Belt Saftey Inspection; Re-Calibrate ODS per Honda (Auto Fitness) Line Markup %25.00; Trim Fender Attachment Bolts; Cover Car For Paint; Hand Glaze After Buffing; Clean Repair Debris From Vehicle/Final Wash; Paint/Materials.
7379/33-398F-05701	2/19/2014	Original estimate	\$ 1,313.07				
		Supplement 1	\$ 447.88				
		Supplement 2	\$ 77.87				
	3/7/2014	Supplement 3	\$ 71.62				
		K & M estimates		State Farm Insurance Companies	\$ 2,162.33	\$ 849.26	AutoFitness- ODS Check per Honda Line Markup %25.00; Pre-Wash and Degrease Vehicle; Tint Color; Paint/Materials

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
7220/42-273H-83104	5/30/2013	Original estimate	\$ 5,859.27				
		Supplement 1	\$ 1,093.58				
		Supplement 2	\$ 450.25				
	6/18/2013	Supplement 3	\$ 52.80				
		Supplement 4	\$ 224.40				
		K & M estimates	\$ 6,917.13				
	6/14/2014	K & M estimates		State Farm Insurance Companies	\$ 8,962.14	\$ 1,559.04	3M Bare Metal Seam Sealer; 3M Panel Bonding Adhesive; Road Test Vehicle; Collision AccessTime; Remove wax, grease 7 tar from repair area; detail vehicle; inspect airbag/SRS system; 4 wheel alignment; D & R battery (for welding operations); Weld thru primer; Shiled Corrosion protection system; Dress and fill welds; cover car for primer; cover car for paint; paint/materials.
7277/33-328P-88302	8/7/2013	Original estimate	\$ 3,667.90				
		Supplement 1	\$ 1,598.01				
	9/18/2013	Supplement 2	\$ 1,066.48				
		K & M estimates		State Farm Insurance Companies	\$ 6,598.70	\$ 266.31	Shield corrosion protection system; scan and clear stored DTCs; 4 wheel alignment; transport to/from alignment; cover car for primer; cover car for paint; clean repair debris from vehicle/final; paint/materials
7409/33-398M-69301	1/17/2014	Original estimate	\$ 309.21				
		Supplement 1	\$ 696.09				
	3/24/2014	Supplement 2	\$ 1,514.96				
		K & M estimates		State Farm Insurance Companies	\$ 5,377.26	\$ 2,356.32	Alloy Wheel; Pre-Wash and Degrease Vehicle; Audi Seat Belt Check; Audi PCI; 4 Wheel Alignment Line Markup %25.00; Scan and Clear Stored DTCs Line Markup %25.00 A; Transport To Audi Asheville; Transport From Audi Asheville; Tint Color; Paint/Materials.
7326/028417972-02	12/3/2013	Original estimate					
	12/10/2013	Supplement 2	\$ 946.20	Liberty - 12/20/2013			
			\$ 2,477.81	Liberty - 1/6/2014			
			\$ 223.94	Liberty - 1/6/2014			
		K & M estimates			\$ 8,814.67	\$ 5,166.72	Alloy Wheel; alloy wheel A; alloy wheel B; Alloy wheel C; Wheels removed for set up/measure; engine under cover; R ctr engine under cover; L ctr engine under cover; Under cover removed for setup/measure; rear exhaust pipe; L exhaust rear heat shield; exhaust removed for rear body access; battery; R. door shell; R. center pillar & rocker complete; L center pillar & rocker complete;refinish time includes for ackside of R; R section rocker panel; L section rocker panel; repair clamp mounting damage; R quarter panel; stretch @ bumper guide mounts, door gap; add for edge & inside rear floor underside; VW bonding adhesive; R rear body floor trim panel; L rear body floor panel; rear body lining panel; pre-wash and degrease vehicle; cover steering wheel seats and floor; pre-measure unibody; pre-measure suspension; structural damage diagnostics; EVO fixture setup required for rail pull; pull and monitor right rail for sway; pull and monitor left rail for sag; EVO mount locations; EVO mount locations A; VW seat belt check (doc attached); Wiring; 3M weld wrap; setup and test MAG welder; setup and test STRS welder; remove factory cavity wax; seam sealer; epoxy primer; re-establish TCM basic settings per VW M; diagnose and clear stored fault codes; 4 wheel alignment line markup %25.00; transport to/from alignment; reset electronic memory functions; road test vehicle; p[rep plastic bumper; tint color; tint inner trunk color; cover car for repairs; wash/tack after repair; cover car for primer; wash/tack after blocking; cover car for paint; gravel guard; setup, test, apply to duplicate OE finish; clean repair debris from vehicle/final wash; de-nib and finess; paint/materials; hazardous waste disposal.

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
7248/0443968300107011-03		Original estimate	\$ 2,991.96	GEICO - 8/14/2013			
		Supplement 1	\$ 4,409.95	GEICO - 8/29/2013			
	10/16/2013	Supplement 2	\$ 1,147.74	GEICO - 10/24/2013			
			\$ 218.69	GEICO - 12/27/2013			
	8/16/2013	K & M estimates			\$ 10,198.72	\$ 1,430.38	Alloy wheels; Air Bag/SRS/Seat Belt Safety Inspection; Repair & restore CP to inside 1/4; Road Test vehicle; Pre-wash and degrease vehicle; wash/tack after repair; wash/tack after blocking; Cover car for buffing/polishing; Clean repair debris from vehicle/final; Paint/materials; De-Nib and Finesse; Hazardous waste disposal
7271/0456994110101030-01		Customer Deductible	\$ 500.00	customer - 9/4/2013			
	8/6/2013	Original estimate	\$ 1,721.68	GEICO - 9/4/2013			
		Supplement 1	\$ 1,064.83	GEICO - 9/4/2013			
	10/16/2013	Supplement 2	\$ 1,684.74	GEICO - 10/24/2013			
	8/30/2013	K & M estimates			\$ 5,779.80	\$ 808.55	4 Wheel Alignment; Transport to/from alignment; Pre-wash and degrease vehicle; cover steering wheel, seats and floor; cover car for paint; clean repair debris from vehicle/final; cover car for paint A; Gravel guard; Pnl 1 @ 0.5 Addnl Pnls @ 0.3; Paint/materials; De-Nib and Finesse; Hazardous Waste Disposal
7241/13-1331280-02	7/17/2013	Original estimate					
		Supplement 1	\$ 1,323.53				
	8/1/2013	Supplement 2	\$ 1,963.95				
	8/1/2013	K & M estimates		Progressive	\$ 7,831.11	\$ 1,372.10	Storage Indoor 7/26-8/1; Paint/Materials; Unibody Setup & Measure & Pull; Pre-Measure-65 Setup-130 Pulls;Rrail-130; D & R Battery; Diagnose and Clear Fault Codes; Road Test Vehicle; Damage Analysis/Post Collision Inspection; Cover Car For Paint.
7339/33-3N43-58402	12/20/2013	Original estimate	\$ 4,068.88				
	1/23/2014	Supplement 1	\$ 1,955.79				
		K & M estimates		State Farm Insurance Companies	\$ 6,917.13	\$ 892.46	Pinch Welds (Clamp Damage); Pinch Welds (Clamp Damage) A; 4 Wheel Alignment; Line Markup %25.00; Transport to/from Alignment; Cover Car for Repairs; Cover Car for Paint; Clean Debris from Vehicle/Final Wash; Paint/Materials.
7209/6132C 50208202151301U/U1	2/15/2013	Original estimate	\$ 5,902.25	Nationwide - 6/25/2013			
		Supplement 1	\$ 125.00				
	6/28/2013	Supplement 2	\$ 5,154.62	Nationwide - 7/29/2013			
		Supplement 2 addition	\$ 718.20	Nationwide - 7/8/2013			
	6/28/2013	K & M estimates			\$ 17,194.34	\$ 5,419.27	L. Fender Panel; Pinch Welds (Clamp damage) A; Disassemble and Recondition Used Rear Do; Damage Analysis; Tech info access fee; Inspect SRS System; Detail vehicle; Road test vehicle; 4 wheel Alignment; deliver vehicle to/from alignment; Protect Interior; Shiled Corrosion Protection system; Additional Coats required for poor Hidin; Cover car for Primer; Additional clear coat mix; Storage- indoor storage (& parts) 6/12-7/1; Paint/Materials; De-Nib and Finesse; Feather, Prime and Block.
7236/000289811670802	6/15/2013	Original estimate	\$ 2,077.76	Allstate - 7/29/2013			
		Supplement S01	\$ 919.04	Allstate - 7/19/2013			
		Supplement S02	\$ 1,002.06	Allstate - 7/19/2013			
	7/29/2013	Supplement S03	\$ 516.55	Allstate - 7/29/2013			
	7/19/2013	K & M estimates			\$ 5,891.53	1376.12	L Fender Panel; W/Shield Adhesive; Upr W/Shield Moulding; Steam Clean Engine compartment; Air bags/SRS/Seat belt safety inspection; Wash/Tack after repair; Additional clear coat mix (Flex add); Paint.

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
7130/6132M 31169007121201C/J1	8/2/2013	Original estimate					
	8/2/2012	Supplement 1					
	8/2/2012	K & M estimates		Nationwide	\$ 28,376.17	\$ 4,476.97	Corrosion Protection; Road test vehicle; Broken glass clean up; protect interior; adhesive removal; polish scratches on vehicle; detail vehicle; steam clean engine compartment; wash jams for tape adhesion; feather/prime/block; collision access time; ck/inspect suspension & underbody; disable/enable SRS system; diagnosis and clear fault codes; frame set up and measure; access time for roof due to hright; additional clear coat mix 2 @ 0.3; tint color; cover car for paint; towing; de-nib and finesse; paint/materials.
7139/6132D 03640208171201G/T1	8/17/2012	Original estimate	\$ 4,397.31				
		Supplement 1	\$ 3,185.06				
		Supplement 2	\$ 4.20				
		Supplement 3	\$ 100.80				
		Supplement 4	\$ 12.60				
		Supplement 5	\$ 1,719.21				
		Supplement 6	\$ 170.74				
	10/24/2012	Supplement 7	\$ 79.80				
	10/9/2012	K & M estimates		Nationwide	\$ 12,072.82	\$ 2,638.30	Protect interior; corrosion protection; prep LKQ door; Pinstripe (tape); Adhesive removal; tint color; mask engine compartment/underhood; mask l. fender opening jamb; mask l front door jamb; mask l rear door jamb; mask pick up bed; de-nib and finesse; paint/materials.
7166/6132C 81485412241201M/A1	12/24/2012	Original estimate	\$ 3,494.87				
		Supplement 1	\$ 66.72				
		Supplement 2	\$ 356.42				
		Supplement 3	\$ 539.63				
		Supplement 4	\$ 27.23				
	2/5/2013	Supplement 5	\$ 328.00				
	6/22/2014	K & M estimates		Nationwide	\$ 6,918.84	\$ 2,105.97	Inspect/fit AM fender & restock fee; Inspect/fit AM lamp & restock fee; Pinch welds (clamp damage); Wash jams for tape adhesion; remove wax, grease & tar from repair areas; steam clean engine compartment; adhesive removal; tint color; mask engine compartment/underhood; cover car for paint; Storage-indoor storage 12/24/12-1/10/13 @ \$50 per day; Paint/materials.
7171/6132C 01557701211301U/U1	1/21/2013	Original estimate	\$ 8,676.36				
		Supplement 1	\$ 291.31				
		Supplement 2	\$ 1,828.56				
		Supplement 3	\$ 2,014.82				
		Supplement 4	\$ 246.40				
		Supplement 5	\$ 134.30				
		Supplement 6	\$ 22.00				
	2/27/2013	Supplement 7	\$ 11.50				
	4/2/2013	K & M estimates		Nationwide	\$ 14,275.95	\$ 1,587.50	Road vehicle test; collision access time; transfer welded gas lid bracket; replace flexible foam; replace rigid foam; Access tech info; test fit trunk; test fit rear lamp; test fit rear cover; inspect airbag/SRS system; disable/enable SRS system; wiring; unibody setup; unibody pull; prep raw plastic bumper; prep raw plastic rocker; additional clear coat mix; cover car for paint; cover car for primer; paint/material; de-nib and finesse.

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
7249/6132M 89734407151301W/W1	7/15/2013	Original estimate	\$ 8,254.49	Nationwide -7/30/2013			
		Supplement 1	\$ 1,275.29	Nationwide - 8/23/2013			
		Supplement 2	\$ 132.00	Nationwide - 9/6/2013			
		Supplement 3	\$ 491.19	Nationwide - 9/6/2013			
	8/30/2013	Supplement 4	\$ 678.94	Nationwide - 9/6/2013			
	6/21/2014	K & M estimates			\$ 12,425.26	\$ 1,593.35	Collision access time; pre-wash and degrease vehicle; cover steering wheel, seats and floor; protect interior from welding damage; wiring; weld thru primer; shield corrosion protection system; epoxy primer; replace rigid foam; paramount sublet 1; paramount sublet 2; transport to alignment; transport from alignment; additional clear coat mix; tint color; trim fender attachment bolts; cover car for repairs; cover car for primer; cover car for buffing/polishing; hand glaze after buffing; claeen repair debris from vehicle/final; paint/material
7329/170832-GA	11/21/2013	Original estimate	\$ 965.45	Nationwide - 12/27/13			
		Supplement 1	\$ 130.00	Nationwide - 12/27/13			
		Supplement 2	\$ 22.20	Nationwide - 12/27/13			
	12/16/2013	Supplement 3	\$ 2,279.23	Nationwide - 12/27/13			
	12/27/2013	K & M estimates			\$ 5,227.91	\$ 1,831.06	Test fit and perform water leak test; rear bumper impact bar A; lifting pad support; pre-wash and degrease vehicle; cover steering wheel, seats and floor; pre-measure unibody; structural damage diagnostics; fixture rental (BMW SPEC); unibody setup; EVO for supplemental anchoring (Pre BMW); measure suspension & mounting point; Benchand EVO mounting points; bench and EVO mounting points; bench and EVO mounting points A; transport to auto fitness; SRS and 4 wheel alignment (auto fitness); line mark up %25.00; transport from auto fitness; cover car for repairs; cove rcar for paint; tint color (5 tint cycles required); denib an dpolish; clean repair debris from vehicle/final wash; paint/materials.
7362/265129-GA-1	1/13/2014	Original estimate	\$ 897.68	Nationwide - 2/17/2014			
	2/10/2014	Supplement S01	\$ 1,005.93	Nationwide - 3/10/2014			
	2/17/2014	K & M estimates			\$ 4,496.74	\$ 2,593.13	Frt Lwr Bumper grille; hood panel; adjust/align hood, striker & latch; Sub-frame; alloy wheel; Alloy wheel A; alloy wheel B; Alloy wheel C; R frt susp steering knuckle; L frt steering knuckle; frt susp stabilizer; steering gear assembly; eng mount support; Frt Eng Supt Trans Mount; Rear Eng Supt Trans Mount; R Frt Seat Belt; L Frt Seat Belt; R Rear Seat Belt; L Rear Seat Belt; Rear Ctr Seat Belt; R Upr Ctr Pillar Trim Panel; L Upr Ctr Pillar Trim Panel; R Lwr Ctr Pillar Trim Panel; L Lwr Ctr Pillar Trim Panel; R Rocker Scuff Plate; L Rocker Scuff Plate; R Frt Door Opening Weatherstrip; L Frt Door Opening Weatherstrip; R Rear Door Opening Weatherstrip; L Rear Door Opening Weatherstrip; Quarter Package Tray Trim Panel; Rear Seat Assy; R Rear Susp Knuckle; L Rear Susp Knuckle; Rear Susp Stabilizer Bar; Rear Susp Sub Frame; Pre-Wash and Degrease Vehicle; Cover Steering Wheel, Seats and Floor; Pre-Measure Unibody; Unibody Setup; Unibody Pull; Pinch Welds (Clamp Damage); Pinch Welds (Clamp Damage) A; Road Test for Seat Belt Check; Paramount Line Markup %25.00; Prep Plastic Bumper; Tint Color; De-Nib And Finesse; Clean Repair Debris From Vehicle/Final W; Paint/Materials.
7420/426446-GA-1		Customer deductible	\$ 500.00	customer - 4/4/2014			
	3/19/2014	Original estimate	\$ 1,209.28	Nationwide - \$709.28 on 4/4/2014			
	6/5/2014	Supplement 1	\$ 509.84	Nationwide - 6/5/2014			

Repair Order #/Ins. Co. Claim #	estimate date	Payment basis	Payment made	Paid by	K & M total	Shortfall	Shortfall itemization
	3/28/2014	K & M estimates			\$ 2,243.09	\$ 523.97	Adhesive residue removal; Match and tint exterior color; Spray out card for variant/tint; DeNib and polish painted panels (30% base finish); Hand glaze refinished panels; Clean repair debris from vehicle/final wash; Pinstripe - tape +33%; Material, Paint; Material, Shop; E.P.C.