

Copyright VW AG

Body Collision Repair  
DMS Repair Order number: undefined  
VIN:  
Model code: GEN  
Engine code: EASA  
License plate:  
User name: Allen

ElsaPro Job no.: 1224970  
  
Model year: 2019  
Model description: Audi e-tron  
Transmission code: UDE  
Final drive code:  
Service advisor - name:

---

## **The High-Voltage System must be De-Energized for the Following Work Procedures.**

The high-voltage system must only be de-energized using Guided Fault Finding. Refer to the chapter High-Voltage System, De-Energizing.

**When performing welding, sanding or cutting procedures near the high-voltage components, the system must be de-energized by a high-voltage technician.**

**The system must be de-energized by a high-voltage technician if using the straightening rack for body procedures.**

**Procedures after de-energizing may only be done by technicians trained in electrical systems.**