
Date: Estimate ID: Estimate Version: Preliminary Profile ID:



PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING REAR WINDOW DEFOGGER, AIR CONDITION, REAR WINDOW WIPER, CRUISE CONTROL TILT STEERING COLUMN, AM/FM STEREO, DRIVER AIRBAG, REAR (DUAL-ZONE) AC LEATHER SEAT, POWER PASSENGER SEAT, FRONT SIDE AIRBAG WITH HEAD PROTECTION LUGGAGE RACK, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, FOG LIGHTS ALUM/ALLOY WHEELS, POWER LIFTGATE\TRUNK, TIRE INFLATION/PRESSURE MONITOR ANTI-THEFT SYSTEM, AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY HIGH INTENSITY DISCHARGE HEADLIGHTS, LEATHER STEERING WHEEL, SATELLITE RADIO CD PLAYER, SUNROOF/MOONROOF, PRIVACY GLASS, GENUINE WOOD TRIM AUTO AIR CONDITION, TRIP COMPUTER, FIRST ROW BUCKET SEAT UNIVERSAL GARAGE DOOR OPENER, REAR HEATING, VENTILATION & AIR CONDITIONING ALL WHEEL DRIVE, SIDE AIRBAGS, AUTOMATIC HEADLIGHTS SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, DUAL SUNROOF, MP3 PLAYER DAYTIME RUNNING LIGHTS, TONNEAU COVER, DRIVER SEAT WITH POWER LUMBAR SUPPORT ELECTRONIC STABILITY CONTROL, FRONT HEATED SEATS, KEYLESS ENTRY SYSTEM RAIN SENSING WIPERS, REAR BENCH SEAT, REAR SPOILER STEERING WHEEL AUDIO CONTROLS

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Labor Amount Units
1	101000	BDY	REMOVE/INSTALL	R W/Shield Deflector	Existing	0.2 r
2	101004	BDY	REMOVE/INSTALL	R Inr W/Shield Garnish Mldg	Existing	INC r
3	101525	REF	REFINISH	R Door Opening Panel Complete		C 3.0
4	104377	BDY	REPAIR	R Rocker Outer Panel -S	Existing	3.5*
5	102238	BDY	REMOVE/INSTALL	R Roof Drip Rail Moulding	Existing	0.4 r
6	102242	BDY	REMOVE/INSTALL	R Cowl/Dash Kick Panel	Existing	0.6 #r
7	102248	BDY	REMOVE/INSTALL	R Upr Ctr Pillar Trim Panel	Existing	INC r
8	102252	BDY	REMOVE/INSTALL	R Lwr Ctr Pillar Trim Panel	Existing	INC r
9	102263	BDY	REMOVE/INSTALL	R Frt Rocker Scuff Plate	Existing	0.4 r
10	102265	BDY	REMOVE/INSTALL	R Rear Rocker Scuff Plate	Existing	0.4 r
11	101135	BDY	REMOVE/INSTALL	R Frt Door Opening Weatherstrip	Existing	0.4 r
12	101188	BDY	REMOVE/INSTALL	R Rear Door Opening Weatherstrip	Existing	0.4 r
13	104248	BDY	REMOVE/INSTALL	R Rear Lwr Door Opening Seal	Existing	0.3 r
14	100003	REF	BLEND	R Frt Door Outside		C 0.9

Mitchell Data Version:

Options:

Software Version:

Copyright (C) 1994 - 2019 Mitchell International All Rights Reserved

Date:
Estimate ID:
Estimate Version:
Preliminary
Profile ID:

					Profile ID:				
15	101120	BDY	REMOVE/INSTALL	R Frt Door Assembly				1.1	
16	101113	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding				1.1	#
17	101115	BDY	REMOVE/INSTALL	R Frt Rear View Mirror			H	NC :	#
18	101419	BDY	REMOVE/REPLACE	R Frt Lwr Door Moulding	ORDER FROM DEALER	185.00		0.2	
19	AUTO	REF	REFINISH	R Frt Lwr Door Moulding		1	C	0.5	
20	101099	BDY	REMOVE/INSTALL	R Frt Door Trim Panel			П	NC	
21	101109	BDY	REMOVE/INSTALL	R Frt Otr Door Handle				0.3	
22	104202	BDY	REMOVE/REPLACE	R Rear Door Shell	8R0 833 052 B	1,300.00		6.0	
23	AUTO	REF	REFINISH	R Rear Door Outside			0 :	2.2	
24	AUTO	REF	REFINISH	R Rear Add For Jambs & Interior		(0	1.0	
25	101468	BDY	REMOVE/REPLACE	R Rear Lwr Door Moulding	ORDER FROM DEALER	190.00	П	NC	
26	AUTO	REF	REFINISH	R Rear Lwr Door Moulding			0	0.5	
27	103329	BDY	REMOVE/REPLACE	R Rear Door Weatherstrip	8R0 839 912 L	160.00	П	NC	
28	103047	REF	BLEND	R Roof Panel Outside			0	1.0	
29	102923	BDY	REMOVE/INSTALL	R Roof Rail			- (0.3	#
30	AUTO	BDY	REMOVE/INSTALL	Roof Headliner			- 1	6.7	
31	100007	REF	BLEND	R Quarter Panel Outside			0	8.0	
32	101180	REF	BLEND	R Fuel Door			II	NC i	#
33	100835	BDY	REMOVE/INSTALL	R Quarter Wheelhouse Liner	Existing		(0.4	r
34	101042	BDY	REMOVE/INSTALL	R Quarter Fuel Door	Existing		(0.3	r
35	101171	GLS	REMOVE/INSTALL	R Quarter Glass			:	2.8	#
36	101221	BDY	REMOVE/REPLACE	Qtr Glass Adhesive	N.A.	25.00			
37	100736	BDY	REMOVE/INSTALL	R Rear Combination Lamp			(0.4	#
38	AUTO	BDY	REMOVE/INSTALL	Liftgate Trim Panel			(0.4	
39	101157	BDY	REMOVE/INSTALL	Rear Bumper Cover				1.0	#
40	AUTO	REF	ADD'L OPR	Three Stage			1	5.7	
41	933018	BDY *	ADD'L OPR	Mask For Overspray		5.00 '	•	0.3*	
42	900500	REF *	REMOVE/REPLACE	SUBSEQUENT MASKING-TWO DOOR OPENINGS	New	5.00 3	(0.5*	
43	900500	BDY *	ADD'L LABOR OP	DENIB AND FINESS	Existing			0.5*	
44	900500	BDY *	ADD'L LABOR OP	TINT COLOR	Existing		:	2.0*	
45	AUTO		ADD'L COST	Paint/Materials		885.50 *			

^{* -} Judgment Item

Estimate Totals

I.	Labor Subtotals Body Refinish Glass	Units 27.6 16.1 2.8 Non-Taxa	Rate 115.00 115.00 115.00	Add'l Labor Amount 5.00 0.00 0.00	0.00 0.00	Totals 3,179.00 1,851.50 322.00 5,352.50	II.	Part Replacement Summary Taxable Parts Sales Tax @ Total Replacement Parts Amount	9.000%	Amount 1,865.00 167.85 2,032.85
	Labor Summary	46.5				5,352.50				
III.	Additional Costs Taxable Cos	ts Sales Tax		@	9.000%	Amount 885.50 79.70	IV.	Adjustments Insurance Deductible		Amount 500.00-
Total Additional Costs Paint Material Method: Rates Init Rate = 55.00, Init Max Hours = 99.9, Addl Rate = 0.00						965.20		Customer Responsibility		500.00-

^{# -} Labor Note Applies

C - Included in Clear Coat / Three Stage Calc

r - CEG R&R Time Used For This Labor Operation



 I.
 Total Labor:
 5,352.50

 II.
 Total Replacement Parts:
 2,032.85

 III.
 Total Additional Costs:
 965.20

 Gross Total:
 8,350.55

IV. Total Adjustments: 500.00-Net Total: 7,850.55

This is a preliminary estimate. Additional changes to the estimate may be required for the actual repair.

Point(s) of Impact 4 Right Rear Side (P)



Assignment Info

