



Trubilt Collision Center

"The Choice of the Chippewa Valley Since 1949"
1631 Harding Ave, Eau Claire, WI 54701
Phone: (715) 834-6617
FAX: (715) 834-3504

Workfile ID: [REDACTED]
PartsShare: [REDACTED]
Federal ID: [REDACTED]

Final Bill

RO Number: 18413

Customer: [REDACTED]	Insurance: STATE FARM INSURANCE	Adjuster: [REDACTED]	Estimator: [REDACTED]
[REDACTED]		Phone: [REDACTED]	Create Date: 5/29/2020
[REDACTED]		Claim: [REDACTED]	
[REDACTED]		Loss Date: 5/28/2020	
[REDACTED]		Deductible: 500.00	

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

VIN: [REDACTED]	Interior Color:	Mileage In: 51,060	Vehicle Out: 6/22/2020
License: [REDACTED]	Exterior Color: Champagne	Mileage Out: 51,060	
State: WI	Production Date: 5/2017	Condition:	Job #: Wayne/Skin

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Type	Paint
1	S01		INFORMATION LABELS						
2	S01	Remove/Replace	RT Caution label air bag	1	2.48T	OEM	0.1T	Body	
3	E01		FRONT BUMPER						
4	E01	Remove/Install	R&I bumper cover				0.8T	Body	
5	E01		FRONT LAMPS						
6	E01	Remove/Install	RT Headlamp assy				0.5T	Body	
7	E01		FENDER						
8	E01	Blend	RT Fender Outback						1.9T
9	S01	Remove/Install	RT Fender liner Legacy				0.5T	Body	
10	E01	Remove/Install	Mud guard Subaru accessory - fender						
11	S01		ELECTRICAL						
12	S02	Remove/Install	Battery NOTE: Terminal R&I required per Subaru See Attachments						
13	E01		INSTRUMENT PANEL						
14	E01	Remove/Install	RT Front dr speaker w/o Harman Kardon				0.0T	Body	
15	S01		RESTRAINT SYSTEMS						
16	S02	Repair	RT Side impact sens front door NOTE: Inspection Required after collision per Subaru see attachments.						
17	S02	Repair	RT Head air bag Outback NOTE: Inspection Required after collision per Subaru see attachments.						
18	S02	Repair	Psngr air bag NOTE: Inspection Required after collision per Subaru see attachments.						
19	S02	Remove/Install	RT Head air bag Outback						

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18413

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

NOTE: Side impact (side airbag module not activated)
Visually inspect the following items and replace any damaged or cracked part (collision side) with a new one.
Specially inspect the damage of airbag module body, mounting bracket and harness connector.
Pad assembly - front seat backrest
Frame assembly - front backrest
Cover COMPL - front backrest
Front door impact sensor
Side airbag module
Side airbag sensor
Curtain airbag module
Curtain airbag sensor

20 S02 Remove/Install

Control module Legacy
NOTE: Check for the following, and replace the damaged parts with new parts.
Control module is cracked or deformed.
Mounting bracket is cracked or deformed.
Connector is scratched, cracked or deformed.
Driver's airbag module has been activated.
Passenger's airbag module has been activated.
Seat cushion airbag module has been activated.
Side airbag module has been activated.
Curtain airbag module has been activated.

21 S02 Remove/Install

Seat belt pretensioner has been activate
RT Ft seat air bag seat back
NOTE: Side impact (side airbag module not activated)
Visually inspect the following items and replace any damaged or cracked part (collision side) with a new one.
Specially inspect the damage of airbag module body, mounting bracket and harness connector.
Pad assembly - front seat backrest
Frame assembly - front backrest
Cover COMPL - front backrest
Front door impact sensor
Side airbag module
Side airbag sensor
Curtain airbag module
Curtain airbag sensor

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 18413

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

22	S02		SEATS & TRACKS						
23	S02	Repair	Seat back frame						
			NOTE: Side impact (side airbag module not activated)						
			Visually inspect the following items and replace any damaged or cracked part (collision side) with a new one.						
			Specially inspect the damage of airbag module body, mounting bracket and harness connector.						
			Pad assembly - front seat backrest						
			Frame assembly - front backrest						
			Cover COMPL - front backrest						
			Front door impact sensor						
			Side airbag module						
			Side airbag sensor						
			Curtain airbag module						
			Curtain airbag sensor						
24	S01		ROOF						
25	S02	Repair	Headliner w/o sunroof w/o Eyesight pkg						
			NOTE: Inspection Required after collision per Subaru see attachments.						
26	E01		PILLARS, ROCKER & FLOOR						
27	E01	Remove/Replace	RT Rocker molding	1	71.45T	OEM	0.4T	Body	
28	E01	Repair	RT Rocker panel				5.5T	Body	1.5T
29	S01		Add for Clear Coat						1.0T
30	E01	Repair	Setup & measure						
31	E01	Repair	Rough pull				2.0T	Body	
32	E01	Remove/Install	RT Upr ctr plr trim				0.2T	Body	
33	S01	Repair	RT Center pillar				1.0T	Body	1.0T
34	E01	Remove/Install	RT Pillar molding				0.3T	Body	
35	S02	Repair	RT Lwr ctr plr trim				0.2T	Body	
			NOTE: Inspection Required after collision per Subaru see attachments.						
36	S02	Repair	RT W/S pillar trim				0.2T	Body	
			NOTE: Inspection Required after collision per Subaru see attachments.						
37	S01	Repair	RT Upr ctr plr trim						
			NOTE: Inspection Required after collision per Subaru see attachments.						
38	S02	Remove/Replace	RT Front sill plate w/o chrome insert	1	11.07T	OEM	0.2T	Body	
39	S02	Remove/Install	RT Lwr ctr plr trim				0.6T	Body	
40	S02	Remove/Install	RT Cowl trim				0.2T	Body	
41	S02	Remove/Install	RT Rear sill plate				0.3T	Body	
42	E01		FRONT DOOR						
43	S02	Remove/Replace	RT Door shell Outback	1	600.00T	OEM	5.9T	Body	3.0T
44	E01		Overlap Major Adj. Panel						(0.4)T
45	S01		Add for Clear Coat						1.1T
46	S01	Remove/Replace	RT Belt molding	1	77.95T	OEM	0.0T	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 18413

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

47	E01	Remove/Install	RT W'strip on body				0.3T	Body	
48	E01	Remove/Install	RT Door w'strip				0.0T	Body	
49	S01	Remove/Replace	RT Upper molding	1	41.63T	OEM	0.2T	Body	
50	S01	Remove/Replace	RT Black out tape front	1	1.70T	OEM	0.1T	Body	
51	S01	Remove/Replace	RT Black out tape rear	1	4.73T	OEM	0.2T	Body	
52	E01	Remove/Replace	RT Lower molding Outback black	1	80.70T	OEM	0.0T	Body	
53	E01	Remove/Install	RT R&I mirror				0.0T	Body	
54	E01	Remove/Install	RT Handle, outside w/Smart key, w/o chrome tungsten				0.0T	Body	
55	S01	Remove/Replace	RT Door w'strip cover rear	1	13.17T	OEM			
56	S01	Remove/Replace	RT Door w'strip cover front	1	6.67T	OEM	0.1T	Body	
57	S01	Remove/Install	RT Door glass Subaru				0.0T	Body	
58	S01	Remove/Install	RT R&I trim panel				0.0T	Body	
59	E01		REAR DOOR						
60	S01	Remove/Replace	RT Belt w'strip Outback	1	86.17T	OEM	0.3T	Body	
61	E01	Remove/Install	RT Handle, outside w/o chrome				0.7T	Body	
62	E01	Remove/Install	RT W'strip on body Outback				0.3T	Body	
63	S01	Remove/Replace	RT Lower molding Outback black	1	57.85T	OEM	0.3T	Body	
64	E01	Remove/Install	RT R&I door assy NOTE: To repair and refinish rt rocker and center pillar damage.				0.7T	Body	
65	S01	Remove/Install	RT R&I door assy				0.7T	Body	
66	S01	Repair	RT Door shell Outback NOTE: 4.0 on outer panel 1.0 on inner shell and door edge 1.0 remove seam sealer complete				6.0T	Body	2.0T
67	E01		Overlap Major Adj. Panel						(0.4)T
68	S01		Add for Clear Coat						
69	E01		Add for Edging						0.5T
70	E01		Add for Inside						0.5T
71	E01	Remove/Install	RT R&I trim panel				0.0T	Body	
72	E01	Remove/Install	RT Lower w'strip				0.2T	Body	
73	E01	Remove/Install	RT Door w'strip Outback				0.4T	Body	
74	S02	Repair	FeatherPrimeBlock SM						0.5T
75	S01	Remove/Install	RT Striker				0.2T	Body	
76	S01	Remove/Install	RT Upper hinge				0.3T	Body	
77	S01	Remove/Install	RT Lower hinge				0.3T	Body	
78	S01		QUARTER PANEL						
79	S01	Remove/Replace	RT Side molding	1	8.83T	OEM			
80	S01		REAR BUMPER						
81	S01	Remove/Replace	O/H rear bumper				1.8T	Body	
82	S01	Remove/Replace	Bumper cover w/o prk sensor	1	251.95T	A/M	0.0T	Body	2.0T
83	S01		Overlap Major Non-Adj. Panel						(0.2)T
84	S01		Add for Clear Coat						0.1T
85	S01	Remove/Install	RT Reflector				0.0T	Body	

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 18413

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

86	E01		VEHICLE DIAGNOSTICS				
87	S02	Remove/Replace	Pre-repair scan	1	100.00T	OEM	
88	S02	Remove/Replace	Post-repair scan	1	50.00T	OEM	
89	E01	Sublet	PreScan				
90	E01	Sublet	as Tech-Post				
91	E01		Corrosion Protection				0.2T
92	E01		Hazardous waste removal	1	4.00T	Other	
93	E01		MISCELLANEOUS OPERATIONS				
94	S02	Remove/Replace	Cover car/bag			OEM	
95	S02	Remove/Replace	3M Materials Invoice				
96	S01	Remove/Replace	AM & OEM Accessories	1	124.95T	Other	
97	S01	Repair	State Farm Not Paying Materials				1.0T UD1
98	S02		Material costs-paint	1	29.94T	Other	
99	S02	Sublet	Co-Pilot Test Drive	1	60.00T	Other	
100	S02		Additional OEM Procedures performed not paid				

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,625.24
Sublet/Miscellaneous					60.00
Labor, Body			60.00	32.0	1,920.00
Labor, Refinish			60.00	14.3	858.00
Refinish			62.00	1.0	62.00
Material, Paint					600.60
Subtotal					5,125.84
Sales Tax					281.92
Grand Total					5,407.76
Deductible					(500.00)
Net Total					4,907.76

Estimate Version	Total \$
Original	3,834.24
Supplement S01	1,573.52
Supplement S02	0.00

Insurance Total \$:	4,907.76
Received from Insurance \$:	4,907.76
STATE FARM INSURANCE COMPANIES	6/23/2020 3,334.24
STATE FARM INSURANCE COMPANIES	6/24/2020 1,573.52
Balance due from Insurance \$:	0.00
Customer Total \$:	500.00

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

Final Bill

RO Number: 18413

2017 SUBA Outback Premium 4D WGN 4-2.5L Gasoline Sequential MPI Champagne

Received from Customer \$:		500.00
	[REDACTED]	6/22/2020
		500.00
Balance due from Customer \$:		0.00

1.) Trubilt guarantees its repair and refinishing work for the lifetime of the vehicle under the original customer's ownership. This guarantee does not apply to exterior or interior rusting, paint chipping or areas damaged by collision or abrasion. This also excludes damage caused by owner neglect, abuse, gasoline exposure, etc.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THE REPLACEMENT PARTS RATHER THAN BY THE MANUFACTURER OF YOUR MOTOR VEHICLE.

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.