

State Farm Insurance Companies
Take this initial estimate to the repair facility of your choice. If additional damage is found have the repair facility use the Request Supplement link at b2b.statefarm.com. **This is not an email address; it is the site to submit a Supplement**. All supplements must be approved by State Farm®.

*** SUPPLEMENT 1 ***

S1 06/07/2020
06/15/2020 09:16 PM

Owner

Owner: [REDACTED]
Address: [REDACTED]
City State Zip: [REDACTED]
Home/Day: [REDACTED]
Cell: [REDACTED]
Home/Evening: [REDACTED]

Control Information

Claim # : [REDACTED]
Loss Date/Time: 06/03/2020
Deductible: \$100.00
Ins. Company: State Farm
Insured: [REDACTED]
Address: [REDACTED]
City State Zip: [REDACTED]
Claim Rep: Weather Response Team Auto Eastern
Address: [REDACTED]
Insured Policy # : [REDACTED]
Loss Type: Comprehensive
Home/Day: [REDACTED]
Cell: [REDACTED]
Home/Evening: [REDACTED]
Work/Day: [REDACTED]

Inspection

Inspection Date: 06/15/2020 12:33 PM
Inspection Location: Autotech Collision Service
Address: 165 Delsea Drive
City State Zip: Sewell, NJ 08080
Primary Impact: Non-Collision
Driveable: Yes
Inspection Type: Virtual
Contact: [REDACTED]
Home/Day: [REDACTED]
Secondary Impact:
Rental Assisted:
Assigned Date/Time:
First Contact Date/Time:
Appraiser Name: [REDACTED]
Address: [REDACTED]
Orig Appraiser Name: [REDACTED]
Received Date/Time: 06/05/2020 10:08 AM
Appointment Date/Time: 06/05/2020 02:12 PM
Appraiser License # : [REDACTED]
Work/Day: [REDACTED]
Appraiser License # :

Repairer

Repairer: Autotech Collision Service
Address: 165 Delsea Drive
City State Zip: Sewell, NJ 08080
Contact: [REDACTED]
Home/Day: [REDACTED]

Remarks

VIRTUAL ESTIMATED CREATED DUE TO COVID 19 RESTRICTIONS
SUPPLEMENT 1 WAS PREPARED BY JOSEPH MARMON (ELECTRONIC SIGNATURE)
NO SUPPLEMENTS WITHOUT PRIOR APPROVAL
F,P,&B= FEATHER,PRIME&BLOCK
safelite glass 1-800-458-4527
***** NO SUPPLEMENTS WITHOUT PRIOR AUTHORIZATION. *****
1st Cover Car is "Inc."per Audatex refinish guidelines.
***** VEHICLE MUST BE PRESENT AT TIME OF SUPPLEMENT INSPECTION. *****

Vehicle

2018 Audi Q5 2.0T Prestige 4 DR Wagon
4cyl Gasoline Turbo 2.0
Automatic Tiptronic

Lic.Plate: [REDACTED]
Lic Expire:
Prod Date: 08/2018
Veh Insp# :
Condition:
Ext. Color: Manhattan Gray Metallic /
Manhattan G
Ext. Refinish: Two-Stage
Ext. Paint Code: X7L

Lic State: NJ
VIN: [REDACTED]
Mileage: 0
Mileage Type: Non Readable
Code: 68773A
Int. Color: Black-Black/Black-Black/Black/titan
Gr
Int. Refinish: Two-Stage
Int. Trim Code: YM

Options - AudaVIN Information Received

1st Row LCD Monitor(s)
Adaptive Cruise Control
Aluminum Trim
Anti-Lock Brakes
Automatic Dimming Mirror
Bucket Seats
Chrome Grille
Cross Traffic Alert
Driver Information Sys
Dual Airbags
Electronic Compass
Fwd. Collision Alert
Head Airbags
Heated Front Seats
Heated W/S Wiper Washers
Intermittent Wipers
Keyless Ignition System
LED Headlamps
Leather Shift Knob
MP3 Decoder
Navigation System
Panorama Roof W/Pwr Mnrf
Power Brakes
Power Windows
Pwr Folding Ext Mirrors
Rear Spoiler
Rem Trunk-L/Gate Release
Side Blind Zone Warning
Stability Cntrl Suspensn
Surround Cameras
Three Zone Climate Ctrl
Traction Control System
Wireless Phone Connect

2nd Row Head Airbags
Alarm System
Aluminum/Alloy Wheels
Auto Dimming Ext Mirrors
Automatic High Beam
Cargo/Trunk Mat
Collision Avoidance Sys
Cruise Control
Driver Seat Memory
Dual Power Seats
Ext Mirror Turn Signals
Garage Door Opener
Heads-Up Display
Heated Power Mirrors
IPOD Control
Keyless Access System
LED Brakelights
Lane Departure Alert
Leather Steering Wheel
Metallic Paint
Overhead Console
Parking Assist System
Power Door Locks
Privacy Glass
Rain-Sensing W/S Wipers
Rear View Camera
Roof/Luggage Rack
SiriusXM Satellite Radio
Strg Wheel Radio Control
Tachometer
Tilt & Telescopic Steer
Trip Computer

AM/FM CD Player
All-Weather Mats (Floor)
Amplifier
Auto-Leveling Headlamps
Auxiliary Audio Input
Center Console
Corrective Lane Assist
Digital Signal Processor
Dual Air Conditioning
Electric Steering
Fog Lights
Hands Free Decklid
Heated Frnt & Rear Seats
Heated Steering Wheel
Illuminated Visor Mirror
Keyless Entry System
LED Daytime Running Lts
Leather Seats
Lighted Entry System
Mirror(s) Memory
Paddle Shifter
Pedestrian Detection Sys
Power Liftgate
Pwr Driver Lumbar Supp
Rear Fog Lamp
Rear Window Defroster
Side Airbags
Split Folding Rear Seat
Subwoofer
Theft Deterrent System
Tire Pressure Monitor
Wireless Audio Streaming

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Stripes And Mouldings								
1	RI	439	Mldg,Rear Door Lower R/R	R & I Assembly			0.3	SM
2	E	200	Clip,Quarter Mldg LT	8U0853909	\$15.84 ✓	S1		SM
			Quantity of 8 @ \$1.98 each					
3	E	201	Clip,Quarter Mldg RT	8U0853909	\$15.84 ✓	S1		SM
			Quantity of 8 @ \$1.98 each					
4	I	473	Mldg,Flare LT	Repair			1.2*	SM
			>> addt.labor added in refin.column for feather,prime&block					
5	L	473	Mldg,Flare LT	Refinish			1.1	RF
				1.0 Surface				
				0.1 Two-stage				
6	RI	473	Mldg,Flare LT	R & I Assembly			INC	SM
7	RI	474	Mldg,Flare RT	R & I Assembly			INC	SM
Front Body And Windshield								
8	EC	144	Sealant Kit,W/Shield	** NON-OEM PART	\$60.00* ✓	S1	2.2	SM
			>> For refinishing of both "A" pillars and roof					
9	RI	152	Mldg,W/S Reveal Upper	R & I Assembly		S1	0.2	SM
10	RI	1274	Mldg,W/S Reveal Side LT	R & I Assembly		S1	INC	SM
11	RI	1275	Mldg,W/S Reveal Side RT	R & I Assembly		S1	INC	SM
12	RI	1345	Fastener,Mldg LT	R & I Assembly		S1	INC	SM
13	RI	1346	Fastener,Mldg RT	R & I Assembly		S1	INC	SM
14	RI	145	Arm,Wiper Blade LT	R & I Assembly			INC	SM
15	RI	146	Arm,Wiper Blade RT	R & I Assembly			INC	SM
16	RI	1321	Grille,Upper Cowl	R & I Assembly		S1	INC	SM
			>> for glass cleanup					
Roof								
17	RI	1974	Headliner R & I	R & I Assembly		S1	INC	SM
18	I	341	Panel,Roof	Repair			1.5*	SM
			>> addt.labor added in refin.column for feather,prime&block					
19	L	341	10 Panel,Roof	Refinish			2.9*	RF
				2.1 Surface				
				0.5 Two-stage				
				0.3 Feather, Prime & Block				
			>> Partial refinish for repairs 3.4to 2.9					
20	RI	343	Glass Panel,Roof	R & I Assembly			0.2	SM
21	RI	381	Glass Panel,Roof	R & I Assembly			0.3	SM
22	E	1180	W/Strip,Glass Panel	3G9877459	\$216.67 ✓	S1	0.3	SM
23	RI	346	Antenna,Assembly	R & I Assembly			2.5	SM
24	E	468	Rail,Roof Side LT	80A860021J3Q7	\$805.00 ✓	S1	2.6	SM
25	RI	469	Rail,Roof Side RT	R & I Assembly			0.8	SM
Dashboard And Components								
26	RI	950	Panel,Inner Cowl Trim LT	R & I Assembly		S1	INC	SM
27	RI	951	Panel,Inner Cowl Trim RT	R & I Assembly		S1	INC	SM
28	RI	954	Mldg,W/S Garnish LT	R & I Assembly		S1	INC	SM
29	RI	955	Mldg,W/S Garnish RT	R & I Assembly		S1	INC	SM
Center Console And Seat Tracks								
30	E	1687	01 Pnl,Package Tray Trim	80A863553A94H	\$933.85 ✓	S1		SM
Front Doors								
31	N	207	Front Door R&I LT	ADDITIONAL OPERATION			0.7	SM
			High Strength Steel					

32	N	208	>> for uniside refinish Front Door R&I RT High Strength Steel	ADDITIONAL OPERATION			0.7	SM
33	I	207	Door Shell,Front LT High Strength Steel	Repair			1.0*	SM
34	RI	488	>> wetsand compount polish W/Strip,Front Door LT	R & I Assembly			0.5	SM
35	RI	489	W/Strip,Front Door RT	R & I Assembly			0.5	SM
36	E	275	Applique,Frt Door Fram LT	80A837901A5FQ	\$138.33*	S1	0.8	SM
37	RI	1238	Striker,Front Lock LT	R & I Assembly			0.1	SM
38	RI	1239	Striker,Front Lock RT	R & I Assembly			0.1	SM

Rear Doors

39	N	287	Rear Door R&I LT >> for uniside refinish	ADDITIONAL OPERATION			0.7	SM
40	N	288	Rear Door R&I RT	ADDITIONAL OPERATION			0.7	SM
41	BR	288	Door Shell,Rear RT	Blend Refinish			1.3	RF
				0.9 Blend				
				0.4 Two-stage				
42	RI	347	W/Strip,RR Door Body LT	R & I Assembly			0.3	SM
43	RI	348	W/Strip,RR Door Body RT	R & I Assembly			0.3	SM
44	RI	472	Mldg,Rear Door Belt RT	R & I Assembly			0.2	SM
45	RI	326	Pnl,Inner Door Trim RT	R & I Assembly			0.4	SM
46	RI	1264	Striker,Rear Lock LT	R & I Assembly			0.1	SM
47	RI	1265	Striker,Rear Lock RT	R & I Assembly			0.1	SM
48	RI	306	Handle,RR Door Outer RT	R & I Assembly			0.1	SM

Quarter And Rocker Panel

49	L	163	# Pillar,Hinge LT	Refinish		LT	0.9*	RF
				0.2 Surface				
				0.6 Two-stage setup				
				0.1 Two-stage				
			# = 10, 13 >> blend prep for clear					
50	L	164	10 Pillar,Hinge RT	Refinish			0.6*	RF RE
				0.5 Surface				
				0.1 Two-stage				
			>> blend - prep for clear					
51	IT	894	07 Panel,Bodyside Otr Up LT	Partial Repair			1.3*	SM
			>> addt.labor added in refin.column for feather,prime&block					
52	L	894	Panel,Bodyside Otr Up LT	Refinish		LT	1.5*	RF
				1.3 Surface				
				INC Two-stage				
				0.2 Feather, Prime & Block				
			>> Partial refinish for repairs 1.9to 1.5					
53	IT	895	07 Panel,Bodyside Otr Up RT	Partial Repair			1.3*	SM
			>> addt.labor added in refin.column for feather,prime&block					
54	L	895	Panel,Bodyside Otr Up RT	Refinish			1.5*	RF RE
				1.3 Surface				
				INC Two-stage				
				0.2 Feather, Prime & Block				
			>> Partial refinish for repairs 1.9to 1.5					
55	L	329	10 Pnl,Rckr & Plr,Center LT	Refinish		LT	1.4*	RF
				0.8 Surface				
				0.6 Two-stage		3.8		
			>> blend prep for clear					
56	L	330	10 Pnl,Rckr & Plr,Center RT	Refinish			1.4*	RF RE
				0.8 Surface				3.5
				0.6 Two-stage				
			>> blend-prep for clear					
57	RI	251	Insert,Frt Sill Plate LT	R & I Assembly		S1	0.1	SM
58	RI	252	Insert,Frt Sill Plate RT	R & I Assembly		S1	0.1	SM
59	RI	321	W/Strip,Rocker Panel LT	R & I Assembly			0.8	SM

60	E		Tire decal-pillar	New Part	\$38.00*	S1	0.1*	SM*
61	N		fineline mask vin.decal	ADDITIONAL OPERATION	\$2.00*		0.2*	SM*
62	RI	322	W/Strip,Rocker Panel RT	R & I Assembly			0.8	SM
63	IT	369	Panel,Quarter LT	Partial Repair			2.5*	SM
64	L	369	Panel,Quarter LT	Refinish			2.6	RF
				1.9 Surface				
				0.4 Two-stage				
				0.3 Feather, Prime & Block				
65	IT	370	Panel,Quarter RT	Partial Repair			3.2*	SM
			>> addt.labor added in refin.column for feather,prime&block					
66	L	370	Panel,Quarter RT	Refinish			2.5	RF
				1.8 Surface				
				0.4 Two-stage				
				0.3 Feather, Prime & Block				
67	I	397	Door,Fuel Filler RT	Repair			0.5*	SM
68	L	397	Door,Fuel Filler RT	Refinish			0.5	RF
				0.3 Surface				
				0.1 Two-stage				
				0.1 Feather, Prime & Block				
69	E	398	Pocket,Fuel Filler RT	80A809906	\$98.33*	S1	0.4	SM
70	E	573	01 Label,Quarter Panel RT	8K0010508N	\$11.38	S1	0.1	SM
71	E	641	Label,Quarter Panel RT	8X0010544A	\$11.38		0.1	SM
72	E	644	Label,Quarter Panel RT	4M0010002	\$18.58		0.1	SM
73	E	401	Glass,Quarter Tinted LT	80A845297JNVB	\$358.33		0.8	SM
74	E	402	Glass,Quarter Tinted RT	80A845298LNVB	\$358.33	S1	0.8	SM
75	EC	477	Sealant Kit,Qtr Glass LT	** NON-OEM PART	\$35.00*	S1	INC	SM
76	EC	478	Sealant Kit,Qtr Glass RT	** NON-OEM PART	\$35.00*	S1	INC	SM
77	RI	1276	Duct,Quarter Panel LT	R & I Assembly		S1	INC	SM
78	RI	1277	Duct,Quarter Panel RT	R & I Assembly		S1	INC	SM

Inner Quarter & Panels

79	RI	399	Plate,Rear Sill LT	R & I Assembly		S1	INC	SM
80	RI	400	Plate,Rear Sill RT	R & I Assembly		S1	INC	SM
81	RI	313	Pnl,Center Plr Trim LT	R & I Assembly		S1	0.5	SM
82	RI	1582	Pnl,Center Plr Trim LT	R & I Assembly		S1	INC	SM
83	RI	314	Pnl,Center Plr Trim RT	R & I Assembly		S1	0.5	SM
84	RI	1583	Pnl,Center Plr Trim RT	R & I Assembly		S1	INC	SM
85	RI	428	Shield,Quarter Panel LT	R & I Assembly		S1	0.3	SM
86	RI	429	Shield,Quarter Panel RT	R & I Assembly			0.3	SM
87	RI	410	Pnl,Qtr Trim Upr RR LT	R & I Assembly		S1	INC	SM
88	RI	625	Pnl,Qtr Trim Upr Frt LT	R & I Assembly		S1	INC	SM
89	RI	411	Pnl,Qtr Trim Upr RR RT	R & I Assembly		S1	INC	SM
90	RI	626	Pnl,Qtr Trim Upr Frt RT	R & I Assembly		S1	INC	SM

Tailgate

91	I	479	Tailgate Assembly Aluminum	Repair			2.8*	SM
			>> addt.labor added in refin.column for feather,prime&block					
92	L	479	Tailgate Assembly	Refinish			2.3	RF
				2.1 Surface				
				INC Two-stage				
				0.2 Feather, Prime & Block				
93	RI	479	Tailgate R & I Aluminum	R & I Assembly			1.2	SM
94	E	494	N/Plate,Tailgate	8R08537412ZZ	\$85.00		0.1	SM
95	E	544	N/Plate,Tailgate	8R0853743A2ZZ	\$63.33		0.1	SM
96	RI	564	N/Plate,Tailgate	R & I Assembly		S1	INC	SM
97	E	483	Emblem,Tailgate	4G58537422ZZ	\$91.67		0.1	SM
98	RI	1134	Switch Assembly,T/G	R & I Assembly			0.1	SM
99	NG	532	Glass,Tailgate Heated	NAGS FB27275-YP	\$686.75		1.8	SM
100	EC	2002	Sealant Kit,T/Gate Gls	** NON-OEM PART	\$60.00*	S1	INC	SM
101	RI	530	Mldg,Tailgate Glass LT	R & I Assembly			INC	SM
102	RI	531	Mldg,Tailgate Glass RT	R & I Assembly			INC	SM

103	RI	563	Arm, Tailgate Wiper	R & I Assembly		INC ✓	SM
104	RI	578	Motor, Tailgate Wiper	R & I Assembly		INC ✓	SM
105	I	1570	Spoiler, Tailgate	Repair		1.5* ✓	SM
106	L	1570	Spoiler, Tailgate	Refinish		1.7 ✓	RF
				1.5 Surface			
				INC Two-stage			
				0.2 Feather, Prime & Block			
107	RI	1570	Spoiler, Tailgate	R & I Assembly		INC ✓	SM
108	RI	503	Frame, License Plate	R & I Assembly		0.2 ✓	SM
109	E	486	01 Pnl, T/G Inner Trim	80A867979A4PK	\$378.33 ✓	INC ✓	SM
110	E	1179	01 Pnl, T/G Inner Trim	8W5867975NCA9	\$175.00 ✓	INC ✓	SM

Rear Bumper

111	N	566	Rear Bumper Cover R&I	ADDITIONAL OPERATION		1.6 ✓	SM	
112	I	566	Cover, Rear Bumper Up	Repair		1.8* ✓	SM	
			>> addt.labor added in refin.column for feather,prime&block					
113	L	566	Cover, Rear Bumper Up	Refinish		3.1 ✓	RF	
				2.4 Surface				
				0.5 Two-stage				
				0.2 Feather, Prime & Block				
114	RI	574	Brkt, Rear Bumper Mtg LT	R & I Assembly		S1	0.1 ✓ SM	
115	RI	575	Brkt, Rear Bumper Mtg RT	R & I Assembly		S1	0.1 ✓ SM	
116	RI	1519	Snsr, Obstacle Warning LT	R & I Assembly			0.1 ✓ SM	
117	RI	1520	Snsr, Obstacle Warning RT	R & I Assembly		INC	SM	
118	RI	1521	Snsr, Obstacle Warning LT	R & I Assembly			0.1 ✓ SM	
119	RI	1522	Snsr, Obstacle Warning RT	R & I Assembly		INC	SM	
120	RI	688	Spoiler, Lower Rear	R & I Assembly			0.2 ✓ SM	
121	BR	1022	Cover, Tow Hook Access LT	Blend Refinish		(0.1)	RF	
				0.1 Blend				
				INC Two-stage				
122	BR	1023	Cover, Tow Hook Access RT	Blend Refinish		(0.1)	RF	
				0.1 Blend				
				INC Two-stage				

Rear Body, Lamps And Floor Pan

123	RI	533	Taillamp Assembly LT	R & I Assembly		0.2 ✓	SM
124	E	534	Taillamp Assembly RT	80A945094A	\$670.00 ✓	0.2 ✓	SM
125	RI	535	Lamp, Fog LT	R & I Assembly		0.2 ✓	SM
126	RI	536	Lamp, Fog RT	R & I Assembly		0.2 ✓	SM

Section Replacement & Refinish

127	RI	708	Seat Assembly, Rear LT	R & I Assembly		S1	0.2 ✓ SM
128	RI	709	Seat Assembly, Rear RT	R & I Assembly		S1	0.2 ✓ SM

Manual Entries

129	N		Denib & Polish-Finesse	ADDITIONAL OPERATION		S1	5.5* ✓ SM	
			>> 30% of 18.5 hours					
130	N		Clean and Re-Tape	ADDITIONAL OPERATION	\$25.00*	S1	(3.0)* SM	
131	RI		Wiring Harness	R & I Assembly		S1	0.5* ✓ SM	
			>> Set Back and Protect					
132	SB		Calibrate System(s)	Sublet Repair	\$656.00* ✓	S1	SM	
			>> Recalibrate lane change assist & camera					
133	EC		Rivet(s)	** NON-OEM PART	\$10.40* ✓	S1	SM	
			Quantity of 10 @ \$1.04* each					
			>> N91201401					
134	I		Accessory R.cargo tray	Repair			(0.2)* SM*	
			>> clean off glass					
135	RI		Accessory R.cargo tray	R & I Assembly			(0.1)* SM*	
136	N		Pre-wash inspection	ADDITIONAL OPERATION			0.4* ✓ SM*	
137	N		Adhesive removal	ADDITIONAL OPERATION	\$2.00* ✓	S1	1.0* ✓ SM*	
138	N		Reset Electrical Component	ADDITIONAL OPERATION			(0.2)* ME*	
139	N		Clean/disinfect-COVID	ADDITIONAL OPERATION	\$25.00* ✓		1.0* ✓ SM*	
			>> Covid-19.inc.steering wheel cover and seat cover					

140	N	Vehicle Wrap (s) >> collision wrap	ADDITIONAL OPERATION	\$15.00*		0.5*	SM
141	N	Glass Clean Up >> extensive-interior of veh.rear trims,inside rear gate,under cowl vent	ADDITIONAL OPERATION			2.5*	SM
142	N	Car Cover >> for prime	ADDITIONAL OPERATION	\$2.00*		0.2*	SM
143	L	Corrosion Protection	Refinish		S1	0.5*	RF*
144	N	Hazardous Waste Removal	ADDITIONAL OPERATION	\$4.00*	S1		SM
145	N	Masking Opening (s)	ADDITIONAL OPERATION	\$8.00*		0.4*	SM
146	RI	License Plate	R & I Assembly			0.1*	SM
147	N	D & R Battery >> Multiple Times	ADDITIONAL OPERATION		S1	0.2*	ME*
148	N	Pre Scan	ADDITIONAL OPERATION			0.5*	U2*
149	N	Post Scan	ADDITIONAL OPERATION			0.5*	U2*
150	N	Protect Headliner	ADDITIONAL OPERATION	\$5.00*	S1	0.3*	SM*
151	N	Program Sun-roof	ADDITIONAL OPERATION	\$100.00*	S1		SM*
152	L	Color Blender	Refinish		S1	0.3*	RF*
153	N	Measure for Emblems	ADDITIONAL OPERATION		S1	0.3*	SM*
154	N	Check lamp functions	ADDITIONAL OPERATION		S1	0.1*	SM*
155	N	Sunroof Bonding Agent >> D355-205A2	ADDITIONAL OPERATION	\$10.92*	S1		SM*
156	N	Applicator >> D009 50025	ADDITIONAL OPERATION	\$2.43*	S1		SM*
157	EC	4M0853582 >> LT and RT ext clips	** NON-OEM PART	\$20.04*	S1		SM*
158	E	D-181-220-A1 >> Primer	New Part	\$7.08*	S1		SM*
159	E	D-009-500-25 Quantity of 3 @ \$2.43* each >> Applicators	New Part	\$7.29*	S1		SM*
160	E	D-009-401-04 >> Cleaning Kit	New Part	\$27.27*	S1		SM*
161	E	D-002-000-A2 >> Adhesive Remover	New Part	\$44.20*	S1		SM*

161 Items

MC Message

01	CALL DEALER FOR EXACT PART # / PRICE
07	STRUCTURAL PART AS IDENTIFIED BY I-CAR
10	INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

OEM Parts	\$4,569.03
Other Parts	\$1,108.54
Paint & Materials	24.3 Hours @ \$32.00 \$777.60
Parts & Material Total	\$6,455.17
Tax on Parts & Material	@ 6.625% \$427.66

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$54.00	24.8	38.6	63.4	\$3,423.60
Mech/Elec (ME)	\$54.00		0.4	0.4	\$21.60
Frame (FR)	\$64.00				
Refinish (RF)	\$54.00	26.3		26.3	\$1,420.20
Specialty Repair (U2)	\$150.00		1.0	1.0	\$150.00

Labor Total		91.1 Hours	\$5,015.40
Tax on Labor	@ 6.625%		\$332.27

Sublet Repairs	\$656.00	
Towing	\$300.00	
Gross Total		\$13,186.50
Less: Deductible		\$100.00-
Net Total		\$13,086.50
Actual Supplement Total	\$3,843.90	
Less: Previous Net Total		\$9,242.60-
Net Supplement Total		\$3,843.90

For more information regarding State Farm's promise of satisfaction relating to new non-original equipment manufacturer (non-OEM) and recycled parts, please visit: <http://st8.fm/7X4> or QR code.



Register online to check the status of your claim and stay connected with State Farm®. To register, go to statefarm.com and select Check the Status of a Claim. If you are already registered, thank you!

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 40209 PXN Region 7
Recycled Parts NOT REQUESTED
Rate Name (02408) PA PHILA CMDN WLMTN NJ

Audatex Estimating 8.0.818 Update 2 S1 06/29/2020 02:03 PM REL 8.0.818 Update 2 DT 05/01/2020
© 2020 Audatex North America, Inc.

2.0 HOURS OF REPAIR TIME WERE ALLOCATED TO FEATHER, PRIME & BLOCK AS INDICATED BY THE ESTIMATE PREPARER'S LABOR ITEMIZATION. FEATHER, PRIME & BLOCK LABOR IS REFLECTED UNDER THE REFINISH OPERATION FOR THE APPLICABLE DAMAGE ENTRY.
4.4 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

SM-SHEET METAL ME-MECH/ELEC FR-FRAME RE-REFINISH SY-SYSTEM
THIS IS AN ESTIMATE. REPAIR FACILITIES MUST INSPECT THE VEHICLE TO DETERMINE IF ANY REPAIRS NOT LISTED ARE REQUIRED, AND TO CONTACT STATE FARM BEFORE MAKING SUCH REPAIRS. REPAIRER ALSO IS RESPONSIBLE FOR CONDUCTING ANY NECESSARY INSPECTION AND SAFETY CHECKS PRIOR TO AND AFTER COMPLETING REPAIRS.

SM-SHEET METAL ME-MECH/ELEC FR-FRAME RE-REFINISH SY-SYSTEM
THIS IS AN ESTIMATE. REPAIR FACILITIES MUST INSPECT THE VEHICLE TO DETERMINE IF ANY REPAIRS NOT LISTED ARE REQUIRED, AND TO CONTACT STATE FARM BEFORE MAKING SUCH REPAIRS. REPAIRER ALSO IS RESPONSIBLE FOR CONDUCTING ANY NECESSARY INSPECTION AND SAFETY CHECKS PRIOR TO AND AFTER COMPLETING REPAIRS.

ANY PERSON WHO KNOWINGLY FILES A STATEMENT OF CLAIM CONTAINING ANY FALSE OR MISLEADING INFORMATION IS SUBJECT TO CRIMINAL AND CIVIL PENALTIES.
THIS IS AN ESTIMATE. REPAIR FACILITIES MUST INSPECT THE VEHICLE TO DETERMINE IF ANY REPAIRS NOT LISTED ARE REQUIRED, AND TO CONTACT STATE FARM BEFORE MAKING SUCH REPAIRS.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF AUTOMOBILE PARTS NOT MADE BY THE ORIGINAL MANUFACTURER. PARTS USED IN THE REPAIR OF YOUR VEHICLE BY OTHER THAN THE ORIGINAL MANUFACTURER ARE REQUIRED TO BE AT LEAST EQUAL IN LIKE, KIND AND QUALITY IN TERMS OF FIT, QUALITY AND PERFORMANCE TO REPLACEMENT PARTS AVAILABLE FROM THE ORIGINAL MANUFACTURER.

STATE FARM INSURANCE IS PROHIBITED BY LAW FROM NEGOTIATING, ADJUSTING OR SETTLING AN AUTOMOBILE DAMAGE CLAIM WITH AN UNLICENSED FACILITY IN ACCORDANCE WITH NJ 11:3-10.3.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = New Part
NG = Replace NAGS	EC = ** NON-OEM PART	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = ** NON-OEM PART
EU = RECYCLED PART	TE = Partial Replace Price	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRIOR	



Audatex

This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2020 Audatex North America, Inc.
AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.





AUTOTECH COLLISION SERVICE

165 DELSEA DRIVE, SEWELL, NJ 08080
Phone: (856) 232-1833
FAX: (856) 232-7628

WORKING CO.
PartsShare:
Federal ID:
License Number:



Preliminary Estimate

Customer: [Redacted]

Job Number:

Written By: Dean Massimini

Insured: [Redacted]
Type of Loss:
Point of Impact:

Policy #:
Date of Loss:

Claim #: [Redacted]
Days to Repair: 0

Owner:
[Redacted]

Inspection Location:
AUTOTECH COLLISION SERVICE
165 DELSEA DRIVE
SEWELL, NJ 08080
Repair Facility
(856) 232-1833 Business

Insurance Company:
State Farm

VEHICLE

2018 AUDI Q5 Prestige 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Gray

VIN: [Redacted]
License: [Redacted]
State: NJ

Interior Color:
Exterior Color: Gray
Production Date:

Mileage In:
Mileage Out:
Condition:

Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package

DECOR

Dual Mirrors
Privacy Glass
Console/Storage
Overhead Console
Wood Interior Trim

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Rear Window Wiper
Telescopic Wheel
Climate Control
Dual Air Condition
Navigation System
Backup Camera
Parking Sensors
Home Link

RADIO

AM Radio

Stereo
Search/Seek
Auxiliary Audio Connection
Premium Radio
Satellite Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Communications System
Hands Free Device
Xenon Headlamps
Blind Spot Detection
Heads Up Display

Luggage/Roof Rack
Electric Glass Sunroof
Skyview Roof

SEATS

Bucket Seats
Leather Seats
Heated Seats

WHEELS

20" Or Larger Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
Signal Integrated Mirrors

TRUCK

Power Trunk/Gate Release

Customer: [REDACTED]

Job Number:

2018 AUDI Q5 Prestige 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection Gray

CONVENIENCE

FM Radio

ROOF