



Printed Date: 5/11/2021

Scott's Collision Repair

2260 NE Loop 286


Paris, TX 75460

(903) 785-2524, (903) 785-2523 (fax)

INVOICE

RO #: [REDACTED]

Est: Johnny Green



Work:
Cell:

14 Cadillac CTS
Color:
Type: PC 2 Door Coupe
VIN: [REDACTED]
Prod Date: Plate: [REDACTED]
Odometer: 50000
Engine:

GEICO
Adjustor:
Phone:
Claim #: [REDACTED]
Deductible: 0
Loss Type: Unknown

P = Who Pays? (I = Insurance, C = Customer)

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
	Parts Existing	Frt Bumper Cover			1	Body	R&I	1.6		I
	Parts Existing	R Front Combination Lamp			1	Body	R&I	0.3		I
	Parts Existing	L Front Combination Lamp			1	Body	R&I	0.3		I
	Parts Existing	Hood Moulding			1	Body	R&I	0.3		I
	Parts Existing	R Hood Washer Nozzle			1	Body	R&I	0.4		I
	Parts Existing	L Hood Washer Nozzle			1	Body	R&I	0.2		I
	Parts Existing	Hood Panel			1	Body	Rpr	7.0		I
	Parts Existing	Hood Outside			1		Ref n		2.7	I
	Parts Existing	Hood Insulator				Body	R&I			I
	Parts New	prime and block hood			1		Repl		0.7	I
	Parts Existing	R Fender Panel			1	Body	Rpr	4.0		I
	Parts Existing	R Fender Outside			1		Ref n		1.7	I
	Parts Existing	L Fender Panel			1	Body	Rpr	3.0		I
	Parts Existing	L Fender Outside			1		Ref n		1.7	I
	Parts Existing	R Fender Panel Extension				Body	R&I			I
	Parts Existing	L Fender Panel Extension				Body	R&I			I
	Parts Existing	R Fender Liner			1	Body	R&I	0.4		I
	Parts Existing	L Fender Liner			1	Body	R&I	0.4		I
	Parts Existing	R Fender Grille			1	Body	R&I	0.2		I
	Parts Existing	L Fender Grille			1	Body	R&I	0.2		I
	Parts New	prime and block left fender			1		Repl		0.3	I
	Parts New	prime and block right fender			1		Repl		0.4	I
	Parts Existing	Communications Antenna	-M		1	Mech	R&I	0.5		I
1	Sub/et	W/Shield Glass	19330830	380.00	1	Glass	Repl			I
1	Parts New	W/Shield Adhesive	N.A.	50.00	1	Body	Repl			I
1	Parts New	R Cowl/Dash Seal	25900731	13.76	1	Body	Repl			I
1	Parts New	L Cowl/Dash Seal	25900732	13.76	1	Body	Repl			I

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
	Parts Existing	L Frt Door Outside			1		Blnd		0.9	1
	Parts Existing	R Frt Door Assembly			1	Body	R&I	1.0		1
	Parts Existing	L Frt Door Assembly			1	Body	R&I	1.0		1
	Parts Existing	R Frt Door Repair Panel			1	Body	Rpr	7.0		1
	Parts Existing	R Frt Door Outside			1		Ref n		1.7	1
	Parts Existing	R Frt Otr Door Belt Moulding			1	Body	R&I	0.4		1
	Parts Existing	L Frt Otr Door Belt Moulding			1	Body	R&I	0.4		1
	Parts Existing	R Frt Rear View Mirror			1	Body	R&I			1
	Parts Existing	L Frt Rear View Mirror			1	Body	R&I			1
	Parts Existing	R Frt Door Trim Panel			1	Body	R&I	0.4		1
	Parts Existing	L Frt Door Trim Panel			1	Body	R&I	0.4		1
	Parts Existing	R Frt Door Switch				Body	R&I			1
	Parts Existing	L Frt Door Switch				Body	R&I			1
	Parts Existing	R Frt Door Latch Striker			1	Body	R&I	0.2		1
	Parts Existing	L Frt Door Latch Striker			1	Body	R&I	0.2		1
	Parts New	PRIME AND BLOCK RIGHT DOOR			1		Repl		0.7	1
	Parts Existing	Roof Panel			1	Body	Rpr	11.5		1
	Parts Existing	Roof Panel Outside			1		Ref n		2.3	1
	Parts Existing	Roof Headliner			1	Body	R&I	4.5		1
	Parts New	PRIME AND BLOCK ROOF PANEL			1		Repl		1.5	1
1	Sublet	Back Window Glass	23339085	608.55	1	Glass	Repl			1
1	Parts New	Back Window Adhesive	N.A.	50.00	1	Glass	Repl			1
	Parts Existing	R Side Body Panel Assembly	-S		1	Body	Rpr	7.0		1
	Parts Existing	R Side Body Panel Complete			1		Ref n		4.8	1
	Parts Existing	L Side Body Panel Assembly	-S		1	Body	Rpr	9.0		1
	Parts Existing	L Side Body Panel Complete			1		Ref n		4.8	1
	Parts Existing	R Uptr Roof Garnish Moulding			1	Body	R&I	0.4		1
	Parts Existing	L Uptr Roof Garnish Moulding			1	Body	R&I	0.4		1
	Parts Existing	R Rocker Moulding			1	Body	R&I	0.5		1
	Parts Existing	L Rocker Moulding			1	Body	R&I	0.5		1
	Parts New	prime and block for rt qtr			1		Repl		0.6	1
	Parts New	prime and block for lft qtr			1		Repl		0.7	1
1	Sublet	R Qtr Glass Stationary	22858021	87.50	1	Glass	Repl			1
1	Sublet	L Qtr Glass Stationary	22858020	87.50	1	Glass	Repl			1
1	Parts Glass	Qtr Glass Adhesive	N.A.	50.00	1	Body	Repl			1
	Parts Existing	Luggage Lid Assy			1	Body	R&I	0.7		1

Qty	Type	Description	Part #	Amount	Sup #	Labor	Op	Labor Units	Paint Units	P
	Parts Existing	Luggage Lid Moulding			1	Body	R&I	0.2		1
	Parts Existing	Luggage Lid Panel			1	Body	Rpr	5.0		1
	Parts Existing	Luggage Lid Outside			1		Ref n		1.8	1
1	Parts New	Luggage Lid Adhesive Emblem	20903641	33.77	1	Body	Repl	0.2		1
1	Parts New	Luggage Lid Adhesive Emblem A	25840466	44.62	1	Body	Repl	0.2		1
1	Parts New	Luggage Lid Adhesive Nameplate	20850971	24.21	1	Body	Repl	0.2		1
	Parts New	prime and block deck lid			1		Repl		0.5	1
1	Parts New	Luggage Lid Adhesive Nameplate A	25841627	15.60	1	Body	Repl	0.2		1
	Parts Existing	R Rear Combination Lamp			1	Body	R&I	0.4		1
	Parts Existing	L Rear Combination Lamp			1	Body	R&I	0.4		1
	Parts Existing	High Mount Stop Lamp			1	Body	R&I	0.6		1
	Parts Existing	Rear Bumper Cover			1	Body	R&I			1
	Parts Existing	Rear Bumper Cover Assy			1	Body	Ovr h	2.4		1
	Parts Existing	Rear Bumper Cover A			1	Body	Rpr	6.0		1
	Parts Existing	Rear Bumper Cover B			1		Ref n		2.9	1
1	Parts New	REAR BUMPER PLASTIC REPAIR KIT		59.95	1	Body	Repl			1
1	Haz Waste	Hazardous Waste Disposal		8.00			Add			1
1	Pnt/Mat	Paint/Materials		1,905.00			Add			1
	Parts Other	Clear Coat					Add		3.3	1
	Parts Other	Painted Stripe			1		Add			1
	Parts New	Do not install per client request								1
	Parts New	geico ear \$3,818.83			1	Body	Repl			1
	Parts New	Disconnect/Reconnect Battery			1	Mech	Repl	0.2		1
1	Parts New	POST-SCAN	N.A.	119.95	1	Mech	Repl	0.5		1
1	Parts New	DE-NIB & FINESSE		8.00	1	Body	Repl	6.8		1
	Parts New	De-nib & Finesse Procedure includes the								1
1	Pnt/Mat NT	COVER CAR		5.00	1	Body	Repl			1
	Parts Existing	MASK UNDER HOOD			1		Rpr		0.5	1
1	Bdy/Sup Tx	RESTORE CORROSION PROTECTION		15.00	1	Body	Repl	0.5		1
1	Parts New	Finish Sand & Buff		35.00	1	Body	Repl	10.2		1
	Parts New	Allow .3 per refinish hour (30%) to FINS								1
	Parts New	MASK DOOR OPENING AND TRUNK OPENING			1		Repl		0.9	1
	Parts New	.3 PER OPENING								1
	Parts New	COVER AND BAG CAR SECOND TIME			1		Repl		0.2	1
1	Pnt/Wat Tx	FLEX ADDITIVE / CHIP RESISTANCE	N.A.	12.00	1		Repl			1
1	Parts New	RETURNED CHECK FEE GEICO	N.A.	5.00	1	Body	Repl			1
	Parts New	Customer Pay Remove headlamps for polish			1	Body	Repl	2.0		1
	Parts New	Customer Pay Remove headlamps for polish A			1		Ref n		2.5	1
1	Sublet	Mount and balance customers tire	N.A.	25.00	1	Body	Repl			1
1	Sublet	PARIS CHEVROLET SUBLET AIT BAG LIGHT	N.A.	197.33	1	Body	Repl			1
	Parts New	PARIS CHEV FOUND THE DRIVERS SIDE SEAT S								1

Printed Date: 5/11/2021

Parts	563.62
Labor	9,553.60
Sublet	1,385.88
Additional Costs	1,905.00
SubTotal	13,408.10
Taxes	192.69
Grand Total	13,600.79

Due from Insurance		Due from Customer	
SubTotal	13,408.10	SubTotal	0.00
Tax	192.69	Tax	0.00
Total	13,600.79	Total	0.00

Total Amount 13,600.79

Date: 5/11/2021

Date	RO#	Last	F	Ins ID	Type	Amount	Balance	Received B	Credit Card	Number
1/20/2021	2305	[REDACTED]	R		Check	6,148.21	7,452.58	Norris, Sara		[REDACTED]
2/4/2021	2305	[REDACTED]	R		Check	-6,148.21	13,600.79	Norris, David		BOUNCE D CHECK GEICO RETURN ED CHECK FEE
2/4/2021	2305	[REDACTED]	R		EFT	-5.00	13,605.79	Norris, David		
5/11/2021	2305	[REDACTED]	R		Check	2,755.06	10,850.73	Norris, Sara		[REDACTED]
5/11/2021	2305	[REDACTED]	R		Check	12,265.05	1,414.32	Norris, Sara		[REDACTED]
					Total:	15,015.11				