Retail Operator

🛛 General Manager

Name: Jonathan Inzano

Title: National Collision Program Manager

□ Sales Pre-Owned

□ Sales New Car

 ☑
 Take Note
 □
 Take Action

 ☑
 Business Manager
 ☑
 Parts & Accessories

 □
 Service
 □
 Administration

 Phone Number: 949-630-5725
 □
 Image: 100 ministration

Source: Aftersales Business Development



Date: 09/12/2024

Supersedes: --

STRUCTURAL STEEL PARTS RESTRICTIONS

TAKE NOTE

Due to complexity of repair and the requirement of highly specialized tools, training, & repair procedures, BMW of North America restricts the provision of certain structural carbon fiber, aluminum, and newly expanded structural steel parts to those collision centers that successfully complete specific training requirements and who possess the required tooling pertaining to the repair. Structural steel parts restrictions will launch on October 1st, 2024.

MORE DETAILS

Repairs involving the steel structure and in vehicles with intelligent lightweight construction technology (comprising of high-strength steel, aluminum, carbon, or a material mix) require highly specialized training and tooling. As a result, BMW of North America will be restricting certain structural steel parts to ensure the correct repair process is followed.

Ordering restricted parts

The restricted part ordering process was updated on March 1st, 2024. All collision centers can request the provision of restricted parts via the "DEKRA iQC Live" Platform at <u>https://bmw-partsrestrictions.dekraqc.com</u>. For more information, please refer to BMW bulletin # C-00-0226-0015 "Restricted Structural Body Parts Ordering

Process Update".

Note: The ordering process of all non-restricted BMW parts remains the same and is not handled via the DEKRA iQC Live Platform.

BMW Group Body & Paint training requirements

| Structural steel repairs | | | | |
|--------------------------|---------------------------------------|----------------|--|--|
| Course Code | Course Name | Notes | | |
| ST2121 | Intro to BMW Group Technical Training | E-Learning | | |
| ST1801 | Workshop Technology I | Instructor-led | | |
| SB060 | Steel Structural Repair | Instructor-led | | |

Take note: ST2121 & ST1801 are prerequisites of SB060, and may be completed directly or by EQVs (equivalency). Please refer to the trainee's BMW Group University transcript to confirm the completion or EQV status.

Tooling requirements*

| Structural steel repairs | | | | |
|--|---------------------------|---|--|--|
| Part Number | Part Name | Notes | | |
| Non-BMW tool | Approved Frame Bench | Celette, Car-O-Liner, Car Bench | | |
| Non-BMW tool | Approved Spot Welder | See current approved units in tool guide* | | |
| 81 49 2 213 059 <u>or</u> non-BMW tool | K1 adhesive cartridge gun | Must be non -compressed-air-driven | | |
| 81 43 5 A5C 138 <u>or</u> non-BMW tool | K5 adhesive cartridge gun | Must fit the K5 cartridge tubes | | |

© 2024 BMW of North America, LLC. The contents of this document are confidential and should not be shared with third parties for distribution.

Take note: The supplied BMW tool part numbers are highly recommended. A supplier-provided tool is accepted as an alternative considering there are no mechanical variations compared to the requirement.

*The tool guide can be found in the "FAQ" section of the iQC Live Platform at <u>https://bmw-partsrestrictions.dekraqc.com</u>

Restricted part number reference list

Due to the dynamic nature of restricted part numbers & supersessions, the most up-to-date list of restricted parts can be found on the home page of the DEKRA iQC Live ordering platform under the "FAQ" section. It is accessible prior to logging in at https://bmw-partsrestrictions.dekraqc.com

MORE QUESTIONS?

In case of further questions or comments, please feel free to contact us at partsrestrictions@bmwna.com or:

| National Team | | | | |
|--|----------------------------|--------------|-------------------------------|--|
| Name | Title | Phone Number | Email Address | |
| Jonathan Inzano | National Collision Program | 949-630-5725 | jonathan.inzano@bmwna.com | |
| | Manager | | | |
| Marcos Ehmann | Body & Paint/ | 201-307-3843 | marcos.ehmann@bmwna.com | |
| | Wholesale/Insurance/R3 | | | |
| | Manager | | | |
| Regional Wholesale, Body, & Paint Managers | | | | |
| Name | Market(s) | Phone Number | Email Address | |
| Eastern Region: | | | | |
| John Schuld | 12, 13, 15 | 267-738-7779 | john.schuld@bmwna.com | |
| Todd Dunham | 14, 19 | 732-639-8970 | <u>todd.dunham@bmwna.com</u> | |
| Michael Pellot | 16, 17, 18 | 856-600-5368 | michael.pellot@bmwna.com | |
| Christian Fleming | 10, 11 | 857-492-7813 | christian.fleming@bmwna.com | |
| Southern Region: | | | | |
| Federico Franco | 20, 22 | 678-429-7189 | federico.v.franco@bmwna.com | |
| Matt Schneider | 21, 28 | 864-404-0693 | matthew.d.schneider@bmwna.com | |
| Mike Jones | 26, 27, 29 | 346-253-4998 | michael.ja.jones@bmwna.com | |
| Melissa Costa | 23, 24 | 551-370-2300 | melissa.costa@bmwna.com | |
| Benjamin Braxton | 25 | 551-273-9339 | benjamin.braxton@bmwna.com | |
| Western Region: | | | | |
| Tad David | 38, 39 | 253-268-6718 | tad.david@bmwna.com | |
| Tor Sivertstol | 35, 37 | 831-252-2107 | tor.sivertstol@bmwna.com | |
| Gerrit Tunstad | 32, 34 | 626-764-6239 | gerrit.tunstad@bmwna.com | |
| Erwin Ocasio | 30, 31 | 551-502-7997 | erwin.ocasio@bmwna.com | |
| Carlos Gonzalez | 36 | 510-949-6944 | carlos.cg.gonzalez@bmwna.com | |
| Natalie Hines | 33 | 949-306-2564 | natalie.hines@bmwna.com | |
| Central Region: | | | | |
| Cannon Fears | 40, 41,45 | 708-549-9188 | <u>cannon.fears@bmwna.com</u> | |
| Dan Thompson | 42, 43, 44 | 724-989-2368 | daniel.thompson@bmwna.com | |
| Dustin Gravelle | 46, 47 | 612-924-5619 | dustin.gravelle@bmwna.com | |