

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer of Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4941	8000886504-1-1	1/2/2013	Deductible			\$ 500.00	Insured									
		1/2/2013	Estimate	21st Century Indemnity Insurance Company	Robert Hays	\$ 4,370.40	21st Century Indemnity Insurance Company				Body Labor - \$48/hr; Paint Labor - \$48/hr; Paint Supplies - \$26/hr					
		1/25/2013	Supplement 1	21st Century Indemnity Insurance Company	Robert Hays	\$ 1,857.98	21st Century Indemnity Insurance Company				Body Labor - \$48/hr; Paint Labor - \$48/hr; Paint Supplies - \$26/hr; Frame Labor - \$50/hr					
		2/15/2013	Supplement 2	21st Century Indemnity Insurance Company	Robert Hays	\$ 2,902.55	21st Century Indemnity Insurance Company				Body Labor - \$48/hr; Paint Labor - \$48/hr; Paint Supplies - \$26/hr; Frame Labor - \$50/hr					
		3/20/2013	Supplement 3	21st Century Indemnity Insurance Company	Jill Weideman (HelpPoint Claims Rep)	\$ 133.89	21st Century Indemnity Insurance Company (Farmers Insurance)				Body Labor - \$48/hr; Paint Labor - \$48/hr; Paint Supplies - \$26/hr; Frame Labor - \$50/hr					
		2/12/2013	Crawford's Final Invoice					\$ 10,086.00	\$ 321.18							

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Name of Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
5328	3000912354-1	7/17/2014	Estimate	21st Century Indemnity Insurance Company	Courtnew Watts	\$ 1,534.03	21st Century Indemnity Insurance Company (Farmers Insurance)									
		7/25/2014	Crawford's Final Invoice					\$ 1,966.68	\$ 432.65		Paint Materials - \$28/hr; Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$65/hr	Clean for delivery (Addnl Labor Op) - (0.5 Time); Nib, Sand & Polish (Repair) - (0.5 Time); Admin Charge Est (Addnl Labor Op)		Color tint - (0.5 Time)	Retainer, Rear Bumpe Lt (new part); Retainer, Rear Bumpe Rt (new part); Mldg, Rear Bumper Co Rt (new part); Flex Additive (new part)	Refinish - 0.5; Labor Operation - 1.0

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4560	000204156293B04	5/27/2011	Estimate	Allstate Insurance Company	Donn Uhlhorn	\$ 1,044.16	Allstate Fire and Casualty Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46/hr					
		6/22/2011	Supplement 1	Allstate Insurance Company	Richard Odenweller (cj1sp@allstate.com)	\$ 886.96	Allstate Fire and Casualty Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46/hr; Paint Materials - \$23.50					
		7/1/2011	Supplement 2	Allstate Insurance Company	Robert Cicconi (rcica@allstate.com)	\$ 220.87	Allstate Fire and Casualty Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46/hr; Paint Materials - \$23.50					
		Crawford's Final Invoice						\$ 2,230.85	\$ 78.86							
4609	000214712135B03	8/25/2011	Estimate	Allstate Insurance Company	Richard Odenweller (cj1sp@allstate.com)	\$ 7,869.14	Allstate Insurance Co				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46; Paint Materials - \$23.50					
		9/12/2011	Supplement 1	Allstate Insurance Company	Lin Price	\$ 3,441.00	Allstate Insurance Co				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46; Paint Materials - \$23.50					
		9/26/2011	Supplement 2	Allstate Insurance Company	Lin Price	\$ 1,432.79	Allstate Insurance Co				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46; Paint Materials - \$23.50					
		10/6/2011	Supplement 3	Allstate Insurance Company	Lin Price	\$ 2,903.63	Allstate Insurance Co				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46; Paint Materials - \$23.50					
		10/12/2011	Supplement 4	Allstate Insurance Company	Lin Price	\$ 145.70	Allstate Insurance Co				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$46/hr; Refinish \$46; Paint Materials - \$23.50					

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		10/12/2011				Crawford's Final Invoice		\$ 17,164.58	\$ 1,372.32			Manifold, exhaust (R & I assy) (1.3 Time); Suspension align, frt (addnl labor op); Suspension R & I lt l/f (addnl labor op); Disc, front brake lt (R & I assy); Arm, lower control l/f (R & I assy); Shaft assembly, axele l/f (R & I assy); Vent gls assembly, f rt (sublet repair); Mldg, rear door scalr/r (repair) (0.3 Time); Tape, rear door rt (repair) (0.3 Time); Stricker, rear lock rt (R & I assy); W/strip, roof rt (R & I assy); Tire, rf, balance (sublet repair); Remove adh on w/strip (addnl labor op) (0.3 Time); Remove tape door applique (addnl labor op) (0.3 Time); Fabrication plates (addnl labor op) (2.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Reset electical comp (addnl labor op) (0.2 Time); Retape 2 mlg (addnl labor op) (0.6 Time); Masking for pinch welds (addnl labor ops) (0.5 Time)		Pnl assembly, inr fn rt (refinish); Reinf, inner fender rt (refinish); Gusset, hinge pillar rt (refinish); Pnl, rckr & plr, cent rt (refinish)	Cradle, engine (new part); Vent gls assembly, f, rt (new part); Michelin primacy (new part); Retap w/o mldg (economy part) (0.3 Time); Masking for primer (economy part) (0.3 Time)	Labor - 6.1; Parts - 0.6

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4931	000267710 977B07	12/6/2012	Estimate	Allstate Property & Casualty Ins	Tim Greenland (chpg4@allstate.com)	\$ 8,760.45					Body - \$47/hr; Paint - \$47/hr; Frame - \$47/hr; Paint Supplies - \$25/hr					
		12/31/2012	Supplement 1	Allstate Property & Casualty Ins	Bob Cicconi (rcica@allstate.com)	\$ 4,716.87					Body - \$47/hr; Paint - \$47/hr; Frame - \$47/hr; Paint Supplies - \$25/hr					
		1/28/2013	Supplement 2	Allstate Property & Casualty Ins	Lin Price (cdf9w@allstate.com)	\$ 1,576.55					Body - \$47/hr; Paint - \$47/hr; Frame - \$47/hr; Paint Supplies - \$25/hr					
		2/14/2013	Supplement 3	Allstate Property & Casualty Ins	Lin Price (cdf9w@allstate.com)	\$ 278.99					Body - \$47/hr					
		2/15/2013	Supplement 4	Allstate Property & Casualty Ins	Lin Price (cdf9w@allstate.com)	\$ 1,702.10					Body - \$47/hr; Paint - \$47/hr; Frame - \$47/hr					
		2/21/2013	Supplement 5	Allstate Property & Casualty Ins	Lin Price (cdf9w@allstate.com)	\$ 286.47					Body - \$47/hr					
				Crawford's Final Invoice				\$ 19,530.56	\$ 2,209.53			Plate, front sill rt (R & I assy); Plate, rear sill lt (R & I assy); Front door R & I (addnl labor op); Back glass, heated (sublet repair); Color, sand buff (addnl labor op) (0.2 Time); Underfloor masking (addnl labor op) (1.0 Time); Cut & weld spare tire brake (addnl labor op) (2.0 Time); Test drive (addnl labor op) (0.5 Time); R/door s/mldgs remove tap (addnl labor op) (0.6 Time); Retape doors s/mldgs (addnl labor op) (0.5 Time)		Extn, rear side rail rt (refinish); Pillar, hinge rt (refinish); Door shell, rear rt (refinish); Mldg, rear door lower lt (refinish); Pnl, qtr-rr pan lt (refinish); Pnl, qtr-rr pan rt (refinish); Pnl, wheelhouse inner rt (refinish); Mldg, lid lower (refinish); Dress pinch welds (refinish) (2.0 Time)	Deflector, rocker panel rt (new part); W/strip, front door boot rt (new part); Cover, luggage (new part) (0.3 Time); Reinf, rear body panel (new part); Ret, rear bumper cover rt (new part); Undercoating (economy part) (0.5 Time); Caulk (economy part) (2.5 Time); Rt Lens guide (new guide); Front license plate (economy part) (0.3 Time); Weld thru primer (economy part) (0.3 Time); Sound deadener material (economy part) (2.0 Time); 3M adhesive (economy part) (0.3 Time)	Labor - 4.8; Refinish - 2.0; Parts - 6.2

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 6 of 39 PageID 3173																
Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
5315	0003304 89279D 01	7/29/2014	Deductible			\$ 150.00	Insured			Allstate Fire and Casualty Ins. Company						
		6/23/2014	Estimate	Allstate Fire and Casualty Ins. Co.	Tim Greenland (chpq4@allstate.com)	\$ 6,050.76	Allstate Fire and Casualty Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		7/29/2014	Supplement 1	Allstate Fire and Casualty Ins. Co.	Tim Greenland (chpq4@allstate.com)	\$ 97.30	Allstate Fire and Casualty Insurance Company				Body - \$48/hr					
		8/22/2014	Crawford's Final Invoice					\$ 8,735.12	\$ 2,587.06		Cover, floor (R & I assy) ; Compt, interior (R & I assy); Headliner (R & I assy); Seatbelt, rear lt (R & I assy); Seatbelt, rear rt (R & I assy); Striker, rear lt (R & I assy); Striker, rear rt (R & I assy); Mldg, roof side lt (R & I assy); Mldg, roof side rt (R & I assy); Antenna assembly (R & I assy); Glass, tailgate heated (sublet repair); Box, tool (R & I assy) (0.2 Time); Panel, rear body trim (R & I assy); Taillamp assembly, o lt (R & I assy); Taillamp assembly, o rt (R & I assy); Clean for delivery (addnl labor op) (1.0 Time); Admin. charge est (addnl labor op); Admin charge to rekey est (addnl labor op); Remove 2 tone stripes (addnl labor op) (1.0 Time); Hazardous waste disposal (sublet repair); Layback harness (addnl labor op) (0.5 Time); License plate (R & I assy) (0.3 Time); Masking for CS & B (addnl labor op) (0.5 Time); Test drive (addnl labor op) (0.5 Time); Back tape windshield (addnl labor op) (0.5 Time); Pnl, center plr trim lt (R & I assy); Pnl, center plr trim rt (R & I assy); W/strip, front door lt (R & I assy); W/strip, front door rt (R & I assy); Qtr glass lt (R & I assy); Qtr glass rt (R & I assy); Shield, quarter pane lt (R & I assy); Lamp, high mounted stop (R & I assy); Rear bumper assy (R & I assy); Brkt, rear bumper mt lt (R & I assy); Brkt, rear bumper mt rt (R & I assy); Cover car interior (addnl labor op) (1.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Reset electrical comp (addnl labor op) (0.2 Time)	Panel, bodyside otr lt (blend refinish); Panel, bodyside otr rt (blend refinish); Pillar, hinge lt (refinish); Pillar, hinge rt (refinish); Panel, rocker lt (blend refinish) (1.0 Time); Panel, quarter lt (blend refinish) (1.6 Time); Pnl, tailgate finish (refinish) (2.0 Time); Spoiler, tailgate (refinish) (1.3 Time)	Masking for primer (economy part) (0.3 Time); Refinishing matl require (new part); Allied matl require (new part); Freight on bump applique (new part); Emblem, tailgate (new part) ; Cover, rr bumper lower (new part)	Labor - 5.5; Refinish - 5.9; Parts - 0.3		
5343	0003318 56443H 01	9/19/2014	Deductible			\$ 100.00	Insured			Allstate						
		6/27/2014	Estimate	Allstate - Allstate National Catastrophe Team	Jim Bradford	\$ 4,337.34	Allstate Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		8/18/2014	Supplement 1	Likeside Auto	Richard Odenweller (cj1sp@allstate.com)	\$ 2,218.76	Allstate Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		9/22/2014	Crawford's Final Invoice					\$ 7,010.20	\$ 454.10							
		10/2/2014	Estimate and Deductible	Allstate Fire and Casualty Ins. Co.	David Pirolli (david.pirolli@allstate.com)	\$ 4,150.70	Insured				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		10/14/2014	Supplement 1	Allstate Fire and Casualty Ins. Co.	David Pirolli (david.pirolli@allstate.com)	\$ 2,219.16	Allstate Fire and Casualty Insurance Company				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Paint Supplies - \$26/hr					
		10/28/2014	Supplement 2	Allstate Fire and Casualty Ins. Co.	Bill Gilles (wgill@allstate.com)	\$ 1,072.04	Allstate Fire and Casualty Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 7 of 38 PageID 3174

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5403	0003429 71710H 01	10/31/2014			Crawford's Final Invoice			\$ 7,972.58	\$ 530.68	Allstate Fire & Casualty Ins. Co.		Frt bumper cvr overhaul (addnl labor op) (1.6 Time); Rt splash guard (R & I assy) (0.2 Time); Pull back carpet & wiring (repair) (1.0 Time); Pad, insulator hood ( R & I assy); W/strip, hood panel lt (R & I assy); W/strip, hood panel rt (R & I assy); Pnl, center plr trim rt (R & I assy); Front door R & I (addnl labor op) ; Door, shell front rt (repair) (1.0 Time); W/strip, frt door lw rt (R & I assy); W/strip, frt door bo rt (R & I assy); Rear door R & I (addnl labor op); W/strip, rr door bod rt (R & I assy); Mldg, roof drip rt (R & I assy); Pnl, inner qtr trim rt (R & I assy); Taillamp assembly, o rt (R & I assy); Set up & measure (addnl labor op) (1.5 Time); Color, sand buff (repair) (2.0 Time); L/f cowl seal (R & I assy); Back tape windshield (addnl labor op) (0.5 Time); Back tape rear glass (addnl labor op) (0.5 Time); Reset electrical comp (addnl labor op) (0.2 Time); Dis/rec e-harness (addnl labor op) (1.0 Time); Nib removal (repair) (1.0 Time)		Cover, front bumper (refinish); Fender, front rt (refinish) (2.8 Time); Panel, bodyside otr rt (blend refinish); Panel, rocker rt (refinish); Panel, quarter rt (blend refinish)	Cover, front bumper (new part); Brkt, front bumper m lt (new part); Brkt, front bumper m rt (new part); Panel, hood (new part); Label, a/c condenser (new part) (0.2 Time); Tape, rocker panel rt (new part); Label, center pillar rt (new part); Emission label (new part); Chipguard (economy part) (0.5 Time); Heavy stone guard @ Rocke (economy part) (1.0 Time); Refinishing matl require (new part)	Labor - 8.3; Refinish - 2.8; Parts - 1.7
5204	0003099 21079D 01	1/31/2013	Deductible			\$ 100.00	Insured			Allstate Insurance Company						
		1/15/2014	Estimate	Allstate Fire and Casualty Ins. Co.	Lin Price (cdf9w@allstate.com)	\$ 2,035.73	Allstate Fire and Casualty Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Spplies - \$26/hr					
		1/24/2014	Supplement 1	Allstate Fire and Casualty Ins. Co.	Bob Cicconi (rcica@allstate.com)	\$ 807.55	Allstate Fire and Casualty Insurance Company				Body - \$48/hr; Paint - \$48/hr; Paint Spplies - \$26/hr					
		1/31/2014						\$ 3,722.11	\$ 778.83			Electric Harness @ Jets (R & I assy) (0.5 Time); Cleanup for delivery (addnl labor op) (1.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Reset electrical comp (addnl labor op) (0.2 Time); Test Drive (addnl labor op) (0.5 Time)		Refinishing Matl Require (new part)	Labor - 2.5	

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 8 of 39 PageID 3175

Order #	In Co. Claim #	Date	Payment Basis	Tenure on Estimate	Adjuster/Appraisal	Amount	Coverage	Policy	Labor Hours	Labor Operations	Reimbursement	Material	Other Operations	Parts	Time Discrepancy
5368	03725147 70101129-01	10/13/2014	Deductible	NA		\$ 1,000.00	Insured			Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		9/2/2014	Estimate	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 7,604.54	Geico General Insurance								
		10/10/2014	Supplement 1	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 3,635.49	Geico General Insurance			Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Mechanical - \$48/hr		Rt rail end (refinish); Rt end mount brk (refinish)(0.2 Time); Lt rail end (refinish)(0.2 Time); Lt mount brk (refinish)(0.3 Time); Repair clamp marks (refinish)(2.0 Time); Deflector, rocker rt (blend refinish)(0.7 Time)	Center pipe gasket; Lt fender liner clips (new part); pipe shield retainer clip (new part); Repair clamp marks (new part)(2.0 Time); Cover, front bumper (economy part); Suspension, align, fnl (economy part)	Labor - 17.5; Refinish - 3.5; Parts - 2.0	
		10/20/2014	Crawford's Final Invoice				\$ 14,975.96	\$5,988.61		Admin charge (addnl labor op); Headlamp assy, halog lt (R & I assy); Headlamp assy, halog rt (R & I assy); Brkt, rad supt lower lt (repair)(1.5 Time); A/C evacuate and recharge (addnl labor op); Refrigerant rcvry setup (addnl labor op); Crsnbr, floor (repair)(1.0 Time); Windshield, tinted (repair)(0.5 Time); mldg, pillar finish lt (R & I assy); Mldg, pillar finish rt (R & I assy); Panel, rocker rt (repair)(0.5 Time); Frame, rear seat (R & I assy)(0.5 Time); Door shell, front rt (repair)(1.0 Time); W/strip, frt door bo lt (R & I assy); W/strip, front door bo rt (R & I assy); Pul, inner door trim lt (R & I assy); Pul, inner door trim rt (R & I assy); Housing, mirror outer lt (R & I assy); Housing, mirror outer rt (R & I assy); Handle, front door o lt (R & I assy); Handle, front door o rt (R & I assy); Mldg, roof drip lt (R & I assy); Mldg, roof drip rt (R & I assy); Back glass, heated (repair)(0.5 Time); Pul, Qtr in window lt (repair)(8.0 Time); Glass, quarter tinted/r (sublet repair); glass, quarter tinted/r (sublet repair); Pul, quarter trim up lt (R & I assy); Pul, quarter trim up rt (R & I assy); Deck lid R & I (addnl labor op); Pul, lid inner trim (R & I assy); Pan, rear floor (repair)(2.0 Time); Pocket, ullmp openin lt (repair)(0.5 Time); Pocket, ullmp openin rt (repair)(0.5 Time); Panel, rear body trim (R & I assy); Rear bumper cover r & i (addnl labor op); spring, rear coil lt (R & I assy); Spring, rear coil rt (R & I assy); Sensor, anti-lock br lt (R & I assy); Sensor, anti-lock br rt (R & I assy); Set up & measure (repair)(1.5 Time); Clean for delivery (addnl labor op)(1.0 Time); Color, sand buff (repair)(2.0 Time); AC option (addnl labor op); Underside floor masking (addnl labor op)(0.5 Time); Dress welds (addnl labor op)(0.5 Time); Pull & square body (repair (3.0 Time); R/S trunk gutter (repair)(0.5 Time); Remove paint abs (repair)(1.0 Time) Masking inside trunk (repair)(0.5 Time); Inside back panel (repair)(0.5 Time); Back tape windshield (addnl labor op)(0.5 Time); Back tape rear glass (addnl labor op)(0.5 Time); Remove adhesive (repair)(0.5 Time); Admin charge (addnl labor op); Caulk and sealer removal (addnl labor op)(1.0 Time); 2nd set up to pull front (repair)(1.5 Time); Align wheels (repair); Mask Jams (addnl labor oper)(0.5 Time); Reset electrical comp. (addnl labor op)(0.2 Time); Test drive (addnl labor op)(0.5 Time)	Panel, bodyside otr lt (blend refinish); Panel, bodyside otr rt (blend refinish); Panel, rocker lt (blend refinish); Panel, rocker rt (refinish); Pocket, ullmp openin lt (refinish)(0.1 Time); Pocket, ullmp openin rt (refinish)(0.1 Time); Cover, front bumper (refinish)(3.6 Time); Fender, front lt (refinish)(2.5 Time); Side member assebl rt (refinish)(0.7 Time); Side member assebl rt (refinish) (0.7 Time); Door shell, front lt (blend refinish)(1.3 Time); Door shell, front rt (refinish)(2.4 Time); Panel, quarter lt (refinish)(3.2 Time); Panel, quarter rt (refinish)(2.6 Time); Door, fuel filler lt (refinish); Panel, rear body (refinish)(2.4 Time); Two tone paint (refinish)(0.5 Time); Clear coat roof edges (refinish); Dress pinch welds (refinish)(0.5 Time); L/side gutter (refinish)(0.3 Time); R/side gutter (refinish)(0.3 Time); Back panel ref in (refinish)(1.0 Time)	Cover, front bumper (new part); Clip, grille lt (new part); Clip, grille rt (new part); Crsnbr, rad pnl lower (new part); Shield, heat (new part); Muffler assembly (new part); Retainer, front fend lt (new part); Retainer, front fend rt (new part); Shield, engine lower (new part)(0.4 Time); Shield, engine lower (new part)(0.4 Time); Resonator, air cleaner (new part)(0.3 Time); Dam, quarter glass lt (new part)(3.2 Time); Dam, quarter glass rt (new part); Panel, rear body (new part)(5.5 Time); Cover, rear bumper (new part); Corrosion protection (new part)(0.2 Time); Under cover coupe (new part)(0.3 Time); Cover for overspray (new part)(0.3 Time); Weld thru primer (new part)(0.5 Time); Seal sealer (new part)(1.0 Time); Engine compartment maskin (new part)(0.3 Time); Belly shield retainers (new part); Masking for primer (economy part)(0.3 Time); Refinishing mtl require (new part); Allied matl required (new part)	Labor - 51.7; Refinish - 29.2; Parts - 12.2		
5408	04959323 30101045-01	11/5/2014	Deductible	NA		\$ 500.00	Insured			Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		10/11/2014	Estimate	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 5,141.51	Geico Indemnity			Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		11/4/2014	Supplement 1	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 5,426.96	Geico Indemnity			Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Paint Supplies - \$26/hr					
		11/4/2014	Crawford's Final Invoice				\$ 9,093.05	\$3,616.93		Featheredge sand and bloc (addnl labor op)(1.0 Time); Install spare to move (addnl labor op)(0.3 Time); Reset electrical comp (addnl labor op)(0.2 Time)			Masking for primer (economy part)(0.3 Time)	Labor - 1.5; Parts - 0.3	
5340	04792676 60101012-01	8/29/2014	Deductible	NA		\$ 500.00	Insured			Body - \$48/hr					
		7/10/2014	Estimate	Geico	Ronee Le (rie@geico.com)	\$ -				Body - \$48/hr					
		8/21/2014	Supplement 1	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 3,359.40	Geico Casualty			Body - \$48/hr					
		8/29/2014	Supplement 2	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 610.00	Geico Casualty			Rt drip mldg (R & I assy)(0.5 Time); Lt drip mldg (R & I assy)(0.5 Time); Rt drain hose ft (R & I assy); (0.2 Time); Lt drain hose ft (R & I assy)(0.2 Time); Rt drain hose rear (R & I assy)(0.2 Time); Lt drain hose rear (R & I assy)(0.2 Time); Rt head air bag (R & I assy)(0.5 Time); Lt head air bag (R & I assy)(0.5 Time); Rt belt & retractor (R & I assy)(0.4 Time); Lt belt & retractor (R & I assy)(0.4 Time); Rt belt & ret w/out adaptiv (R & I assy)(0.3 Time); Lt belt & ret w/out adaptiv (R & I assy)(0.3 Time); Add time R & I sunroof (addnl labor op)(3.0 Time)	Sunshade gray (new part)	Labor - 4.6			
		9/22/2014	Crawford's Final Invoice				\$ 5,675.90	\$1,706.50		Admin charge (addnl labor op); Mldg, w/s garnish lt (R & I assy); Mldg, w/s garnish rt (R & I assy); Pul, center plr trim lt (R & I assy); Pul, center plr trim rt (R & I assy); Rail, luggage rack lk (R & I assy); Rail, luggage rack rt (R & I assy); Hsg, glass panel (R & I assy); Panel, bodyside trim lt (R & I assy); Panel, bodyside trim rt (R & I assy); Admin charge est (addnl labor op); Disconnect battery (addnl labor op)(0.3 Time); Reset electrical comp (addnl labor op)(0.2 Time); Test drive (addnl labor op)(0.5 Time); Reconnect headliner (addnl labor op)(0.5 Time)				Labor - 1.5	
5313	03296962 40101039-01	6/16/2014	Estimate	Geico	Craig Rogerson (crogerson@geico.com)	\$ -				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		7/11/2014	Supplement 1	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 3,844.94	Geico General Insurance			Body - \$48/hr; Paint - \$48/hr					
		8/12/2014	Supplement 2	Geico	Michael Wasyluk (Mwasyluk@geico.com)	\$ 3,975.52	Geico General Insurance			Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr		Rustproofing (addnl labor op)(0.5 Time); Lt roof rail (sublet repair); Map lamp assy w/o sunroof (R & I assy); Masking for caulk, & seam (addnl labor op)(0.5 Time); R & I glass (addnl labor op); Rt inner refinish (repair)(1.0 Time); W shield header w/o sunro (repair)(1.5 Time); Rear header weld zone (repair)(1.5 Time); Lt inner refinish (repair)(1.0 Time); Rt Extension (repair)(0.5 Time); Lt Extension (repair)(0.5 Time)	Clear coat (refinish)(3.0 Time); Rt inner refinish (refinish)(0.5 Time); W shield header w/o sunroof (refinish)(0.4 Time); Rear header weld zone (refinish)(0.4 Time); Lt inner refinish (refinish)(0.5 Time); Rt extension (refinish)(0.2 Time); Lt extension (refinish)(0.2 Time)	Paint materials capped (new part)	Labor - 7; Refinish - 5.2
		8/5/2014			Michael Wasyluk (Mwasyluk@geico.com)	\$ 3,023.34	Geico General Insurance			Admin charge (addnl labor op); Windshield, tinted (sublet repair); Switch, sldg roof (R & I assy)(0.1 Time); Handle, grab lt (R & I assy); Handle, front door o lt (R & I assy)(0.4 Time); Pillar center lt (sublet repair); Mldg, rear door belt lt (R & I assy)(0.3 Time); Gutter, tailgate lt (repair)(0.5 Time); Gutter, tailgate rt (repair)(0.5 Time); Glass, quarter time lt (sublet repair); Glass, tailgate heated (sublet repair); Color, sand buff (repair)(4.0 Time); Lt door w/strip drop top (R & I assy)(0.2 Time); Admin charge est (R & I assy); Adj. panel repair (repair)(2.0 Time); Cavity wash (addnl labor op)(0.5 Time); Disconnect battery (addnl labor op)(0.3 Time); Mask jams (addnl labor op)(0.5 Time); Prefit/measure welded pan (addnl labor op)(1.0 Time); Test drive (addnl labor op)(0.5 Time)	Adj panel refinish (refinish)(1.0 Time); Refinish inside roof (refinish)(1.0 Time); Lt door shell (refinish)(1.0 Time); Color tin (refinish)(0.5 Time); Two tone paint (refinish)(0.5 Time); Shell, tailgate (refinish)(3.8 Time); Panel, roof (refinish)(3.4 Time); Door shell, rear lt (refinish)(2.2 Time); Door shell, front lt (refinish)(3.2 Time); Panel, hood (refinish)(5.9 Time); Gutter, tailgate lt (refinish)(0.4 Time); Gutter, tailgate rt (refinish)(0.4 Time)	Door shell, front lt (new part)(5.8 Time); Tape, front door lt (new part)(0.2 Time); Dam, quarter glass lt (new part)(1.0 Time); Shell, tailgate (new part)(1.0 Time); Urethane Adhesive @ roof (economy part)(0.5 Time); Masking for CS & B (economy part)(0.5 Time); Masking for primer (economy part)(0.3 Time); Roof mldg studs @ 16 (economy part)(1.0 Time); Blind rivet @ 2 (new part)	Labor - 10.8; Refinish - 22.1; Parts - 10.3		
		8/13/2014	Crawford's Final Invoice				\$ 12,894.70	\$2,050.90							



Repair Order #	Inc. Co. Claim #	Date	Payment Basis	Insurance on Estimate	Adjuster/Approver	Assigned To	Approved By	Cost Center	Material	Lab Policy	Labor Notes	Labor Operations	Material Reimbursement	Vehicle Operations	Parts	Time Discrepancy
5221	03256816 50101046-01	3/13/2014	Deductible													
		2/11/2014	Estimate	Geico	Michael Wasylyk (Mwasylyk@geico.com)	\$ 500.00	Insured				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Paint Supplies - \$26/hr					
		3/18/2014	Supplement 1	Geico	Michael Wasylyk (Mwasylyk@geico.com)	\$ 4,008.06	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr	Trim support (repair)(4.0 Time); Reservoir (R & I assy); Shroud as an assy (R & I assy); Upper hose (R & I assy)(0.2 Time); Reservoir hose (R & I assy)(0.2 Time); Cooler line transmission (R & I assy)(0.5 Time); Lower hose (R & I assy)(0.4 Time); AC tube (R & I assy)(0.5 Time); Pressure hose (R & I assy)(0.3 Time); Dehydrator (R & I assy)(1.2 Time); Rt cowl grille (R & I assy)(0.7 Time); Lt cowl grille (R & I assy)(0.2 Time); Lt Door glass chevrolet (R & I assy)(0.6 Time); Lt module (R & I assy)(0.5 Time); Reset electronic comp (repair)(0.4 Time)	Repair clamp marks (refinish)(2.0 Time); Underside of rad support (refinish)(1.0 Time); Complete car cover (refinish)(0.2 Time)	Rustproofing (new part)(0.3 Time); Fender front (economy part)(1.3 Time); Freon (new part); Seam sealer (economy part)	Labor - 9.7; Refinish - 3.2; Parts - 1.6	
		8/12/2014			Crawford's Final Invoice	\$ 8,450.65	\$ 1,319.65									
5301	00322457 40101186-01	7/18/2014	Deductible													
		6/5/2014	Estimate	Geico	Michael Wasylyk (Mwasylyk@geico.com)	\$ 500.00	Insured				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		7/16/2014	Supplement 1	Geico	Michael Wasylyk (Mwasylyk@geico.com)	\$ 9,564.74	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Paint Supplies - \$26/hr	Wheel, steering (R & I assy); Vehicle to CJ's & pick up (addnl labor op)(1.0 - Time)		Refinishing mat'l require (new part)	Labor - 1.0	
		7/29/2014			Crawford's Final Invoice	\$ 16,674.69	\$ 4,583.67									
5208	03725147 70101103-01	1/23/2014	Estimate	Geico	Bryan Gazzillo (bgazzillo@geico.com)	\$ 1,013.57	Insured				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		2/19/2014	Supplement 1	Geico	Michael Wasylyk (mwasylyk@geico.com)	\$ 755.78	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr	Deflector, rocker pa lt (R & I assy); Deflector, rocker pa rt (R & I assy); Sight shield (R & I assy)(0.2 Time)	Clear coat (refinish)(0.3 Time)		Labor - 0.2; Refinish 0.3	
		2/20/2014			Crawford's Final Invoice	\$ 2,084.07	\$ 314.72				Brkt, front bumper m lt (R & I assy); Brkt front bumper m rt (R & I assy); Color, sand buff (repair)(1.3 Time); Cleanup for delivery (addnl labor op)(1.0 Time); Disconnect battery (addnl labor op)(0.2 Time); Reset electrical comp (addnl labor op)(0.2 Time); Test drive (addnl labor op)(0.5 Time)		Panel, hood (new part); Masking for primer (economy part)(0.3 Time); Cover for overspray (new part)(0.3 Time); Seam seal hood (economy part)(1.0 Time)	Labor - 3.2; Parts - 1.6		
5209	03725147 70101095-01	1/23/2014	Estimate	Geico	Bryan Gazzillo (bgazzillo@geico.com)	\$ 611.16	Insured				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		2/19/2014	Supplement 1	Geico	Michael Wasylyk (mwasylyk@geico.com)	\$ 1,826.49	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		2/20/2014			Crawford's Final Invoice	\$ 2,640.26	\$ 202.61				Cover, tow hook access (repair)(0.1 Time); Headlamp assy, halog lt (R & I assy); Headlamp assy, halog rt (R & I assy); Headlamps aim (addnl labor op)(0.4 Time); Duct, air intake (R & I assy); Color, sand buff (repair)(0.5 Time); Cleanup for delivery (addnl labor op)(1.0 Time); Raw bumper set up (addnl labor op)(1.0 Time); Disconnect battery (addnl labor op)(0.3 Time); Reset electrical comp (addnl labor op)(0.2 Time)	Test panel spray out (refinish)(0.5 Time); Cover, tow hook access (refinish)(0.1 Time)	Cover for overspray (new part)(0.3 Time)	Labor - 3.5; Refinish - 0.6; Parts - 0.3		
5250	#####	3/28/2014	Estimate	Geico	Michael Wasylyk (mwasylyk@geico.com)	\$ 2,662.72	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		4/18/2014	Supplement 1	Geico	Michael Wasylyk (mwasylyk@geico.com)	\$ 1,331.10	Geico General Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		7/7/2014			Crawford's Final Invoice	\$ 4,989.69	\$ 995.87				Door, shell front lt (repair)(7.0 Time); Cover, rear bumper (repair)(1.0 Time)		"H" emblem (economy part)(0.5 Time); Allied mat'l required (new part)	Labor - 8.0; Parts - 0.5		

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4350	014882351-01	5/20/2010	Deductible			\$ 100.00	Insured									
		5/20/2010	Estimate	Liberty Mutual Insurance Company	Robert Gahman (robert.gahman@libertymutual.com)	\$ 2,591.05	Liberty Mutual				Sheetmetal - \$46/hr; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish - \$46/hr; Pain Materials - \$24/hr					
		9/30/2010	Supplement 1	Liberty Mutual Insurance Company	Mark Bretz (mark.bretz@libertymutual.com)	\$ 4,332.11	Liberty Mutual				Sheetmetal - \$46/hr; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish - \$46/hr; Pain Materials - \$24/hr					
		10/8/2010	Supplement 2	Liberty Mutual Insurance Company	Mark Bretz (mark.bretz@libertymutual.com)	\$ 1,101.55	Liberty Mutual				Sheetmetal - \$46/hr; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish - \$46/hr; Pain Materials - \$24/hr					
		10/27/2010	Supplement 3	Liberty Mutual Insurance Company	Mark Bretz (mark.bretz@libertymutual.com)	\$ 270.69	Liberty Mutual				Sheetmetal - \$46/hr; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish - \$46/hr; Pain Materials - \$24/hr	Pan bodyside otr upr rt (Repair) - (0.5 Time)		Pnl bodyside otr upr rt - (1.6 Time)	Part price increase (new part)	Labor Operation - 0.5; Refinish - 1.6
		10/27/2010	Prelim Supplement 4	Liberty Mutual Insurance Company	Carl Specht (carl.specht@libertymutual.com)	\$ 756.42	Liberty Mutual				Sheetmetal - \$46/hr; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish - \$46/hr; Pain Materials - \$24/hr	Windshield, shaded (sublet repair); Handle, rr door oute lt (R & I Assembly) (0.9 Time); W/Strip, glass panel (R & I Assembly) (0.1 Time); Back glass, heated (sublet repair); panel, quarter lt (repair) (6.0 Time); lens, talliamp outer lt (R & I Assembly) (0.1 Time); rear bumper assy R & I (addnl labor op) (2.0 Time); Supt, rr bumper cove lt (R & I Assembly) (1.0 Time); Supt, rr bumper cove rt (R & I Assembly); Rewrite inspection stick (sublet repair); Layback left s/airbag (Addnl Labor Op) (0.5 Time); Layback right s/airbag (Addnl Labor Op) (0.5 Time); Lt upr rail/outer (Repair); Rt upr rail/outer (Repair); Reweld Roof Reinf (Addnl Labor Op) (1.0 Time); Prewash to refinish (Addnl Labor Op) (1.0 Time)		Panel, bodyside otr rt (Refinish); Pnl, rear door outer lt (Refinish) (1.1 Time); roof seal underside (Refinish) (0.5 Time); decklid seal underside (Refinish) (0.5 Time); hood seal underside (Refinish) (0.3 Time); roof underside (Refinish)(2.8 Time)	Allied mat'l required (new part); Refinishing mat'l required (new part); Corrosion protection (economy part); N/plate, deck lid (new part); Mldg, front door sca lt (new part) (0.2 Time); Panel, hood (new part) (1.1 Time)	Parts - 1.3; Labor Operation - 13.1; Refinish - 5.2
		10/29/2010	Crawford's Final Invoice					\$ 10,496.56	\$ 1,344.74							

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4509	018372075-01	4/26/2011	Deductible			\$ 1,000.00	Insured									
			Estimate			\$ 7,005.52	Liberty Mutual									
		4/6/2011	Supplement 1	Liberty Mutual Insurance Company	Jim Master (james.master@libertymutual.com)	\$ (203.97)					Sheet Metal - \$46/hour; Mech/Elec - \$48/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Materials - \$24/hr	Mldg, frt bumper cov rt (R & I Assembly); Fan assy, eng cooling (repair) (0.5 Time); Harness, i/p wiring (repair) (0.5 Time)		Brkt, front bumper m lt Refinish; Supt, radiator sd pa lt (Refinish) (0.2 Time)	Seal, inner fender lt	Labor Operation - 1.0; Refinish Operations - 0.2
		4/25/2011	Supplement 2	Liberty Mutual Insurance Company	Jim Master (james.master@libertymutual.com)	\$ 875.89	Liberty Mutual				Fan assy, eng cooling (R & I assy) (1.0 Time); Skirt, inner fender lt (R & I assy) (0.8 Time); Skirt, inner fender rt (R & I assy) (0.5 Time); Mldg, rocker panel lt (R & I assy) (0.4 Time); Mldg, rocker panel rt (R & I assy) (0.4 Time); Setup and measure (repair) (2.0 Time); unibody frame alignment (repair) (4.0 Time); Adjust and align latches (addnl labor op) (2.0 Time); Cleanup for Delivery (addnl labor op) (1.0 Time); Layback harness (addnl labor op) (0.5 Time); Reset electrical comp (addnl labor op) (0.2 Time); check and diagnose fans (Addnl labor op) (0.5 Time); Install glove box gear (addnl labor op) (0.5 Time); Dress welds (addnl labor op) (1.0 Time); Mask jams (addnl labor op) (0.5 Time); Brkt, rad supt lower lt (repair) (0.1 Time)		Color, sand and buff (0.5 Time)	Brkt, rad supt lower lt (Refinish) (0.1 Time), Dress pinch welds (Refinish) (1.0 Time)	Cover, front bumper (new part) (1.5 Time); latch, hood panel, lt (new part) ; latch, hood panel rt (new part); ret, hood lock cable lt (new part) (0.2 Time); Ret, hood lock cable rt (new part) (0.2 Time); Crsmbr, rad panel upr (new part) (1.0 Time); Brkt, rad pnl mounti lt (new part); Seal, inner fender lt (new part) (0.2 Time); Vanity plate mldg (new part) (0.3 Time); Glovebox Ins. #203680002 (new part); Refinish mat'l required (new part); Allied Mat'l required (new part); Masking for primer (economy part) (0.3 Time); Cover for Overspray (new part) (0.3 Time)	Labor Operation - 15.4; Paint and Materials - 0.5; Refinish - 0.2; Parts - 3.9
		4/26/2011	Crawford's Final Invoice						\$ 9,962.69	\$ 1,081.28						

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 12 of 39 PageID 3179																
Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
5247	029302898-01	4/3/2014	Deductible			\$ 500.00	Insured			Liberty Mutual Insurance Co	Sheetmetal - \$48/hr; Mech/Elec - \$50/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		3/19/2014	Estimate	Liberty Mutual Insurance Company	Carl Specht (carl.specht@libertymutual.com)	\$ 2,902.13	Liberty Mutual									
		4/8/2014	Supplement 1	Liberty Mutual Insurance Company	Carl Specht (carl.specht@libertymutual.com)	\$ 335.67	Liberty Mutual				Sheetmetal - \$48/hr; Mech/Elec - \$50/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr	Headlamps Aim (addnl labor op); Reinf, Inner Fender Lt (repair) (1.0 Time); Pnl, Inner Door Trim Lt (R & I assy); Mirror, Outer R/C Lt (R & I assy); Clean for Delivery (repair) (1.0 Time); Disconnect Battery (addnl labor op) (0.3 Time); Engine Compartment Maskin (addnl labor op) (0.5 Time); Prewash to Repair (addnl labor op) (0.5 Time); Reset Electrical Comp (addnl labor op) (0.2 Time); Chemically Strip Lkq Fend (repair) (1.0 Time); Prep Lkq Fender (repair) (1.0 Time); Test Drive (addnl labor op) (0.5 Time)	Fender, Front Lt (refinish) (2.3 Time); Test Panel Spray Out (refinish) (0.5 Time); Color Tint (refinish) (0.5 Time); Reinf, Inner Fender Lt (refinish)	Cover, Front Bumper (new part); Flex Additive (new part); Cover for Overspray (new part) (0.3 Time); Masking for Primer (economy part) (0.3 Time); Refinishing Mat'l Require (new part); Allied Mat' Required (new part); Lamp Assembly, Fog; Lt (new part); Ret, Radiator Support (new part); Fender Front, Lt (economy part) (2.2 Time); Retainer, Front Fend Lt (new part)	Labor Operations - 6.0; Refinish - 3.3; Parts - 2.8	
		4/8/2014	Crawford's Final Invoice						\$ 4,223.01	\$ 820.88						
5430	572997675039-202	11/13/2014	Estimate	American States Insurance Company	John Regler (john.regler@safeco.com) and Christopher Carper	\$ 3,959.61	Safeco Insurance Companies			American States Ins. Co; / Safeco						
		11/21/2014	Supplement 1	American States Insurance Company	John Regler (john.regler@safeco.com) and Christopher Carper	\$ 1,321.21	Safeco Insurance Companies									
		12/2/2014	Supplement 2	American States Insurance Company	John Regler (john.regler@safeco.com) and Christopher Carper	\$ 1,417.69	Safeco Insurance Companies									
		12/18/2014	Crawford's Final Invoice						\$ 7,788.82	\$ 1,090.31		Reset electrical comp (addnl labor op) (0.2 time)		Paint supplies capped (new part); Nameplate grille (new part); hinge, hood panel (new part) (2.3 time); hinge, hood panel (new part) (1.8 time); condenser a/c (new part) (0.5 time); refinishing mat'l require (new part)	Labor - 0.2; Parts - 4.6	
5188	505337140-201	2/17/2014	Deductible			\$ 1,000.00	Insured			Ohio Casualty / Safeco	Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		1/13/2014	Estimate	Safeco Insurance Company	John Regler (john.regler@safeco.com)	\$ 4,658.04	Ohio Casualty/ a Liberty Mutal Company				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		2/12/2014	Supplement 1	Safeco Insurance Company	John Regler (john.regler@safeco.com)	\$ 705.89	Ohio Casualty/ a Liberty Mutal Company							Paint Materials (new part)		
		7/28/2014	Crawford's Final Invoice						\$ 7,714.15	\$ 2,350.22		Pnl, front door oute rt (repair) (6.0 time); Glass, quarter tinte rt (sublet repair); Pnl, quarter trim up (R & I asy); Pnl, qtr trim lower (r & I assy)	Door, sheel front rt (refinish) (1.7 time)	Cover for overspray (new part) (0.3 Time); Masking for primer (economy part) (0.3 time)	Labor - 6.0; Refinish - 1.7; Parts - 0.6	

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 13 of 39 PageID 3180

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insured Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
5234	205359350	2/28/2014	Estimate	Peerless Indemnity Insurance Company	John Regler (john.regler@safeco.com)	\$ 2,781.42	Ohio Casualty/ a Liberty Mutal Company			Peerless Indemnity Insurance Company	Body - \$48/hr; Paint - \$48/hr; Frame - \$50/hr; Paint Supplies - \$26/hr					
		3/18/2014	Supplement 1	Peerless Indemnity Insurance Company	John Regler (john.regler@safeco.com)	\$ 309.52	Ohio Casualty/ a Liberty Mutal Company				Body - \$48/hr; Paint - \$48/hr; Frame - \$50/hr; Paint Supplies - \$26/hr					
		3/27/2014	Supplement 2	Peerless Indemnity Insurance Company	John Regler (john.regler@safeco.com)	\$ 2,411.21	Ohio Casualty/ a Liberty Mutal Company				Body - \$48/hr; Paint - \$48/hr; Frame - \$50/hr; Paint Supplies - \$26/hr					
		7/28/2014	Crawford's Final Invoice						\$ 7,644.95		\$ 2,142.80					
5182	4775332550 02-202	3/20/2014	Supplement 2	American States Insurance Company	John Regler (john.regler@safeco.com) and Heather Duerksen	\$ 2,568.52	Safeco Insurance			American State Insurance/ Safeco	Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		4/11/2014	Estimate/Deductible			\$ 2,366.31	Insured									
		4/14/2015	Supplement 3	American States Insurance Company	John Regler (john.regler@safeco.com) and Heather Duerksen	\$ 2,562.75	Safeco Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$26/hr					
		5/5/2014	Crawford's Final Invoice						\$ 8,705.82	\$ 1,207.94	Mldg, fender lower lt (R&I assembly) (0.1 time); mldg, fender lower rt (R&I assembly) (0.1 time); w/strip, frt door bo lt (R&I assembly) (0.1 time); w/strip, frt door bo rt (R&I assembly) (0.3 time); visor (R&I assembly) (0.3 time); cover air cleaner (R&I assembly); insert frt sill pnl (R&I assembly) (0.1 time); insert frt sill pnl rt (R&I assembly) (0.1 time); sunroof mldg (R&I assembly) (0.1 time); rt w/s pillar trim (R&I assembly) (0.2 time); lt w/s pillar trim (R&I assembly) (0.2 time); rope glass (repair) (0.6 time); leak and wind test (addnl labor oper) (1.0 time); mask for hardern (addnl labor oper) (0.5 time); mask jams (addnl labor oper) (0.5 time); mldg, flare lt (R&I assembly); mldg, flare rt (R&I assembly); scoop, hood panel (R&I assembly) (0.8 time); nozzle, w/s washer lt (R&I assembly); nozzle, w/s washer rt (R&I assembly); skirt, inner fender lt (R&I assembly) (0.3 time); arm, wiper blade lt (R&I assembly) (0.1 time); arm, wiper blade rt (R&I assembly) (0.1 time); mldg, w/s garnish lt (R&I assembly); mldg, w/s garnish rt (R&I assembly); visor, sun lt (R&I assembly) (0.3 time); visor, sun rt (R&I assembly) (0.2 time); handle, grab lt (R&I assembly); handle, grab rt (R&I assembly); pnl, center plr trim lt (R&I assembly) (0.8 time); pnl, center plr trim rt (R&I assembly); pnl, center plr trim rt (R&I assembly) (0.8 time); w/strip, top glass (R&I assembly) (0.1 time); antenna, assembly (R&I assembly) (0.3 time); deflector, glass panel (R&I assembly) (0.3time); color, sand and buff (addnl labor oper) (4.0 time); mask exterior (addnl labor oper) (0.2 time); mask jams (addnl labor oper) (1.0 time); reset electrical comp (addnl labor oper) (0.5 time); disconnect battery (addnl labor oper) (0.3 time); remove stone guard (addnl labor oper) (0.4 time); remove adhesive r&l (addnl labor oper) (0.6 time); remove guard adhesive (addnl labor oper) (0.2 time);rope windshield (addnl labor oper) (0.5 time); test drive (addnl labor oper) (0.5 time); masking for poly surfacer (addnl labor oper) (0.5 time); air duct (R&I assembly) (0.6 time)	Paint supplies (refinish) : panel, hood (refinish) (3.7 time); scoop, hood panel (refinish) (1.6 time); fender, front rt (refinish) (1.6 time); panel, cowl top (refinish) (0.3 time); panel, bodyside front rt (refinish) (1.2 time); panel, roof (refinish) (2.5 time)	Bumper cover clip (new part); panel hood (new part) (1.6 time); emission label (new part) (0.2 time); 2 clips #46064AE00 (new part); 2 bumper clips #909140007 (new part); clip #909140059 (new part); poly surfacer (economy part) (1.0 time); a/c hood label (new part) (0.1 time); masking for primer (economy part); r/r door stone guard (new part) (0.3 time)	Labor - 17.6; Refinish - 10.6; Parts - 3.2		

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Named on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
5299	7637782 65002	6/11/2014	Estimate	American States Insurance Company	John Regler (john.regler@safeco.com) and Jacob Barnes	\$ 7,597.38	Safeco Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$55/hr					
		7/17/2014	Supplement 1	American States Insurance Company	John Regler (john.regler@safeco.com) and Jacob Barnes	\$ 2,949.11	Safeco Insurance				Body - \$48/hr; Paint - \$48/hr; Mechanical - \$85/hr; Paint Supplies - \$28/hr	Seat assembly, drive (r & l assy) (0.3 time); lupper ctr prl trim (r & l assy) (0.3 time); l lower ctr plr trim (r & l assy) (0.5 time); recovery add for ac option (addnl labor op) (0.4 time)		Add't clear coat (refinish) (0.5 time)	Brkt, headlamp upper lt (new part); add't paint materials (new part)	Labor - 1.5; Refinish - 0.5
		7/25/2014										Horn, low note (r & l assy); reservoir w/s washer (r & l assy); housing, mirror oute lt (r & l assy); housing, mirror oute rt (r & l assy); supt, frt door handl lt (r & l assy); supt, frt door handl rt (r & l assy); set up and measure (addnl labor op) (2.0 time); clean for delivery (addnl labor op) (1.0 time); disconnect battery (addnl labor op) (0.3 time); hazardous waste disposal (sublet repair); diagnose a/b code (sublet repair); check and evaluate code (sublet repair)		Cover front bumper (refinish); panel, hood (refinish); hinge, hood panel (refinish); hinge, hood panel (refinish); panel assy rad supt (refinish) (8.5 time); fender front (refinish); side member assembl rt (refinish); door sheel front lt (blend refinish); door shell front rt (blend refinish); two tone paint (refinish) (0.5 time)	Panel, hood (new part); catch, hood safety (new part); Reinf, front bumper (new part); asborber, front energy (new part) (0.1 time); emblem grille (new part); brkt, headlamp (new part); panel assy rad supt (new part); radiator (new part); condenser a/c (new part); label, a/c condenser (new part); hose a/c (new part); extension, side memb rt (new part); horn, high note (new part); sensor oxygen (new part); module airbag control (new part); seatbelt front lt (new part); corrosion protection (new part) (0.2 time)	Labor - 3.3; Refinish - 9.0; Parts - 0.3

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer On Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4172	5837C16393 201021001L	1/12/2010	Deductible			\$ 500.00	Insured									
		1/12/2010	Estimate	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 531.88	Nationwide Insurance				Body - \$45/hr; Paint - \$45/hr; Paint Supplies - \$24/hr					
		1/22/2010	Supplment 1	Nationwide Enterprise	John McDonnell	\$ 36.57	Nationwide Insurance				Body - \$45/hr					
		1/22/2010	Crawford's Final Invoice					\$ 1,224.75	\$ 156.30						Refinish mtl require (new part); Allied mtl require (new part)	

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 16 of 39 PageID 3183

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Name of Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy	
4637	5837E37832 910021101P/R1	10/4/2011	Deductible			\$ 500.00	Insured				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr						
		10/4/2011	Estimate			\$ 1,006.58											
		10/11/2011	Supplement 1			\$ 250.58						Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr					
		10/20/2011	Crawford's Final Invoice					\$ 2,465.24	\$ 133.08			Color, sand buff (repair) (2.0 Time); Cleanup for delivery (addnl labor op) (1.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Reset electrical comp (addnl labor op) (0.2 Time); Mask jams (addnl labor op) (0.5 Time)	Color, tinte (refinish) (0.5 Time)	Corrosion protection (new part) (0.3 Time); Masking for primer (economy part) (0.3 Time)	Labor - 4.0; Refinish - 0.5; Parts - 0.6		
4573	5837E26675 007071101M/S1	9/16/2011	Deductible			\$ 250.00	Insured										
			Estimate			\$ 5,499.73	Nationwide Insurance										
		7/11/2011	Supplement 1	Nationwide Enterprise	Thomas Havas (havast@nationwide.com)	\$ 369.32	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr						
		7/28/2011	Supplement 2	Nationwide Enterprise	W. Scott Wensing	\$ 2,014.38	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr	Cover, Front Bumper (repair); Modling Assy W/RR Camera (R & I assy) (0.3 Time)		Rt bodyside Panel Assy (Refinish) (3.5 Time)	Nameplate "Lacrosse" (new part) (0.3 Time); Seam Sealer Kit (economy part); Lt Applique (new part); Lt Applique Rear (new part) (0.3 Time)	Labor - 0.3; Refinish - 3.5; Parts - 0.6	
		8/19/2011	Supplement 3	Nationwide Enterprise	Christian Harper	\$ 633.44	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr	Frt Bumper Cvr Overhaul (addnl labor op) (2.2 Time); W/Strip, Grille Upper (R & I assy); Lamp Assembly, Fog Lt (R & I assy) (0.5 Time); Lamp Assembly, Fog Rt (R & I assy) (0.5 Time); Hood Panel R & I (R & I assy) (2.0 Time); Hsg, Blower (R & I assy) (2.2 Time); Windshield, Tinted (sublet repair); Panel Assy, Body Sid Lt (repair) (16.0 Time); Panel Bodyside Otr Rt (repair) (2.0 Time); Grille, Inst Pnl Spkr (R & I assy) (0.2 Time); Compt, Glove Box (R & I assy); Duct Air Inlet (R & I assy); Outlet, Air Vent Duct (R & I assy); Panel, Instrument (R & I assy) (5.8 Time); Pnl, Inst Cluster (R & I assy); Bezel, Instrument Pnl (R & I assy); Radio, AM/FM W/C/D (R & I assy) (0.4 Time); Control Unit, Radio (R & I assy) (0.4 Time); Display Unit, Inst Pnl (R & I assy) (0.1 Time); Frame, Rear Seat Rt (R & I assy); Frame, Rear Seat Lt (R & I assy) (1.3 Time); Frame, Front Seat Rt (R & I assy) (1.3 Time); W/Strip, Frt Door Bo Lt (R & I assembly); Rear Door R & I (R & I assy); W/Strip, RR Door Bod Lt (R & I assy); Mldg, Rear Door Uppel/F (R & I assy); Mldg, Rear Door Belt Lt (R & I assy); Back Glass, Heated (sublet repair); Panel, Quarter Lt (repair) (4.0 Time); Mldg, Deck Lid (R & I assy); Taillamp Assembly Lt (R & I assy); Taillamp Assembly Rt (R & I assy); Lamp, License Rt (R & I assy) (0.1 Time); Rear Bumper Cover R & I (addnl labor op) (0.9 Time); Brkt, Rear Bumper Mt Lt (R & I assy); Brkt Rear Bumper Mt Rt (R & I assy); Harness, Rear Bumper (R & I assy) (0.5 Time); Snsr, Obstacle Warn Lt (R & I assy); Snsr, Obstacle Warn Rt (R & I assy); Dis/Rec E Harness (addnl labor op) (1.0 Time); Mask Jams (addnl labor op) (2.0 Time); Remove Adhesive (addnl labor op) (1.0 Time); License Plate (R & I assy) (0.3 Time); Disconnect Battery (addnl labor op) (0.3 Time); D & R Steering Columb (addnl labor op) (0.5 Time); Engine Compartment Maskin (addnl labor op) (0.5 Time); Carpeting (R & I assy) (1.0 Time); Roof Seam Sealer (reapir) (4.0 Time); Cleanup Broken Glass (addnl labor op) (2.0 Time); Remove ADH @ Hood Ornamen(addnl labor op) (0.6 Time); Prefit Welded Panel (addnl labor op) (1.0 Time); labor to Program Key (sublet repair)	Cover, Front Bumper (refinish); Panel, Bodyside Qtr Rt (Refinish) (1.5 Time); Panel, Quarter (blend refinish); Cover, Rear Bumper (refinish); Panel, Hood (refinish) (6.3 Time); Fender, Front Rt (refinish); Panel Assy, Body Sid Lt (refinish) (7.3 Time); Door Shell, Front Lt (refinish); Lid, Rear Deck (refinish) (2.8 Time); Refinish Inner Roof Pane (refinish) (1.0 Time)	Panel, Hood (salvage part); Label, Radiator Support (new part); Applique, Frt Door F, Lt (new part); Glass, Front door T Lt (new part); Applique Assy, Rear Lt (new part); Panel, Roof (new part) (25.9 Time); N/Plate, Deck Lid (new part) (0.3 Time); Flex Additive (economy part); Corrosion Protection (economy part) (0.3 Time); Cover Car Exterior (economy part) (0.3 Time); Cover Car Interior (economy part) (1.0 Time); Allied Mat'l Required (new part); Cavity Wax (economy part) (0.3 Time); Masking for Primer (economy part) (1.0 Time); Roof Rib Adhesive (economy part) (1.0 Time); Weld Thu Primer (economy part) (1.0 Time); Refinishing Mat'l Require (new part); Sound Deadner Pad (economy part) (0.3 Time); Cover for Overspray (new part) (0.3 Time); Retape Hood Ornaments (economy part) (0.6 Time); Key #13500226 (new part)	Labor - 74.3; Refinish - 18.9; Parts - 32.2		
		8/29/2011	Supplement 4	Nationwide Enterprise	John McDonnell	\$ 319.37	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr						
		9/16/2011	Supplement 5	Nationwide Enterprise	John McDonnell	\$ 1,386.25	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr						
		9/16/2011	Crawford's Final Invoice					\$ 16,914.81	\$ 6,692.32								



Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 17 of 39 PageID 3184

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4908	5837B61800 211151201S /H1	11/21/2012	Estimate	Nationwide Enterprise	Eric Fink (finke@nationwide.com)	\$ 1,524.88	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr					
		11/30/2012	Supplement 1	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 299.61	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr					
		12/5/2012		Crawford's Final Invoice					\$ 2,441.74	\$ 617.25		Clean for delivery (addnl labor op) (1.0 Time); Color, sand buff (addnl labor op) (1.0 Time); disconnect battery (addnl labor op) (0.3 Time); mask jams (addnl labor op) (0.5); reset electrical comp (addnl labor op) (0.2 Time); test drive (addnl labor op) (0.5 Time); Handle, front door o rt (R & I assy)	Cover, front bumper (refinish); Panel, hood (blend, refinish); Pnl, front door oute rt (blend refinish)	Masking for primer (economy part) (0.3 Time); refinishing matl required (new part); allied matl required (new part); cover, front bumper (new part); fender, front rt (new part) (2.2 Time); corrosion protection (economy part) (0.3 Time); cover car exterior (economy part) (0.3 Time)	Labor - 3.5; Parts - 3.1	
4866	5837B50857 109121201 M/S1	9/20/2012	Deductible			\$ 500.00	Insured									
		9/20/2012	Estimate	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 6,496.55	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		10/4/2012	Supplement 1	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 3,415.08	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		10/9/2012	Supplement 2	Nationwide Enterprise	Eric Fink (finke@nationwide.com)	\$ 1,168.10	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr; Paint Supplies - \$27/hr	Cover, Console (R & I assy) (0.2 Time); Frame, Front Seat Rt (R & I assy) (0.4 Time); Pnl, Rear Compt Trim Rt (R & I assy) (0.2 Time); Rt Front W/ Strip (R & I assy); 2nd of Hadlmps for Rpl Co (R & I assy) (0.8 Time); Upper Clmn Cover (R & I assy) (0.3 Time); Lower Clmn Cover (R & I assy) (0.3 Time); Steering Wheel (R & I assy) (0.7 Time); R & I Instrument Panel (R & I assy) (5.0 Time); Radio Pnl (R & I assy) (0.6 Time); Cluster Assy (R & I assy) (0.6 Time); Glove Box Assy Black (R & I assy) (0.3 Time); Lt Lower Dash Pnl Back (R & I assy) (0.3 Time); Rt Lower Dash Pnl Back (R & I assy) (0.3 Time); Center Panel (R & I assy) (0.4 Time); Lt Air Outlet (R & I assy) (0.2 Time); Rt Air Outlet (R & I assy) (0.2 Time); Cluster Visor (R & I assy) (0.2 Time); Rt Concole Assy (R & I assy) (1.1 Time); Lt Concole Assy (R & I assy) (1.1 Time); Psng Air Bag (R & I assy) (1.4 Time); Rt Real Sill Plate (R & I assy) (0.2 Time); RT Low Sill Plate (R & I assy) (0.3 Time); Trim to fit/Test Fit (R & I assy) (1.0 Time); Wind Sheild Lt & Rt Trim (R & I assy) (1.0 Time); Rt Pillar Molding (R & I assy); Rt Air Vent (R & I assy) (0.2 Time); O/H Front Susp Rt (addnl labor op) (2.5 Time); Extn, RR Bumper Oute Rt; Test Drive; Rt Apron Assy Hss; Rt Rear Wheel Alloy; Repair Weld Zone; Create Section Plate; Repair Clamp Damage BS (repair) (2.0 Time)	Panel, Bodyside Fron Rt (refinish) (3.6 Time); Extn, RR Bumper Oute Rt (refinish) (1.7 Time); Rt Apron Assy Hss (refinish) (1.0 Time); Repair Clamp Damages (refinish) (1.0 Time); Repair Clamp Dam Rt Side (refinish) (1.0 Time)	Rt Front Sill Plate (new part) (0.2 Time); Lt Lower Seal (new part) (0.2 time); Rt F Wheel (new part) (0.3 Time); 2nd Car Cover (new part) (0.3 Time); Bearing/Hub/Knuckle(new part) (1.6 Time); Paint Supplies (new part)	Labor - 26.4; Refinish - 8.3; Parts - 2.6	
		10/19/2012	Supplement 3	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 1,143.24	Nationwide Insurance				Cover, Rear Bumper (repair) (2.0 Time); Mldg W/ Garnish (R & I assy); Rt Front W/ Strip (R& I assy) (0.3 time); 3rd Test Drive (addnl labor op) (0.5 Time); Unibody-Frame Inc Setup (repair) (2.5 Time); Cover, Front Bumper (repair) (2.0 Time); Module, Hdllmp Contro Rt (R & I assy) (1.0 Time); Pnl Assembly, Inr Fn Rt (repair) (1.0 Time); Bracket, Tire Indica Rt (R & I assy) (0.2 Time); Cover, Steeling Column (R & I assy); End, Tie Rod Outer L/F; (R & I assy) End, Tie Rod Outer R/F (R & I assy); Reservoir, W/S Washer (R & I assy); Mldg, W/S Garnish Rt (R & I assy) (0.3 Time); Plate, Front Sill Lt (R & I assy) (0.2 Time); Plate, Front Sill Rt (R & I assy) (0.2 time); Pnl, Center Plr Trim Rt (R & I assy); Pnl, Inner Door Trim RT (R & I assy); Reinf, Center Pillar Rt (repair) (4.0 Time); Mldg, Rear Door Belt Rt (R & I assy) (0.9 Time); Mldg, Rear Door Belt Lt (R & I assy) (0.3 Time); Tape, Rear door (R & I assy) (0.3 Time); Glass, Quarter Tinte Rt (sublet repair); Pan, floor (repair) (4.0 Time); Taillamp Assembly, O Rt (R & I assy) (0.3 Time); Dress Welds (addnl labor op) (2.0 Time); Re-Setup Charge (reapir) (2.0 Time); Inside Rocker (repair) (1.0 Time); Center Pillar (repair) (1.0 time); Underside Frt Wheelhouse (repair) (1.0 Time); Diagnose Steering Gear As(repair) (1.0 Time); 2nd Test Drive (addnl labor op) (0.5 Time); Diagnose Failed Parts (addnl labor op) (3.0 Time); Diagnose R/F Bearing (addnl labor op) (0.5 Time); Cleanup for Delivery (addnl labor op) (1.0 Time); Disconnect Battery (addnl labor op) (0.3 Time); Mask Jams (addnl labor op) (0.5 Time); Reset Electrical Comp (addnl labor op) (0.2 Time); Test Drive (addnl labor op) (0.5 Time)	Pnl Assembly, Inr Fn Rt (refinish); Panel, Hinge Pillar Rt (refinish) (0.7 Time); Pillar Hinge (refinish); Pan, Floor (refinish); Cover, Rear Bumper (refinish) (1.4 Time); Panel, Hood (blend refinish) (1.9 Time); Reinf, Inner Fender Rt (refinish) (0.8 Time); Strut Assembly, Fron Rt (new part) (0.3 Time); Pnl, Rckr & Plr, Cent Rt (refinish) (3.1 Time); Reinf, Rocker Panel Rt (refinish) (0.8 Time); Door Shell, Front Rt (refinish) (2.6 Time); Mldg, Front Door Low Rt (refinish); Panel, Quarter Rt (refinish) (2.7 Time); Mldg, Rear Door Lowe Rt (refinish); Door Shell, Rear Rt (refinish) (2.6 Time); Pillar, Inner Center Rt (refinish) (0.7 Time); Reinf, Center Pillar Rt (refinish) (0.8 Time); Rt Roof Rail (blend refinish) (0.2 Time); Dress Pinch Welds (refinish) (2.0 Time); Inside Rocker (refinish) (1.0 Time); Center Pillar Refinish (refinish) (1.0 Time); Ref Under Wheelhouse (refinish) (1.0 Time)	Module, Hdllmp contro Rt (new part) (0.2 Time); Reinf, Inner Fender Rt (new part) (5.6 Time); Fender, Front Rt (new part) (1.9 Time); Skirt, Inner Fender Rt (new part); Wheel, Front Rt (salvage part) (0.3 Time); Hub, Front Wheel Lt (new part) (1.6 Time); Knuckle, Steering R/F (new part) (0.4 Time); Arm, Lower Control R/F (new part) (0.3 Time); Strut Assembly, Fron Rt (new part) (0.3 Time); Link Kit, Front Stab Rt (new part) (0.2 Time); Gear Assy, Steering (new part) (6.8 Time); End, Tie Rod Outer R/F (new part) (0.4 Time); End, Tie Rod Inner R/F (new part) (8.1 Time); Plate, Front Sill Rt(new part); Pnl, Inner Door Trim Rt (new part) (0.4 Time); Tape, Front Door Rt (new part) (0.1 Time); Flex Additive (economy part); Undercoating (new part); Caulk (economy part) (1.0 Time); Cover Car Interior (economy part) (0.3 Time); A/M Tire 235/55R18 (economy part); Cover for Overspray (economy part) (0.5 Time); Chippguard (economy part) (0.5 Time); Sound Deadner Pad (economy part) (0.5 Time); Cavity Wax (economy part) (0.3 Time); Masking for Primer (economy part) (0.3 Time)	Labor - 51.2; Refinish - 30.4; Parts - 32.1		
		11/1/2012	Supplement 4	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 816.87	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Name of Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		11/14/2012	Supplement 5	Nationwide Enterprise	William Scott Wensing (wensingw@nationwide.com)	\$ 1,598.83	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
			Supplement 6													
		12/3/2012	Supplement 7	Nationwide Enterprise	William Scott Wensing (wensingw@nationwide.com)	\$ 1,004.94	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Frame - \$48/hr					
		11/16/2012	Crawford's Final Invoice					\$20,561.24	\$ 4,417.63							

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4966	58C859582 OEM	2/6/2013	Deductible			\$ 100.00	Insured									
		2/6/2013	Estimate	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 3,302.66	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr					
		2/22/2013	Supplement 1			\$ 160.11	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr					
		2/22/2013	Supplement 2	Nationwide Enterprise	Monica Eagles (eaglesm@nationwide.com)	\$ 56.20	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$27/hr	W/ Strip, Belt Outer Lt (R & I assy); Clean for Delivery (repair) (1.0 Time); Disconnect Battery (addnl labor op); Color, sand buff (repair) (1.0 Time) Engine Compartment Maskin (addnl labor op) (0.3 Time); Mask Jams (addnl labor op) (0.5 Time); Test Drive (addnl labor op) (0.5 Time)		Color Tint (refinish) (0.5 Time); Test Panel Spray Out (refinish) (0.5 Time)	W/Strip, Belt Outer Lt (new part); Corrosion Protection (new part) (0.3 Time); Reseal Fender Foam (economy part) (0.3 Time); Masking for Primer Foam Sealer 3M#8463 (economy part) (0.6 Time)	Labor 3.3 - Refinish - 1.0; Parts - 1.2
		2/22/2013	Crawford's Final Invoice					\$ 4,175.25	\$ 556.28							
5157	5873E378329110 81301P/R1	11/13/2013	Estimate	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 3,715.79	Nationwide Insurance			Nationwide Insurance	Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$30/hr					
		11/26/2013	Supplement 1	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 505.79	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$30/hr					
		12/3/2013	Supplement 2	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 1,083.39	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr					
		12/19/2013	Supplement 3	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 292.50	Nationwide Insurance	\$ 5,597.47			Body - \$48/hr; Paint - \$48/hr	Adtl paint materials (addnl labor op)		Paint materials capped (refinish)	2nd Car cover (new part)	
		12/13/2013	Crawford's Final Invoice					\$ 7,583.54	\$ 1,778.57			Airbag sensor, front lt (R & I assy); Airbag sensor, front rt (R & I assy); A/C evacuate and charge (addnl labor op); Refrigerant rcvry setup (addnl labor op) (0.6 Time); Reservoir, w/s washer (R & I assy); Mldg, roof drip rt (R & I assy) (0.4 Time); Glass, quarter tinte rt (sublet repair); Pnl, quarter trim up rt (R & I assy); Pnl, qtr trim lower rt (R & I assy) (0.6 Time); Rear bumper cover R & I (addnl labor op); Color, sand buff (repair) (2.0 Time); Cleanup for delivery (addnl labor op) (1.0 Time); Engine compartment maskin (addnl labor op) (0.5 Time); Featheredge sand and bloc (addnl labor op) (0.5 Time); Mask jams (addnl labor op) (0.5 Time); Rope windshield (addnl labor op) (0.5 Time); Test drive (addnl labor op) (0.5 Time)		Hinge, hood panel rt (refinish); Fender, front rt (refinish); Test panel spray out (refinish) (0.5 Time)	Absorber, front bumper (new part); Hinge, hood panel rt (new part); Panel assembly, rad supt (economy part); Brkt, radiator mount rt (new part); Duct, air intake (new part); Mldg, roof drip (new part); Masking for primer (economy part) (0.3 Time)	Labor - 8.1; Refinish - 0.5; Parts - 0.3

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 20 of 39 PageID 3187

Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5158	5837U011995110 81301C/F1	12/1/2013	Deductible			\$ 750.00	Insured			Nationwide Insurance Company						
		11/13/2013	Estimate	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 5,670.00	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr					
		11/26/2013	Supplment 1	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 1,626.08	Nationwide Insurance				Body - \$48/hr					
		12/19/2013	Supplement 2	Nationwide Enterprise	William Scott Wensing (wensinw@nationwide.com)	\$ 1,520.88	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr	Lt lwr ctr pillar trim (R & I assy) (0.2 Time); Lt regulator (R & I assy) (1.4 Time); Lt door check (R & I assy) (0.3 Time); Lt pressure valve (R & I assy) (0.1 Time); Label install (addnl labor op) (0.5 Time); Glovve box black (R & I assy) (0.3 Time)			Color tint (economy part) (0.5 Time)	Labor - 2.8; Parts - 0.5
		7/21/2014			Crawford's Final Invoice			\$ 12,811.57	\$ 3,244.61			Pad, insulator hood (R & I assy); Steering column o/h (R & I assy); Windshield, shaded (sublet repair); Arm, wiper blade lt (R & I assy) (0.1 Time); Arm, wiper blade rt (R & I assy) (0.1 Time); Cover, console (R & I assy); HSG, cluster (R & I assy); Console, center (R & I assy); Panel, instrument (R & I assy); Radio, am/fm (R & I assy); Plate, front sill lt (R & I assy); Plate, front sill rt (R & I assy); Plate, rear sill lt (R & I assy); Front door R & I (addnl labor op); W/strip, frt door bo lt (R & I assy); W/strip, belt outler lt (R & I assy) (0.3 Time); Glass, front door t lt (R & I assy); Module, frt dr carri lt (R & I assy); Switch, frt door lt (R & I assy); Handle, front door o lt (R & I assy); Striker, front lock lt (R & I assy); Rear door R & I (addnl labor op); Switch, rear door lt (R & I assy); Striker, rear lock lt (R & I assy); Grille, vent rt (R & I assy); Grille, vent lt (R & I assy); Color, sand buff (repair) (3.0 Time); Glass cleanup (addnl labor op) (4.0 Time); Cleanup for delivery (addnl labor op) (1.0 Time); Layback wiring harness (repair) (1.0 Time); Engine compartment maskin (addnl labor op) (0.5 Time); Featheredge sand and bloc (addnl labor op) (1.0 Time); Mask jams (addnl labor op) (1.0 Time); Reset electical comp. (addnl labor op) (0.2 Time); Test drive (addnl labor op) (0.5 Time)	Panel, hood (refinish) (5.1 Time); Fender, front lt (refinish); Pnl, rck & Plr, cent lt (refinish); Test panel spary out (refinish) (0.5 Time)	Cover, front bumper (new part) (1.3 Time); Brkt, front bumper m lt (new part); Hinge, hood panel lt (new part) (1.6 Time); Hinge, hood panel rt (new part) (1.6 Time); Panel assembly, rad supt (new part) (7.9 Time); Cover, rad supt panel (new part); Condenser, A/C (economy part); Label, engine (new part); Mldg assy, w/s reveal (new part); Mldg, front door sca lt (new part); Rustproofing (economy part); Pinstripes-tape (economy part) (0.6 Time); Corrosion protection (new part) (0.3 Time); Refrigerant (economy part); Freon & oil (economy part); Seal seal hood (economy part) (1.0 Time); Masking for primer (economy part) (0.3 Time); Allied matl required (new part)	Labor - 12.7; Refinish - 5.6; Parts - 13.6	

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 21 of 39 PageID 3188																
Repair Order #	Ins. Co. Claim #	Date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5183	5837E399491201 1301C/M1	12/23/2013	Estimate	Nationwide Enterprise	Eric Fink (finke@nationwide.com)	\$ 3,108.66	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$30/hr					
		1/23/2014	Supplement 1	Nationwide Enterprise	Eric Fink (finke@nationwide.com)	\$ 694.09	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$30/hr					
		1/24/2014			Crawford's Final Invoice			\$ 5,493.63	\$ 1,690.88			Front bumper cover R & I (addnl labor op); Pnl, center plr trim lt (R & I assy); Pnl, inner qtr trim lt (R & I assy); Color, sand buff (repair) (2.0 Time); Test drive (addnl labor op) (0.5 Time); Prefit l/f door (addnl labor op) (1.0 Time); featheredge sand bloc (addnl labor op) (1.0 Time); Mask jams (addnl labor op) (0.5 Time); REset electrical comp. (addnl labor op) (0.2 Time); Front fender R & I lt (R & I assy); speaker, front door lt (R & I assy); handle, rr door oute lt (repair) (0.5 time); shield, quarter inne lt (R & I assy); Cleanup for delivery (addnl labor op) (1.0 Time); Rope back glass (addnl labor op) (0.5 Time); Rope windshield (addnl labor op) (0.5 Time)	Test panel spray out (refinish) (0.5 Time)	Cover for overspray (economy part) (0.3 Time); Masking for primer (economy part) (0.3 Time); refinishing matl require (new part); allied matl require (new part); seam seal tape l/r door (economy part) (0.5 Time); glass kit (economy part)	Labor - 9.7; Refinish - 0.5; Parts - 1.1	
5292	603990-GA-1	5/29/2014	Estimate	Nationwide Affinity Insurance Company	Robert Gehringer (gehrinr@nationwide.com)	\$ 6,504.66	Nationwide Insurance			Nationwide Affinity Insurance Company	Body - \$48/hr; Paint - \$48/hr					
		6/10/2014	Supplement 1	Nationwide Affinity Insurance Company	Robert Gehringer (gehrinr@nationwide.com)	\$ 1,677.11	Nationwide Insurance				Body - \$48/hr; Paint - \$48/hr; Paint Supplies - \$30/hr	Air Grill Center w/p Chro (R & I assy) (0.2 Time); Support Cylinder (R & I assy) (0.1 Time); Windshield (R & I assy); Cover Engine Compartment (R & I assy) (0.3 Time); Insert, RR Sill Plat Lt (addnl labor op)		Headliner Clip (new part)		
		6/26/2014	Supplement 2	Nationwide Affinity Insurance Company	Robert Gehringer (gehrinr@nationwide.com)	\$ 679.10	Nationwide Insurance				Body - \$48/hr	Mldg, w/s Garnish Lt (R & I assy); Mldg, w/s Garnish RT (R & I assy); Masking to CS&B (addnl labor op) (0.5 Time); Engine Compartment Maskin (addnl labor op) (0.5 Time); Test Drive (addnl labor op) (0.5 Time); Reset Airbag Code (sublet repair) (1.0 Time); Grille, Frt Bmpr Cvr (R & I assy); Headlamp Assy, Halog Lt (R & I assy); Headlamps Aim (addnl labor op); Pad, Insulator Hood (R & I assy) (0.5 time); Mldg, w/s Reveal Sid Lt (R & I assy); Mldg, w/s Reveal Sid Rt (R & I assy); Headliner R & I (R & I assy) (4.0 Time); Pnl, Center Plr Trim Lt (R & I assy); Pnl, Center Plr Trim Rt (R & I assy); W/ Strip, Front Door Lt (R & I assy) (0.3 Time); Glass, Front Door T Lt R & I assy); W/ Strip, Rear Door Lt (R & I assy); W/ Strip, Rear Door, Rt (R & I assy); Channel, Rear Glass Lt (R & I assy); Rear Vent Class R & Lt (R & I assy) (0.9 Time); Striker, Rear Lock Lt (R & I assy) (0.4 Time); Striker, Rear Lock Rt (R & I assy) (0.4 Time); Glass Panel, Roof (R & I assy); Deflector, Glass Panel R (R & I assy); Cover, SLiding Roof Inr (R & I assy); Shield, Quarter Inne Lt (R & I assy); Pnl, Inner Qtr Trim Lt (R & I assy); Pnl, Inner Qtr Trim Rt (R & I assy); Panel, Quarter Trim Up Lt (R & I assy); Panel, Quarter Trim Up Rt (R & I assy); Mldg, Tailgate Lower (R & I assy); Handle, Tailgate Outer (R & I assy); W/ Strip, Tailgate (R & I assy); Lamp, High Mounted Stop (R & I assy); Brkt, Rear Bumper Mt Lt (R & I assy); Brkt, Rear Mt Rt (R & I assy); Clean for Delivery (addnl labor op) (1.0 Time); Disconnect Battery (addnl labor op) (0.3 time); Mask Jams (addnl labor op) (1.0 Time); Featheredge Sand and Bloc (addnl labor op) (2.0 Time)	Door, Fuel Filler, RT (refinish); Panel, Hood (refinish); Fender, Front Lt (blend refinish); Panel Assy, Body Sid Lt (refinish); Panel Assy, Body Sid Rt (refinish); Door Shell, Rear Lt (refinish) (2.3 Time); Panel, Roof (refinish); Gutter, Tailgate Lt (refinish); Gutter, Tailgate Rt (refinish)	Panel, Hood (new part); Lamp, High Mounted Stop (new part); Corrosion Protection (new part); Masking for Primer (economy part) (0.3 Time); Refinishing Mat'l Require (new part); Allied Mat'l Require (new part)	Labor - 13.3; Refinish - 2.3; Parts - 0.3	
		6/26/2014	Crawford's Final Invoice					\$ 13,328.32	\$ 4,467.45							

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 22 of 30 PageID 3189																
Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4390	38-007-97501	10/18/2010	Estimate	State Farm Insurance Companies	James Shifflett	\$ 1,431.42	Insured				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Materials - \$24/hr					
		10/22/2010	Supplement 1	State Farm Insurance Companies	Angelo Depero	\$ 381.50	Insured				Sheetmetal - \$46/hr; Refinish \$46/hr; Paint Materials - \$24/hr					
		11/4/2010	Supplement 2	State Farm Insurance Companies	Angelo Depero	\$ 14.31	State Farm Mutual Automobile Insurance Company				u					
		10/29/2010	Crawford's Final Invoice						\$ 2,260.30		\$ 433.07		Panel, bodyside trim lt (R & I assy) (1.2 Time); glass, quarter shade lt (R & I assy); clean for delivery (addnl labor op) (1.0); disconnect battery (addnl labor op) (0.3 Time); reset electcal comp. (addnl labor op) (0.3 Time); mask jams (addnl labor op) (0.5 time); clr/snd/buff 1 qtr pnl (addnl labor op) (0.5 time); prewash to refinish (addnl labor op) (0.5 Time)	Color tint (refinish) (0.5 Time)	Masking for primer (economy part) (0.2 Time); allied mat as required (economy part); ref mat as req (economy part)	Labor - 4.3; Refinish - 0.5; Parts - 0.2
4326	21486668000 000 000000	11/19/2010	Deductible			\$ 500.00	Insured				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Supplies - \$24/hr					
		8/20/2010	Estimate	State Farm Insurance Companies	James Guthrie	\$ 16,523.23	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Supplies - \$24/hr					
		10/21/2010	Supplement 1	State Farm Insurance Companies	James Guthrie	\$ 677.80	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Supplies - \$24/hr			Grille retainer (new part); firt bumper cover ret (new part); headliner retainers (new part)		
		11/2/2010	Supplement 2	State Farm Insurance Companies	James Guthrie	\$ 1,784.05	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Supplies - \$24/hr			End, tie rod outer l/f (new part)		
		11/2/2010	Preli Prior Estimate	State Farm Insurance Companies	James Guthrie	\$ 2,321.47	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish \$46/hr; Paint Supplies - \$24/hr	Tray, battery (R & I assy); Module, computer (R & I assy) (0.2 Time); Mount, engine lt (R & I assy); mount, engine rt (R & I assy); suspension align, firt (addnl labor op); hose front brake lt (R & I assy); caliper, brake disc, lt (R & I assy); arm lower control r/f (R & I assy); spring, front coil lt (R & I assy); spring, front coil rt (r & I assy); bar, front stabilizer (R & I assy); compressor, air rt (R & I assy); brkt, front susp sen lt (R & I assy); shaft assembly, axel l/f (R & I assy); shaft assembly axel r/f (R & I assy); yoke, front axle lt (r & I assy); hose, power srg coling (r & I assy); mldg, w/s reveal sid rt (R & I assy); reservoir, w/s washer (r & i assy) (0.3 Time); pinch welds (addnl labor op) (2.0 Time); temp fab (addnl labor op) (0.3 Time); lift/support eng (addnl labor op) (0.5 Time); clean up broken glass (addnl labor op) (1.0 Time); misc. fluid lines (addnl labor op) (2.0 Time); tow vehicle to sanners (sublet repair); tow vehicle from sanners (sublet repair); masking for pweld repair (addnl labor op) (1.0 Time); diagnose a/b computer (sublet repair); fabricate fish plates (addnl labor op) (1.0 Time); collision access labor (addnl labor op) (1.0 Time); disconnect battery (addn labor op) (0.3 Time); engine compartment maskin (addnl labor op) (0.5 Time); rear seat assem (R & I assy) (1.0 Time)	Brkt, headlamp mtg rt (refinish); pnl, front door oute lt (refinish) (2.4 time); pnl, rear door oute rt (refinish); color tint (refinish) (0.5 time); pinch welds (refinish) (2.0 Time)	Radiator (new part); brkt, radiator mount lt (new part); mount, radiator rt (new part); condensor, a/c (new part); panel, inner fender lt (new part) (8.0 Time); cradle, engine (new part); hub, front wheel lt (new part); knuckle, steering l/f (new part); arm, lower control l/f (new part); gear assy, steering (new part); clock spring (new part); retainer, headliner lt (new part); airbag, roof lt (new part); airbag, roof rt (new part); seatbelt, middle lt (new part); coolant (new part) (0.3 Time); pwr strng fluid (new part) (0.3 time); upr rad brkt gromm (new part) (0.1 time); clip #25725191 (new part); retainer 15795653 (new part); retainer 11518017 (new part); retainer 10121502 (new part); retainer 11589291 (new part); rivets 11516807 (new part); refinishing matl required (new part); allied matl required (new part); masking for primer (economy part) (0.3 Time); weld thu primer (new part) (0.5 Time)	Labor - 13.7; Refinish - 4.9; Parts - 9.5	

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
		11/5/2010	Supplement 3	State Farm Insurance Companies	James Guthrie	\$ 28.40	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Supplies - \$24/hr					
		11/10/2010	Supplement 4	State Farm Insurance Companies	James Guthrie	\$ 451.15	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Supplies - \$24/hr					
		11/19/2010	Crawford's Final Invoice					\$ 27,862.44	\$ 4,411.46							

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 24 of 39 PageID 3191

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursment	Refinish Operations	Parts	Time Discrepancy
4451	38M0721 47	1/20/2011	Deductible			\$ 500.00	Insured									
		1/20/2011	Estimate	State Farm Insurance Companies	Angelo Depero	\$ 2,277.92	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					
		1/26/2011	Supplement 1	State Farm Insurance Companies	Angelo Depero	\$ 549.50	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					
		2/3/2011	Supplement 2	State Farm Insurance Companies	Angelo Depero	\$ 106.27	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					
		2/15/2011	Supplement 3	State Farm Insurance Companies	Angelo Depero	\$ 5.15	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					
		2/4/2011	Crawford's Final Invoice						\$ 3,900.14	\$ 466.45		Tailgate glass (R & I assy) (1.6 Time); Shell, tailgate (repair) (10.0 Time); glass, tailgate heated (sublet repair); mldg, t/gate garnish (R & I assy) (0.2 time); Panel, rear body (repair) (6.0 Time)			Mldg, t/g glass lower (new part); bulb, license lamp lt (new part) (0.1 Time); bulb, license lamp rt (new part) (0.1 Time); tape, rear bumper (new part) (2.0 time)	Labor - 17.8; Parts - 2.2
4543	38-M145-433	6/13/2011	Estimate	State Farm Insurance Companies	James Guthrie	\$ 1,883.19	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					
		6/21/2011	Supplement 1	State Farm Insurance Companies	James Guthrie	\$ 201.01	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr					



Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		6/22/2011					Crawford's Final Invoice	\$ 2,412.59	\$ 328.39			Mldg, rear door side lt (repair) (0.3 Time); mldg, rear door side lt (R & I assy); mask jams (addnl labor op) (0.5 Time); cover car exterior (sublet repair) (0.2 Time); clean up for delivery (addnl labor op) (1.0 time); reset electrical comp. (addnl labor op) (0.2 time) (disconnect battery) (addnl labor op) (0.3 Time)		Mldg, rear door side lt (refinish) (1.1 Time)	seam sealer (economy part); 3m Heavy steam sealer (new part); sound deadner matl (economy part) (0.3 time)	Labor - 2.5; Refinish - 1.1; Parts - 0.3
4366	38-L980-44001	5/27/2011	Deductible			\$ 1,984.00	Insured									
		11/2/2010	Estimate	State Farm Insurance Companies	James Guthrie	\$ 5,132.52	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr				
		1/6/2011	Supplement 1	State Farm Insurance Companies	James Guthrie	\$ 958.11	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr; Refinish - \$46/hr; Paint Materials - \$24/hr				
		3/15/2011	Supplement 2	State Farm Insurance Companies	James Guthrie	\$ 233.00	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr; Refinish - \$46/hr; Paint Materials - \$24/hr				
		4/4/2011	Supplement 3	State Farm Insurance Companies	James Guthrie	\$ 217.27	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr				
		4/14/2011	Supplement 4	State Farm Insurance Companies	James Guthrie	\$ 145.58	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr				
		12/3/2013				\$ 455.89	State Farm Mutual Automobile Insurance Company					Sheetmetal - \$46/hr; Mech/Elec - \$46/hr; Frame - \$48/hr; Refinish - \$46/hr; Paint Materials - \$24/hr				

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		5/27/2011					Crawford's Final Invoice	\$ 8,438.14	\$ (688.23)			W/strip, hood panel lt (R & I assy) (0.3 Time); w/strip, hood panel rt (R & I assy) (0.3 time); windshield, shaded (sublet repair); frame, windshield up lt (repair) (1.0 Time); panle, inner cowl tr rt ( R & I assy) (0.1 Time); front door r & I rt (R & I assy) (0.5 Time); w/strip, front door lt (R & I assy); w/strip, front door rt (R & I assy) (0.2 Time); color, sand buff (addnl labor op) (2.5 time); disconnect battery (addnl labor op) (0.3 time); differential noise (repair) (1.0 time); collision access labor (addnl labor op) (1.0 time)		Panel, hood (refinish) (4.2 time); brkt, front fender rt (refinish) (0.2 time); frame, windshield upr (refinish) (0.5 time)	Masking for primer (economy part) (0.3 time)	Labor - 7.2; Refinish - 4.9; Parts - 0.3

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4782	38-0Z03-88901	6/20/2012	Deductible			\$ 1,000.00	Insured									
		5/4/2012	Estimate	State Farm Insurance Companies	George Galczynski and William Haggerty	\$ 2,229.82	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					
		6/5/2012	Supplement 1	State Farm Insurance Companies	William Haggerty	\$ 721.01	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					
		6/13/2012	Supplement 2	State Farm Insurance Companies	George Galczynski	\$ 353.35	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					
		6/20/2012	Crawford's Final Invoice					\$ 5,099.74	\$ 795.56			Brace, bedside panel rt (R & I assy); brace, bedside panel (R & I assy); cable, t/g support lt (R & I assy); cable, t/g support rt (R & I assy); Ureth, adhes, rem (addnl labor op) (0.1 Time); back tape glass mldg (addnl labor op) (0.4 Time); w/strip, belt outer rt (R & I assy); panel, beside, inner rt (repair) (2.0 Time); Pnl, wheelhouse inne rt (repair) (2.0 Time); Panel, bed front (repair) (0.5 Time); remove adhesive @ gate (addnl labor op) (0.3 Time); remove tape @ gate (addnl labor op) (0.3 Time); rope off rear glass (addnl labor op) (0.5 time); remove tape @ mldg (addnl labor op) (0.3 time); remove adh @ door (addnl labor op) (0.3 Time); mask jams (addnl labor op) (1.0 Time); cover & mask bed (addnl labor op) (1.0 Time); shell, tailgate (repair) (3.0 Time); clean for delivery (addnl labor op) (1.0 Time); color sand buff (addnl labor op) (2.0 time); layback wire harness (repair) (1.0 time); retape spoiler (addnl labor op) (0.3 time); disconnect battery (addnl labor op) (0.2 time)		Extn, bedside panel rt (refinish); reinf, bedside panel rt (refinish); bracket, bedside pane rt (refinish); inside bed panel (refinish) (2.0 Time); Panel, bedside inner rt (refinish) (1.7 Time); pnl, wheelhouse inne rt (refinish); panel, bed front (refinish) (1.4 Time); refinish inside bed ledge (refinish) (0.5 Time)	Masking for primer (economy part) (0.3 time); weld thu primer (economy part) (0.5 time); stoneguard (economy part); corrosion protection (economy part) (0.8 time); glass install kit (economy part); cover for overspray (economy part) (1.0 time); seam sealer (economy part)	Labor - 14.4; Refinish - 5.6; Parts - 2.6
		12/14/2011	Estimate	State Farm Insurance Companies	James Guthrie						Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					
		1/10/2012	Supplement 1	State Farm Insurance Companies	James Guthrie	\$ 5,047.88	Insured (paying estimate and supplement 1)				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4702	38-067F-69901	1/23/2012	Supplement 2	State Farm Insurance Companies	James Guthrie	\$ (76.76)					Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish - \$48/hr; Paint Materials - \$26/hr					
		8/5/2013	Tow Bill			\$ 111.00	State Farm Automobile Insurance Company									
		2/17/2012	Crawford's Final Invoice					\$ 6,669.51	\$ 1,621.63			Mount, engine rear (R & I assy); suspension align, firt (addn labor op); Tire, rf, balance (sublet repair); clean for delivery (addnl labor op) (1.0 time); color sand buff (addnl labor op) (1.5 time); remove tape adhesive (addn labor op) (0.3 Time); hazardous waste disposal (sublet repair); reset electrical comp (addn labor op) (0.5 Time); tire disposal (sublet repair); touch up bolts (addnl labor op) (0.5 time); clean up grease @ axle (addnl labor op) (1.0 time); engine cradle diagnose (addnl labor op) (0.5 time); set up jack stands (addnl labor op) (0.5 time); mask jams (addnl labor op) (0.5 time)			Fender, front rt (new part); flex additive (economy part); corrosion protection (new part) (0.3 Time); retape mldgs (economy part) (0.3 time); tire turanza (new part)	Labor - 6.3; Part 0.6

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 29 of 39 PageID 3196																
Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
4981	38-2F46-51101	2/27/2013	Deductible			\$ 528.45	Insured									
		2/27/2013	Estimate	State Farm Insurance Companies	Jenn Deutel	\$ 5,361.55	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		3/5/2013	Supplement 1	State Farm Insurance Companies	Jenn Deutel	\$ 1,022.60	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		3/13/2013	Supplement 2	State Farm Insurance Companies	James Guthrie	\$ 1,517.51	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		3/27/2013	Supplement 3	State Farm Insurance Companies	James Guthrie	\$ 975.73	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		4/3/2013	Supplement 4	State Farm Insurance Companies	James Guthrie	\$ 87.01	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		4/6/2013		Crawford's Final Invoice					\$12,688.65	\$ 2,514.30		Pinch weld (repair) (0.4 Time); grille, front brake rt (R & I assy) (0.4 Time); blade assembly, wipe lt (R & I assembly); blade assembly, wipe rt (R & I assembly); screen, cowl (R & I assy); Rod, front door check rt (R & I assy) (0.2 time); rear door r & i rt (addnl labor op); layback radiator (addnl labor op) (0.5 time); d&r wiring harness (addnl labor op) (1.0 Time); bleed brake system w/abs (addnl labor op) (1.5 time); diagnose r/f sus damage (addnl labor op) (1.0 time); remove adh @ rr dr mldg (repair) (0.3 time); remove adh @ rr dr panel (repair) (0.3 time); dress welds (addnl labor op) (2.0 time); masking pinch weld repair (addnl labor op) (0.5 time); remove tape adh @ rf mldg (addnl labor op) (0.2 time); retape r/f door mldg (addnl labor op) (0.2 time); changeover applique (r & i assy) (0.3 time); changeover belt mldg (r & i assy) (0.5 time); changeover scalp mldg (r & i assy) (0.2 time); changeover lower strip (r & i assy) (0.1 time); changeover door handle (r & I assy) (0.1 time); change over trim panel (R & I ass) (0.2 Time); change over glass (r & I assy) (0.8 time); change over motor (R & i assy) (1.0 time); changeover speaker (r & i assy) (0.3 time); changeover r/channel (r & i assy) (0.5 time); change over lock (r & I assy) (0.5 time); prep lkq door (repair) (2.0 time); engine comp masking (addnl labor op) (0.5 time); rope windshield (addnl labor op) (0.5 time); rope back glass (addnl labor op) (0.5 time); test drive (addnl labor op) (0.5 time); remove adh @ l/f door (repair) (0.3 time); remove adh @mldg (repair) (0.3 time); prefit door (addnl labor op) (1.0 time)	Pinch weld (refinish) (0.4 time); color, sand buff (refinish) (3.0 time); dress pinch welds (refinish) (2.0 time)	Arm, lower control r/f (new part) (1.3 time); retape rr dr sid mldg (economy part) (0.3 time); retape l/side grille (economy part) (0.2 time); cover for overspray (new part) (0.3 time); weld thu primer (new part) (0.5 time); retape l/f mldg (economy part) (0.3 time)	Labor - 18.6; Refinish - 5.4; Parts - 2.9	
		4/3/2013	Estimate	State Farm Insurance Companies	James Guthrie	\$ 9,074.99	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 30 of 39 PageID 3197																
Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5010	38-2139-70001	4/8/2013	Supplement 1	State Farm Insurance Companies	James Guthrie	\$ 2,160.35	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		4/12/2013	Supplement 2	State Farm Insurance Companies	Jenn Deutel	\$ 719.08	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		4/23/2013	Suplement 3	State Farm Insurance Companies	Jenn Deutel	\$ 460.36	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		4/23/2013	Suplement 4	State Farm Insurance Companies	Jenn Deutel	\$ 178.08	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		5/7/2010	Supplement 5	State Farm Insurance Companies	Jenn Deutel	\$ 206.34	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$48/hr; Mech/Elec - \$48/hr; Frame - \$50/hr; Refinish \$48/hr; Paint Materials - \$26/hr					
		5/10/2013	Crawford's Final Invoice						\$17,358.92		\$ 4,059.72	Engine Harness replacement (sublet repair); tow receipts (sublet repair); separate apron section (addnl labor op) (0.1 time); separate rail ext (addnl labor op) (0.5); prefit welded pan (addnl labor op) (1.0 time); prefit measure welded (addnl labor op) (1.0 time); weld burn repair (repair) (1.0 time); tow to sloans (sublet repair); tow from sloans (sublet repair); test drive (addnl labor op) (0.5 time); remove oem lables (addn labor op) (0.5 time); unibody frame set up (repair) (6.0 time);; susp align 4 wheel (addnl labor op); clean for delivery (addnl labor op) (1.0 time); color sand buff (addnl labor op) (3.0 time); dress welds (addn labor op) (2.0 time); disconnect battery (addnl labor op) (0.3 time); shipping hid conver kit (sublet repair)		Weld damage (refinish); test panel spray out (refinish) (0.5 time); 2 tone refinish (refinish) (0.5 time); dress pinch welds (refinish); (2.0 time)	Cavity wax (economy part); mask jams (economy part) (1.0 time); maksing for primer (economy part) (0.3 time); weld thu primer (economy part) (0.3 time); battery (new part); kensun, hid conversion (economy part) (1.0 time); engine harness (new part)	Labor - 16.9; Refinish - 3.0; Parts - 2.6
		12/13/2013	Deductible			\$ 1,000.00	Insured				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$29/hr					
		11/18/2013	Estimate	State Farm Insurance Companies	William Haggerty (13-03-03)	\$ 6,365.42	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$29/hr					
		11/25/2013	Supplement 1	State Farm Insurance Companies	William Haggerty (13-03-03)	\$ 1,096.07	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$29/hr					

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster / Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5162	38-3K01-88001	12/13/2013	Supplement 2	State Farm Insurance Companies	William Haggerty (13-03-03)	\$ 455.89	State Farm Mutual Automobile Insurance Company			State Farm Insurance Companies	Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$29/hr					
						\$ 209.91	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$29/hr					
		12/13/2013	Crawford's Final Invoice					\$11,150.57				Front bumper overhaul (addnl labor op); cable, hood lock (R & I assy); Reinf, inner fender rt (repair) (0.5 time); reinf, inner fender lt (repair) (4.0 time); mount, engine cradle lt (r & I assy) (0.4 time); mount, engine cradle rt (r & I assy) (0.4 time); side member assembl lt (repair) (1.0 time); side member assembl rt (repair) (1.0 time); clean for delivery (addnl labor op) (1.0 time); unibody frame alignment (repair) (6.0 time); color sand buff (addnl labor op) (2.0 time); layback wire harness (repair) (0.8 time); set up for structural pull (addnl labor op) (2.0 time); inside r/s frame channel (repair) (0.5 time); inside l/s frame channel (repair) (0.5 time); disconnect battery (addnl labor op) (0.3 time); dress welds (addnl labor op) (2.0 time); mask underside of floor (addnl labor op) (0.5 time); engine compart masking (addnl labor op) (0.5 time); mask jams (addnl labor op) (0.5 time); prefit/measure welded pan (addnl labor op) (1.0 time); test drive (addnl labor op) (0.5 time); diagnostic check airbag (addnl labor op)		Panel, inner fender rt (refinish); side member assembl lt (refinish); side member assembl rt (refinish); 2 tone refin inner panels (refinish) (0.5 time); ref inside r/s channel (refinish) (0.5 time); ref inside l/s channel (refinish) (0.5 time); dress pinch welds (refinish) (2.0 time); ref inside support (refinish) (0.8 time)	Moulding, grille lt (new part); moulding grille rt (new part); cover car exterior (economy part) (0.5 time); anti-freeze coolant (new part); cavity wax (economy part) (0.3 time); masking for primer (economy part) (0.3 time); weld thru primer (new part) (0.5 time)	Labor - 25.4; Refinish - 4.3; Parts - 1.6

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 32 of 39 PageID 3199																	
Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Shortfall Itemization Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy	
5283	38-409K-97401	5/23/2014	Deductible			\$ 500.00	Insured			State Farm Insurance Companies							
		3/1/2014	Estimate	State Farm Insurance Companies	Terry Maloney 13-03-01						Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr						
		5/22/2014	Supplement 1	State Farm Insurance Companies	William Haggerty 13-03-03						Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr						
			Crawford's Final Invoice						\$ 1,385.56		\$ 1,385.56		Frt bumper covr overhaul (addnl labor op); clean for delivery (addnl labor op) (1.0 time); disconnect battery (addnl labor op) (0.3 time)		Color tint (refinish) (0.5 time); nib sanding (refinish) (0.5 time)	Flex additive (new part)	Labor - 1.3; Refinish - 1.0
5200	38-3P3693802	1/11/2014	Estimate	State Farm Insurance Companies	Bob Innocent 13-03-01	\$ 1,884.86	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$28/hr						
		1/27/2014	Supplement 1	State Farm Insurance Companies	Jenn Deutel 13-03-07	\$ 996.20	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$28/hr						
		2/11/2014	Supplement 2	State Farm Insurance Companies	Jenn Deutel 13-03-07	\$ 63.99	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$28/hr						
		2/12/2014	Supplement 3	State Farm Insurance Companies	Jenn Deutel 13-03-07	\$ -	State Farm Mutual Automobile Insurance Company				Pillar hinge (repair) (1.0 time); w/strip, frt door lt (R & I assy); w/strip, rr door (R & I assy); mldg, roof drip (r & I assy); mldg, rear drip (r & I assy); clean vehicle (addnl labor op) (1.0 time); color sand buff (repair) (0.5 time); dis battery (repair) (0.5 time); rope windshield (addnl labor op) (0.5 time); rope back glass (addnl labor op) (0.5 time); headlamps aim (addnl labor op) (0.5 time); fog lamps aim (addnl labor op) (0.3 time); mast, attena (r & i assy) (0.2 time); guard fender mud (r & I assy) (0.3 time); pnl, inner door trim (r & I assy) (0.5 time); flex additive (addnl labor op); corrosion protection (addnl labor op) (0.3 time); cover car exterior (addnl labor op) (0.3 time); clean for delivery (addnl labor op) (1.0 time); color sand buff (addn labor op) (2.0 time); remove adhesive (addnl labor op) (0.3 time); hazardous waste removal (addnl labor op); retape mldgs (addnl labor op) (0.5 time); remove adhesive @ door (repair) (0.3 time); collision access labor (addnl labor op) (1.0 time); disconnect battery (addnl labor op) (0.3 time); mask jams (addnl labor op) (0.5 time); reset elec comp (addnl labor op) (0.2 time); test drive (addnl labor op) (0.5 time)		Pillar hinge (refinish); panel, bodyside otr (blend refinish); pnl, cab side outer (blend refinish); tint paint to match (refinish) (0.5 time); cover for overspray (refinish) (0.5 time); pnl, front end finis lt (refinish); panel, hood (blend refinish) (1.9 time); color tint (refinish) (0.5 time); raw bumper set up (refinish) (1.3 time)	Brk, front bumper (new part); cover for overspray (new part) (0.3 time); maksing for primer (economy part) (0.3 time)	Labor - 11.2; Refinish - 4.7; Parts - 0.6		
		3/13/2014	Supplement 4	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 70.36	State Farm Mutual Automobile Insurance Company										
		7/28/2014	Crawford's Final Invoice						\$ 4,940.38		\$ 1,924.95						
		9/16/2014	Deductible			\$ 500.00	Insured										



Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 33 of 39 PageID 3200																
Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5375	38-510S-44902	8/4/2014	Estimate	State Farm Insurance Companies	Ed Winchester 13-03-07	\$ 114.66	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					
		9/12/2014	Supplement 1	State Farm Insurance Companies	William Haggerty 13-03-03		State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					
		9/22/2014	Crawford's Final Invoice						\$ 2,223.56				Mldg, rear door belt (R & I assy) ; rear vent glass (r & I assy); handle, rr door oute (r & I assy); corrosion protection (addnl labor op) (0.2 time); clean for delivery (addnl labor op) (1.0 time); disconnect battery (addnl labor op) (0.3 time); mask jams (addnl labor op) (0.5 time); reset electrical comp (addnl labor op) (0.2 time)		Pnl, rear door outer (refinish); color tint (refinish) (0.5 time); color sand buff (refinish) (1.0 time)	Brkt, rear bumper mt (new part); Brkt, rear bumper mt (new part); masking for primer (economy part) (0.3 time)
5363	38-509F-070	10/3/2014	Deductible			\$ 300.24	Insured			State Farm Insurance Companies						
		8/25/2014	Estimate	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 8,348.38	State Farm Mutual Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					
		9/4/2014	Supplement 1	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 2,351.83	State Farm Mutual Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					
		9/16/2014	Supplement 2	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 319.00	State Farm Mutual Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					
		9/29/2014	Supplement 3	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 58.67	State Farm Mutual Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish - \$50/hr; Paint Materials - \$30/hr					

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		9/30/2014	Supplement 4	State Farm Insurance Companies	William Haggerty 13-03-03	\$ 609.70	State Farm Mutual Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$30/hr	Fender front lt (repair) (3.0 time); fender front rt (repair) (4.0 time); Mldg. pillar drip rt (R & I assy) (0.2 time); w/strip frt door (r & I assy); w/strip rear door (r & I assy); pillar bedside front (repair) (0.8 time); pillar bedside front (repair) (0.8 time); shield, beside pane (r & i assy) (0.3 time); taillamp assy (r & I assy); brkt rear bumper mt (repair) (0.5 time); clean for delivery (addn labor op) (1.0 time); unibody frame alingment (repair) (2.5 time); color sand buff (repair) (4.0 time); retape mldgs (addnl labor op) (0.5 time); remove adhesive @ door (repair) (0.3 time); collision access labor (addnl labor op) (1.0 time); disconnect battery (addnl labor op) (0.3 time); mask jams (addnl labor op) (0.5 time); reset elec comp (addnl labor op) (0.2 time); test drive (addnl labor op) (0.5 time); layback harness (addnl labor op) (1.0 time); r/door adhesive remove (addnl labor op) (0.2 time); l/door adhesive remove (addnl labor op) (0.2 time); set up measure (addnl labor op) (4.0 time); weld burn at top bed (repair) (0.5 time); weld burn inside lip (repair) (0.5 time); tail lamp pocket inner (repair) (0.5 time); wheel opening repair (repair) (0.5 time); wheel opeing repair (repair) (0.5 time); re attach bed brace (repair) (0.8 time); back tape rear glass (addnl labor op) (0.5 time); back tape windshield (addnl labor op) (0.5 time);		Pnl, rear door outer (blend refinish) (1.2 time); panel, bedside outer rt (refinish) (3.5 time); pillar bedside fron (refinish) (0.8 time); pillar bedside fron (refinish); color tint (refinish) (0.5 time); refinish inside bed lip (refinish) (0.5 time); tail lamp pocket inner (refinish) (0.5 time); dress frame rails (refinish) (1.0 time)	Bumper, front (new part) (2.8 time); radiator (new part); pipe exhaust (new part) (0.4 time); bumper assy, rear step (new part); anti freeze coolant (new part); bumper assy rear (new part); masking for primer (economy part) (0.3 time); weld thu primer (new part) (0.5 time); rear step pad (new part)	Labor - 31.1; Refinish - 8.0; Parts - 4.0
		10/24/2014			Crawford's Final Invoice			\$ 16,691.39	\$ 5,003.82							
5238	38-3v3948401	2/24/2014	Deductible	State Farm Insurance Companies	Thomas Nye	\$ 500.00	State Farm Mutual Automobile Insurance Company									
		2/24/2014	Estimate	State Farm Insurance Companies	Thomas Nye	\$ 1,861.95	Stat Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$30/hr					
		3/7/2014	Supplement 1	State Farm Insurance Companies	William Haggerty (13-03-03)	\$ 1,790.59	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$30/hr					
		3/17/2014	Supplement 2	State Farm Insurance Companies	Jenn Deutel (13-03-07)	\$ 914.67	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$30/hr					
		4/18/2014	Supplement 3	State Farm Insurance Companies	William Haggerty (13-03-03)	\$ 251.14	State Farm Mutual Automobile Insurance Company				Sheetmetal - \$50/hr; Mech/Elec - \$50/hr; Frame - \$52/hr; Refinish \$50/hr; Paint Materials - \$30/hr	Qtr Glass R&I (r & I assy); collision pull (addn labor op) (2.5 time)			Tape, rear door rt (new part) (0.1 time); clip (new part); pnl, qtr rr pan rt (new part) (3.2 time)	Labor - 2.5; Parts - 3.3

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insured on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
		4/23/2014			Crawford's Final Invoice			\$ 4,818.35				Chg to rekey supp 3 (addnl labor op); panel, bodyside fron rt (repair) (1.0 time); panel, bodyside otr, rt (repair) (6.0 time); plate, front sill rt (r & i assy) (0.2 time); pnl, center plr trim rt (r & i assy) (0.2 time); front door r&l rt (addnl labor op) (0.6 time); w/strip, frt door bo rt (r & i assy) (0.5 time); flex additive (addnl labor op); set up and measure (repair) (2.0 time); clean for delivery (addnl labor op) (1.0 time); unibody frame align (repair) (6.0 time); clean for delivery (addnl labor op) (2.0 time); nib sanding (addnl labor op); rr wheel & tire (r & i assy) (0.5 time); cover interior to protect (addnl labor op) (0.5 time); dress welds (addnl labor op) (0.5 time); dress welds (addnl labor op) (2.0 time); layback wire harness (repair) (1.0 time); remove heavy seam sealer (repair) (1.0 time); floor pan underside (repair) (1.0 time); masking at under panel (addnl labor op) (5.0 time); back tape windshield (addnl labor op) (0.5 time); mask jams (addnl labor op) (0.5 time); section plate @ qtr sail (repair) (1.0 time); section plate @ lock pill (repair) (1.0 time); masking underside (addnl labor op) (0.5 time); dis/rec charness (repair) (0.5 time); featheredge sand (addnl labor op) (1.0 time); prfit/measure welded pan (addnl labor op) (1.0 time); prewsh to repair (addnl labor op) (0.5 time); test drive (addnl labor op) (0.5 time); raw bumper set up (addnl labor op) (1.0 time); floor panel (repair) (0.5 time)		Panel assy, body side rt (refinish); Panel, bodyside fron (refinish); door shell, rear (blend refinish); rein, tlilmp opening lt (refinish); pnl, wheelhouse oute rt (refinish); panel bodyside otr rt (refinish) (2.5 time); panel rocker rt (refinish) (1.2 time); pnl, rear door outer rt (blend refinish); rein, quarter inner (refinish) (0.5 time); extn, qtr whl open (refinish) (0.2 time); panel rear body (refinish) (1.6 time); pan, rear floor (refinish) (1.8 time); prep raw rr bmpr (refinish) (1.0 time); color tint (refinish) (0.5 time); color sand buff (refinish) (2.0 time); dress pinch welds (refinish) (2.0 time); floor pan underside ref (refinish) (1.0 time); floor panel (refinish) (1.0 time)	Cover, rear bumper (new part) (1.0 time); clip, rear bumper (new part); undercoating (new part) (0.3 time); caulk (economy part) (1.5 time); sound deadner material (economy part) (1.0 time); maksing for primer (economy part) (0.3 time); cavity wax (economy part) (0.3 time); weld thu primer (economy part) (0.5 time); cover for overspray (new part) (0.3 time)	Labor - 40.5; Refinish - 15.3; Parts - 5.2

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5011	13-1914136-01	4/3/2013	Deductible			\$ 392.63	Insured									
		4/3/2013	Estimate	Progressive	Steve Teague (steague1@progressive.com)	\$ 7,302.18	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr; Mechanical - \$50/hr					
		4/8/2013	Supplement 1	Progressive	Steve Teague (steague1@progressive.com)	\$ 4,403.04	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr; Mechanical - \$50/hr					
		4/13/2013	Supplement 2	Progressive	Steve Teague (steague1@progressive.com)	\$ 978.40	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr; Mechanical - \$50/hr					
		4/26/2013	Supplement 3	Progressive	Steve Teague (steague1@progressive.com)	\$ 2,556.76	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr; Mechanical - \$50/hr					
		5/1/2013	Supplement 4	Progressive	Steve Teague (steague1@progressive.com)	\$ 423.54	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr; Mechanical - \$50/hr					
		5/1/2013	Crawford's Final Invoice					\$ 16,779.78	\$ 615.86							

Repair Order #	Ins. Co. Claim #	Estimate/ Invoice date	Payment Basis	Insurer on Estimate	Adjuster/ Appraiser	Payment Amount	Payment Made By	Crawford's total	Shortfall	Insurer on Policy	Labor Rates	Labor Operation	Paint and Material Reimbursement	Refinish Operations	Parts	Time Discrepancy
5371	14-3124430-01	9/2/2014	Deductible	NA	John Baker - no number or contact information listed	\$ 500.00	Insured			Progressive Insurance - Policy 50359990-8						
		9/12/2014	Supplement 1	Progressive Advanced Insurance Co	Rob Canfield (#516059) - no contact information listed	\$ 4,823.14	Progressive Advanced Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr					
		9/24/2014	Supplement 2	Progressive Advanced Insurance Co	Rob Canfield (#516059) - no contact information listed	\$ 145.96	Progressive Advanced Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr					
		9/29/2015	Supplement 3	Progressive Advanced Insurance Co	Steven Teague (#273261)	\$ 463.41	Progressive Advanced Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr					
		10/1/2014	Supplement 4	Progressive Advanced Insurance Co	Rob Canfield (#516059) - no contact information listed	\$ 523.77	Progressive Advanced Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr	Front bumper cover R & I (addnl labor op); Grille assembly (R & I assy); Headlamp assy, halog lt (R & I assy) (0.3 Time); Headlamp assy, halog rt (R & I assy) (0.3 Time); Pad, insulator hood (R & I assy); Seatbelt, front lt (R & I assy); Seatbelt, front rt (R & I assy); Seatbelt, rear lt (R & I assy); Seatbelt, front lt (R & I assy); Anchor, childseat te lt (R & I assy) (0.2 Time); Anchor, childseat te rt (R & I assy) (0.2 Time); Pnl, center plr trim lt (R & I assy); Pnl, center plr trim rt (R & I assy); Reinf, roof (R & I assy); Deflector assy, air (R & I assy); Rail, luggage rack lt (R & I assy); Pnl, quarter trim up lt (R & I assy); Pnl, quarter trim up rt (R & I assy); Pnl, quarter trim up lt ( R & I assy); Pnl, quarter trim up rt (R & I assy); Pnl quarter trim up rt (R & I assy); Taillamp assy rt (R & I assy) (0.3 Time); clean for delivery (addnl labor op) (1.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Mask jams (addnl labor op) (0.5 Time); Reset electrical comp (addnl labor op) (0.2 Time); Test drive (addnl labor op) (0.5 Time); Polish paint from pdr (repair) (2.0 Time); Prewash to repair (addnl labor op) (0.5 Time); washer hose D & R (addnl labor op) (0.5 Time); Seal seal hood (addnl labor op) (1.0 Time); harness @ pushbar (addnl labor op) (0.3 Time); A/M parts admin (repair) (1.0 Time); admin charge (addnl labor op)	Fender, front lt (refinish) (2.5 Time); Fender, front rt (refinish) (2.5 Time)	Hardware - bolt & nut (economy part); Refinish mtl required (new part); push bar hardware (economy part); corrosion protection (new part)	Labor - 10.5; Refinish - 5.0	
		11/10/2014	Crawfords Final Invoice								\$ 7,866.56	\$ 1,410.28				
5370	14-2641498-02	9/2/14 & 9/16/14	Estimate/Supplement 1	Progressive	Steven Teague (#273261) - steaugel@progressive.com - 610.496.1412	\$ 5,140.59	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr					
		10/3/2014	Supplement 2	Progressive	Steven Teague (#273261) - steaugel@progressive.com - 610.496.1412	\$ 1,231.11	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Frame - \$48/hr					
		10/20/2014	Crawford's Final Invoice								\$ 8,134.04	\$ 1,762.34		Cover, front bumper (refinish)	Panel, headlamp mtg (new part); Hinge, hood panel lt (new part); Misc hardware (new part); Refinish mtl required (new part); Allied mtl required (new part)	Labor - 6.7
		1/7/2014	Deductible			\$ 100.00	Insured				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr					
			Estimate		Lisa Malin	\$ 1,040.69	Progressive Speciality Insurance Co - check									

Case 6:14-cv-06016-GAP-TBS Document 205-12 Filed 01/08/16 Page 38 of 39 PageID 3205																	
5172	13-1753284-01		Supplement 1			\$ 91.37	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
			Supplement 2			\$ 318.93	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
		12/13/2013	Supplement 3	Progressive	Glenn Schaeffer	\$ 1,549.47	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
		12/24/2013	Supplement 4	Progressive	Jim Underberg	\$ 481.13	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr	Color, sand buff (addnl labor op) (2.0 Time); Cleanup for delivery (addnl labor op) (1.0 Time); Mask Jams (addnl labor op) (0.5 Time); Reset electrical comp (addnl labor op) (0.2 Time	Fender, front rt (refinish); Raw bumper prep (refinish) (1.0 Time)	Cvr, front bumper upr (new part); Cvr, front bumper lwr (new part); Panel, radioar supt (new part); cover for overspray (economy part) (0.2 Time); Masking for primer (economy part) (0.3 Time)	Labor - 3.7; Refinish - 1.0; Parts - 0.5		
		12/31/2013	Supplement 5	Progressive	Jared Unruh	\$ 404.93	Progressive Speciality Insurance Co - check				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
		1/7/2014	Crawford's Final Invoice						\$ 5,130.85	\$ 1,144.43							
5258	14-4518010-01	5/7/2014	Deductible			\$ 750.00	Insured										
		4/18/2014	Estimate	Progressive Advanced Insurance Company	Jared Unruh	\$ 990.41	Progressive Advanced Insurance Company				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
		5/1/2014	Supplement 1	Progressive Advanced Insurance Company	Jared Unruh	\$ 264.06	Progressive Advanced Insurance Company				Body - \$48/hr; Refinish - \$48/hr; Mechanical - \$50/hr						
		5/7/2014	Crawford's Final Invoice						\$ 2,874.52	\$ 870.05			Cover, front bumper (refinish)	Cradle, engine (salvage part) (6.2 Time); Shield, heat (new part); Shield, engine lower (new part); Allied mtl required (new part)	Labor - 3.5; Parts - 6.2		
5232	14-3504937-01	2/25/2014	Estimate	Progressive	Glen Schaeffer (glen_schaeffer@progressive.com)	\$ 2,734.48	Progressive Direct Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Glass - \$48/hr						
		3/13/2014	Supplement 1	Progressive	Glen Schaeffer (glen_schaeffer@progressive.com)	\$ 186.15	Progressive Direct Insurance Co				Body - \$48/hr; Refinish - \$48/hr; Glass - \$48/hr	Mldg, rocker panel lt (R & I assy) (0.4 Time); W/strip, belt outer l/f (R & I assy) (0.5 Time); Handle, front door o lt (R & I assy) (0.3 Time); Pnl, rear door outer lt (R & I assy) (7.0 Time); Glass, rear door r & lt (R & I assy); Rear vent glass (R & I assy); Reinf, rear door inn (R & I assy)	Test panel spray out (refinish) (0.5 Time)	Sound deadner material (economy part) (0.3 Time)	Labor - 8.2; Refinish - 0.5; Parts - 0.3		
		7/7/2014	Crawford's Final Invoice						\$ 4,609.18	\$ 1,688.55			Rail, luggage rack (R & I assy) (0.5 Time); Reg, rear door glass lt (R & I assy); Pnl, inner door trim lt (R & I ass) (0.4 Time); Mldg, front door low lt (R & I assy); Speaker, rear door lt (R & I assy); Clean for delivery (addnl labor op) (1.0 Time); Lower molding alloy wheel (addnl labor op) (3.0 Time); Clean & polish (addnl labor op) (1.0 Time); Disconnect battery (addnl labor op) (0.3 Time); Mask jams (addnl labor op) (0.5 Time); Reset electrical comp (addnl labor op) (0.2 Time); Test drive (addnl labor op) (0.5 Time)	Pillar, windshield lt (blend refinish) (0.5 Time); Panel, bodyside otr lt (blend refinish); Door shell, front lt (refinish); Pnl, rear door outer lt (refinish);	Corrosion protection (new part); L quarter rivets 4 @ 1 (new part) (0.3 Time); Masking for primer (economy part) (0.3 Time)	Labor - 7.4; Refinish - 0.5; Parts - 0.6	
		6/10/2014	Estimate	Progressive	Mike Zogorski	\$ 2,312.81	Progressive Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr						

5303	14-592-6477-02	6/30/2014	Supplment 1	Progressive	Mike Zogorski	\$ 354.36	Advanced Insurance Co				Body - \$48/hr; Refinish - \$48/hr				
		7/21/2014	Crawford's Final Invoice					\$ 3,508.02	\$ 840.85		Admin charge (addnl labor op); Admin charge to rekey (addnl labor op); Mldg assy, wheel opn lt (R & I assy); Mldg, pillar finish lt (R & I assy); Mldg, rear door belt lt (R & I assy); Mldg rear door side lt (R & I assy); Color, sand buff (repair) (2.0 Time); Prefit/measure bolted pnl (addnl labor op) (1.0 Time); Reset electrical comp (addnla labor op) (0.5 Time);		Door shell, front lt (refinish) (2.7 Time); Door shell, rear lt (blend refinish); Lt front fender (blend refinish) (1.9 Time)	Allied matl required (new part); Refinishing mtl required (new part); Mldg, front door low lt (new part); Door shell, front lt (new part)	Labor - 3.5; Refinish - 4.6