

State Farm Insurance Companies
Itemized supplement requests, photos and any applicable invoices should be
emailed to suppteam14@statefarm.com and must be approved by State Farm.
A Supplement Request form may be found on b2b.statefarm.com.
If email is unavailable, you may fax to 844-386-0287.

Victoria 12:07 PM
1/31

*** PRELIMINARY ESTIMATE ***

01/19/2018 09:32 AM

Owner

Owner: MELISSA ARMSTRONG
Address: [REDACTED]
City State Zip: [REDACTED]

Work/Day: [REDACTED]
Cell: [REDACTED]
Home/Evening: [REDACTED]

Control Information

Claim #: [REDACTED]
Loss Date/Time: 12/08/2017 05:00 AM
Deductible: \$250.00

Insured Policy #: [REDACTED]
Loss Type: Collision

Ins. Company: State Farm

Insured: MELISSA ARMSTRONG
Address: [REDACTED]
City State Zip: [REDACTED]

Work/Day: [REDACTED]
Cell: [REDACTED]
Home/Evening: [REDACTED]

Claim Rep: Prop B T1 CS Team
Address: [REDACTED]

Work/Day: [REDACTED]

Inspection

Inspection Date: 01/19/2018 09:31 AM
Inspection Location: Coach Works Auto Body
Address: 30 East Vine Avenue
City State Zip: Mesa, AZ 85210
Primary Impact: Left Rear Side
Driveable: No

Inspection Type: Field
Contact: [REDACTED]
Home/Day: [REDACTED]

Secondary Impact:
Rental Assisted:

Assigned Date/Time:
First Contact Date/Time:

Received Date/Time: 01/18/2018 03:56 PM
Appointment Date/Time: 01/19/2018 09:35 AM

Appraiser Name: DESTINY MVBV

Appraiser License #: [REDACTED]

Repairer

Repairer: Coach Works Auto body
Address: 30 e Vine ave
City State Zip: Mesa, AZ 85210

Contact: [REDACTED]
FAX: [REDACTED]

Vehicle

2013 Nissan Pathfinder SV 4 DR Wagon
6cyl Gasoline 3.5
Continuously Variable Tr

Lic.Plates: [REDACTED]
 Lic Expire: [REDACTED]
 Prod Date:
 Veh Insp# :
 Condition:
 Ext. Color: Cayenne Red
 Ext. Refinish: Two-Stage
 Ext. Paint Code: NAH

Lic State: AZ
 VIN: [REDACTED]
 Mileage: 81,585
 Mileage Type: Actual
 Code: Z7144B
 Int. Color: Almond
 Int. Refinish: Two-Stage
 Int. Trim Code: H

Options - AudaVIN Information Received

1st Row LCD Monitor(s)	2nd Row Head Airbags	3rd Row Head Airbags
AM/FM CD Player	Alarm System	Aluminum/Alloy Wheels
Anti-Lock Brakes	Auto Headlamp Control	Auxiliary Audio Input
Bodyside Cladding	Bucket Seats	Center Console
Compact Spare Tire	Cruise Control	Dual Air Conditioning
Dual Airbags	Electro-Hyd Steering	Floor Mats
Halogen Headlights	Head Airbags	Illuminated Visor Mirror
Intermittent Wipers	Keyless Access System	Keyless Entry System
Keyless Ignition System	Leather Shift Knob	Leather Steering Wheel
Lighted Entry System	Limited Slip Differential	MP3 Decoder
Mud/Splash Guards	Overhead Console	Power Brakes
Power Door Locks	Power Drivers Seat	Power Mirrors
Power Windows	Privacy Glass	Pwr Accessory Outlet(s)
Rear Spoiler	Rear View Camera	Rear Window Defroster
Rear Window Wiper/Washer	Reverse Sensing System	Roof Rails
Side Airbags	Split Folding Rear Seat	Stability Cntrl Suspensn
Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Third Seat (trucks)	Three Zone Climate Ctrl	Tilt & Telescopic Steer
Tire Pressure Monitor	Tow Hooks	Traction Control System
Trip Computer	USB Audio Input(s)	Velour/Cloth Seats
Wireless Phone Connect	XM Satellite Radio	

AudaVIN options are listed in bold-italic fonts

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Roof									
1	RI	954		Airbag,Roof LT	R & I Assembly			4.8	ME
2	RI	359		Mldg,Roof Drip LT	R & I Assembly			0.9	SM
3	RI	1003		Roof Headliner R & I	R & I Assembly			INC	SM
Rear Doors									
4	RI	287		Rear Door R&I LT	R & I Assembly			1.0	SM
5	BR	289	13	Pnl,Rear Door Outer LT	Blend Refinish			2.2	RF
					1.1 Blend				
					0.6 Two-stage setup				
					0.5 Two-stage				
6	RI	334		Mldg,Rear Door Belt LT	R & I Assembly			0.2	SM
7	RI	307		Pnl,Inner Door Trim LT	R & I Assembly			0.1	SM
8	RI	305		Handle,Rr Door Outer LT	R & I Assembly			0.2	SM
Quarter And Rocker Panel									
9	BR	1314		Panel,Bodyside Otr Upr LT	Blend Refinish			1.4	RF
					1.1 Blend				
					0.3 Two-stage				
10	L	389		Panel,Quarter LT	Refinish			4.6	RF
					2.3 Surface				

				1.5 Edge 0.8 Two-stage				
11	EU	389	Pnl,Qtr (in Window Opn LT	RECYCLED PART	\$500.00	+35.00	20.4	SM
			>> Aviation Auto 800-227-9746					
			>> 5231 E. Drexal					
			>> Tucson AZ 85706					
			>> Quote# 121515914274860, Stock# GG388, Henry					
12	BR	397	Door,Fuel Filler LT	Blend Refinish			0.2	RF
				0.1 Blend				
				0.1 Two-stage				
13	RI	397	Door,Fuel Filler LT	R & I Assembly			INC	SM
14	SB	467	Sealant Kit,Qtr Glass LT	Sublet Repair	\$20.00*			SM

Inner Quarter & Panels

15	E	416	07 Pnl,Quarter Inner L/F	766313KA0A	\$216.85		6.4	SM
			High Strength Steel					
16	L	416	Pnl,Quarter Inner L/F	Refinish			1.0	RF
				0.8 Surface				
				0.2 Two-stage				
17	RI	419	Shield,Quarter Inner LT	R & I Assembly			INC	SM
18	RI	1093	Cover,Inner Qtr Trim LT	R & I Assembly			0.2*	SM
19	RI	407	Pnl,Inner Qtr Trim LT	R & I Assembly			INC	SM
20	RI	438	Pnl,Qtr Trim Up Frt LT	R & I Assembly			INC	SM
21	RI	453	Pnl,Qtr Trim Up Rr LT	R & I Assembly			INC	SM

Tailgate

22	BR	479	Shell,Tailgate	Blend Refinish			1.4	RF
				0.9 Blend				
				0.5 Two-stage				
23	RI	479	Tailgate R & I	R & I Assembly			INC	SM
24	RI	503	Mldg,Tailgate	R & I Assembly			0.2	SM
25	E	1102	N/Plate,Tailgate	908963KG0A	\$46.31		0.2	SM
26	E	1185	N/Plate,Tailgate	908953KA0A	\$47.98		0.2	SM
27	RI	488	Tailgate Glass R & I	R & I Assembly			2.4	SM
28	RI	550	Spoiler,Tailgate	R & I Assembly			INC	SM

Rear Bumper

29	PC	566	Cover,Rear Bumper	RECOND PART	\$400.00		1.0	SM
			>> Keystone - Phoenix 800-551-5605					
			>> 5670 S 32nd St.					
			>> Phoenix AZ 85040					
			>> Quote# 121515914274860, Stock# NI1100290R, Sales					
30	L	566	Cover,Rear Bumper	Refinish			2.9	RF
				2.4 Surface				
				0.5 Two-stage				

Rear Body, Lamps And Floor Pan

31	RI	533	Taillamp Assembly,Otr LT	R & I Assembly			INC	SM
32	RI	534	Taillamp Assembly,Otr RT	R & I Assembly			INC	SM
33	RI	535	Taillamp Assembly,Inr LT	R & I Assembly			0.2	SM
34	RI	536	Taillamp Assembly,Inr RT	R & I Assembly			0.2	SM

Manual Entries

35	N		Corrosion Protection	ADDITIONAL OPERATION	\$15.00*		0.5*	SM
36	N		Cover Car Interior	ADDITIONAL OPERATION	\$20.00*			SM
37	E		Flex Additive	New Part	\$3.00*			SM
38	N		Seam Sealer	ADDITIONAL OPERATION	\$20.00*			SM
39	N		Hazardous Waste Removal	ADDITIONAL OPERATION	\$5.00*			SM
40	N		Rope Glass Molding (s)	ADDITIONAL OPERATION			0.3*	SM
			>> Windshield					
41	N		D & R Battery	ADDITIONAL OPERATION			0.2*	ME*
41	Items							

MC	Message
07	STRUCTURAL PART AS IDENTIFIED BY I-CAR
13	INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

Estimate Total & Entries

Gross Parts		\$314.14	
Other Parts		\$960.00	
Paint & Materials	13.7 Hours @ \$30.00	\$411.00	
Line Item Markup		\$175.00	
Parts & Material Total			\$1,860.14
Tax on Parts & Material	@ 8.050%		\$149.74

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$50.00	33.8	0.8	34.6	\$1,730.00
Mech/Elec (ME)	\$75.00	4.8	0.2	5.0	\$375.00
Frame (FR)	\$75.00				
Refinish (RF)	\$50.00	13.7		13.7	\$685.00

Labor Total	53.3 Hours		\$2,790.00
Sublet Repairs		\$20.00	
Gross Total			\$4,819.88
Less: Deductible			\$250.00-
Net Total			\$4,569.88

For more information regarding State Farm's promise of satisfaction relating to new non-original equipment manufacturer (non-OEM) and recycled parts, please visit: <http://st8.fm/7X4> or QR code.



Register online to check the status of your claim and stay connected with State Farm®. To register, go to statefarm.com and select Check the Status of a Claim. If you are already registered, thank you!

Alternate Parts Y/01/01/00/00/00 CUM 01/01/00/00/00 Zip Code: 85285 Phoenix Metro
 Rate Name (01998) AZ Phoenix Mesa Scottsdale

Audatex Estimating 8.0.414 ES 01/19/2018 10:21 AM REL 8.0.414 DT 01/01/2018 DB 01/15/2018
 © 2018 Audatex North America, Inc.

**3.5 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.
 ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.**

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE

MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER
OF YOUR VEHICLE.

Op Codes

* = User-Entered Value	^ = Labor Matches System Assigned Rates	E = New Part
NG = Replace NAGS	EC = ** NON-OEM PART	OE = Replace PXN OE Srpls
UE = Replace OE Surplus	ET = Partial Replace Labor	EP = ** NON-OEM PART
EU = RECYCLED PART	TE = Partial Replace Price	PM = REMAN/REBUILT PART
UM = REMAN/REBUILT PART	L = Refinish	PC = RECOND PART
UC = RECOND PART	TT = Two-Tone	SB = Sublet Repair
N = ADDITIONAL OPERATION	BR = Blend Refinish	I = Repair
IT = Partial Repair	CG = Chipguard	RI = R & I Assembly
P = Check	RP = RP-RELATED PRIOR	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



Estimate Summary Page

DESTINY MVBV

Gross Total	\$4,819.88
Less: Deductible	\$250.00-
Net Total	\$4,569.88

Audatex Estimating 8.0.414 ES 01/19/2018 10:21 AM REL 8.0.414 DT 01/01/2018 DB 01/15/2018
© 2018 Audatex North America, Inc.

FOR YOUR PROTECTION ARIZONA LAW REQUIRES THE FOLLOWING STATEMENT TO APPEAR ON THIS FORM: ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS IS SUBJECT TO CRIMINAL AND CIVIL PENALTIES.

FAILURE TO PRESENT THIS ESTIMATE TO THE REPAIRING GARAGE BEFORE REPAIR MAY RESULT IN ADDITIONAL EXPENSE TO YOU. ANY SUPPLEMENT TO THIS ESTIMATE MUST BE AUTHORIZED BY A STATE FARM REPRESENTATIVE.

NOTICE: REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER.

THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL BY A STATE FARM REPRESENTATIVE.

THIS IS AN ESTIMATE. REPAIR FACILITIES MUST INSPECT THE VEHICLE TO DETERMINE IF ANY REPAIRS NOT LISTED ARE REQUIRED AND TO CONTACT STATE FARM BEFORE MAKING SUCH REPAIRS. REPAIRER ALSO IS RESPONSIBLE FOR CONDUCTING ANY NECESSARY INSPECTION AND SAFETY CHECK PRIOR TO AND AFTER COMPLETING REPAIRS.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

State Farm Insurance Companies
Itemized supplement requests, photos and any applicable invoices should be
emailed to suppteam14@statefarm.com and must be approved by State Farm.
A Supplement Request form may be found on b2b.statefarm.com.
If email is unavailable, you may fax to 844-386-0287.

Recycled Real Steel Locate Report

Owner Name: MELISSA ARMSTRONG

Claim # : [REDACTED]

Vehicle

2013 Nissan Pathfinder SV 4 DR Wagon
6cyl Gasoline 3.5
Continuously Variable Tr

Options

1st Row LCD Monitor(s)	2nd Row Head Airbags	3rd Row Head Airbags
AM/FM CD Player	Alarm System	Aluminum/Alloy Wheels
Anti-Lock Brakes	Auto Headlamp Control	Auxiliary Audio Input
Bodyside Cladding	Bucket Seats	Center Console
Compact Spare Tire	Cruise Control	Dual Air Conditioning
Dual Airbags	Electro-Hyd Steering	Floor Mats
Halogen Headlights	Head Airbags	Illuminated Visor Mirror
Intermittent Wipers	Keyless Access System	Keyless Entry System
Keyless Ignition System	Leather Shift Knob	Leather Steering Wheel
Lighted Entry System	Limited Slip Differential	MP3 Decoder
Mud/Splash Guards	Overhead Console	Power Brakes
Power Door Locks	Power Drivers Seat	Power Mirrors
Power Windows	Privacy Glass	Pwr Accessory Outlet(s)
Rear Spoiler	Rear View Camera	Rear Window Defroster
Rear Window Wiper/Washer	Reverse Sensing System	Roof Rails
Side Airbags	Split Folding Rear Seat	Stability Cntrl Suspensn
Strg Wheel Radio Control	Tachometer	Theft Deterrent System
Third Seat (trucks)	Three Zone Climate Ctrl	Tilt & Telescopic Steer
Tire Pressure Monitor	Tow Hooks	Traction Control System
Trip Computer	USB Audio Input(s)	Velour/Cloth Seats
Wireless Phone Connect	XM Satellite Radio	

Line	Part Description	Year/Make / Notes	VIN?	Cleanup	Supplier ID	Stock #
11	Pnl,Qtr (in Window Opn LT		Y		APU100047	GG388

> = ESTIMATE TOTAL IS BASED ON PRICE QUOTED BY THIS SUPPLIER. REPAIRERS MAY USE THE SUPPLIER OF THEIR CHOICE AND MAY NEGOTIATE SPECIFIC TERMS OF PURCHASE WITH THAT SUPPLIER.

Detailed Distributor List

APU100047 Aviation Auto 800-227-9746 Quote# [REDACTED], Stock# [REDACTED], Henry

Audatex Estimating 8.0.414 ES 01/19/2018 10:21 AM REL 8.0.414 DT 01/01/2018 DB 01/15/2018

Zip Code: 00000 Search Area: Default

© 2018 Audatex North America, Inc.



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.



QUALITY REPLACEMENT PARTS REPORT

Vehicle

2013 Nissan Pathfinder SV 4 DR Wagon
6cyl Gasoline 3.5
Continuously Variable Tr

Options

1st Row LCD Monitor(s) AM/FM CD Player Anti-Lock Brakes Bodyside Cladding Compact Spare Tire Dual Airbags Halogen Headlights Intermittent Wipers Keyless Ignition System Lighted Entry System Mud/Splash Guards Power Door Locks Power Windows Rear Spoiler Rear Window Wiper/Washer Side Airbags Strg Wheel Radio Control Third Seat (trucks) Tire Pressure Monitor Trip Computer Wireless Phone Connect	2nd Row Head Airbags Alarm System Auto Headlamp Control Bucket Seats Cruise Control Electro-Hyd Steering Head Airbags Keyless Access System Leather Shift Knob Limited Slip Differential Overhead Console Power Drivers Seat Privacy Glass Rear View Camera Reverse Sensing System Split Folding Rear Seat Tachometer Three Zone Climate Ctrl Tow Hooks USB Audio Input(s) XM Satellite Radio	3rd Row Head Airbags Aluminum/Alloy Wheels Auxiliary Audio Input Center Console Dual Air Conditioning Floor Mats Illuminated Visor Mirror Keyless Entry System Leather Steering Wheel MP3 Decoder Power Brakes Power Mirrors Pwr Accessory Outlet(s) Rear Window Defroster Roof Rails Stability Cntrl Suspensn Theft Deterrent System Tilt & Telescopic Steer Traction Control System Velour/Cloth Seats
---	---	---

Line	Part Description	Supplier Part Number	Substituted For OEM Part Number	Supplier Code	CLS	SRC
29	Cover,Rear Bumper	NI1100290R	850223KA1H	1	R	3

> = ESTIMATE TOTAL IS BASED ON PRICE QUOTED BY THIS SUPPLIER

Key to Classification / Source Codes

CLS = Classification Code

C - CAPA CERTIFIED PART QUOTED BY LISTED SUPPLIER
M - REMANUFACTURED / REBUILT PART
R - RECONDITIONED PART
S - OEM SURPLUS PART

SRC = Source Code

1 - NON ORIGINAL EQUIPMENT MANUFACTURER PART
3 - ORIGINAL EQUIPMENT MANUFACTURER (OEM) PART

Detailed Distributor List

1	KEYSTONE - PHOENIX 800-551-5605	Quote#	Stock#

Audatex Estimating 8.0.414 ES 01/19/2018 10:21 AM REL 8.0.414 DT 01/01/2018 DB 01/15/2018
Zip Code: 85285 Search Area:

Phoenix Metro

© 2018 Audatex North America, Inc.



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2018 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

