

Claim #:
Workfile ID:

Supplement of Record 2 Summary

Insured: [REDACTED] Owner Policy #: [REDACTED] Claim #: [REDACTED]
Type of Loss: Liability Date of Loss: 03/23/2019 12:00 PM Days to Repair: 9
Point of Impact: 06 Rear Deductible: [REDACTED]

Owner (Claimant):

Inspection Location:

Virtual

Appraiser Information:

Repair Facility:

VEHICLE

2013 FORD C-Max Hybrid SEL 4D H/B 4-2.0L Hybrid Electronic Fuel Injection White Platinum Trico

VIN: [REDACTED] Production Date: [REDACTED] Interior Color: [REDACTED]
License: [REDACTED] Odometer: 78808 Exterior Color: White Platinum Trico
State: NE Condition: Good

TRANSMISSION

Automatic Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat

DECOR

Dual Mirrors
Console/Storage
Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control

Parking Sensors

Home Link

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

SEATS

Bucket Seats

Leather Seats

Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Three Stage Paint

OTHER

Fog Lamps

Traction Control

Stability Control

Rear Spoiler

Signal Integrated Mirrors

California Emissions

Power Trunk/Gate Release

Supplement of Record 2 Summary

2013 FORD C-Max Hybrid SEL 4D H/B 4-2.0L Hybrid Electronic Fuel Injection White Platinum Trico

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	S01	Subl	Pre-Diagnostic Scan	1	150.00 X	0.0	0.0
2	ROOF							
3		S01	R&I	LT Roof molding	0	0.00	0.4	0.0
4	#	S01	Refn	LT Roof rail Clear Only	0	0.00	0.0	0.7
5	#	S01	R&I	Rope Glass	0	0.00	0.3	0.0
6		S02	Repl	LT Roof molding	1	143.23	0.4	0.0
7	PILLARS, ROCKER & FLOOR							
8		S01	R&I	LT Pillar molding	0	0.00	0.3	0.0
9		S01	R&I	LT Vent glass FORD w/black molding	0	0.00	1.1	0.0
10	**	S01	Repl	A/M Glass Installation Kit	1	10.00	0.0 G	0.0
11	QUARTER PANEL							
12	*	S01	Rpr	LT Quarter panel	0	0.00	0.5	2.3
13		S01		Add for Three Stage	0	0.00	0.0	1.6
14	#	S01	Refn	Partial Refinish w/ Full Clear	0	0.00	0.0	-0.3
15	*	S01	R&I	LT Stone guard	0	0.00	0.3	0.0
16		S01	R&I	LT Pillar trim	0	0.00	0.2	0.0
17		S01	R&I	LT Qtr glass Ford black frame	0	0.00	1.3	0.0
				NOTE: LABOR: Time is after pillar trim and trunk side trim are removed.				
18	**	S01	Repl	A/M Glass Installation Kit	1	10.00	0.0 G	0.0
19	REAR BODY & FLOOR							
20		S01	R&I	LT Trunk side trim	0	0.00	0.4	0.0
21	LIFT GATE							
22	*	S01	Rpr	Lift gate	0	0.00	3.5	2.1
				NOTE: time includes inner shell repair .5				
23		S01		Overlap Major Adj. Panel	0	0.00	0.0	-0.4
24		S01		Add for Three Stage	0	0.00	0.0	0.7
25		S01		Add for Edging	0	0.00	0.0	0.6
26	#	S01	Refn	Partial Refinish w/ Full Clear	0	0.00	0.0	-0.3
27		S01	Repl	Nameplate "SEL"	1	13.78	0.2	0.0
28		S01	Repl	Nameplate "C-MAX" from 02/02/2013	1	40.68	0.2	0.0
29		S01	Repl	Nameplate "HYBRID"	1	34.46	0.2	0.0
30		S01	R&I	Release handle w/o rear camera	0	0.00	0.3	0.0
31		S01	R&I	Lower trim panel w/o power lift gate	0	0.00	0.4	0.0
32	#	S01	R&I	Rope Glass	0	0.00	0.5	0.0
				NOTE: liftgate glass				
33	#	S01	R&I	License plate	0	0.00	0.1	0.0
34	REAR LAMPS							
35		S01	R&I	LT Tail lamp assy	0	0.00	0.3	0.0

Claim #:

Workfile ID:

Supplement of Record 2 Summary

2013 FORD C-Max Hybrid SEL 4D H/B 4-2.0L Hybrid Electronic Fuel Injection White Platinum Trico

36	S01	R&I	RT Tail lamp assy	0	0.00	0.3	0.0
37	S01	R&I	LT Tail lamp assy	0	0.00	Incl.	0.0
38	REAR BUMPER						
39	S01		O/H rear bumper	0	0.00	1.9	0.0
40	**		Repl A/M CAPA Valance	1	115.00	Incl.	0.0
41	S01		Repl Park sensor	1	80.78	0.2	0.2
42	S01		Add for Three Stage	0	0.00	0.0	0.1
43	S01		Repl LT Rear bracket outer	1	26.89	0.0	0.2
44	S01		Add for Three Stage	0	0.00	0.0	0.1
45	** <>	S01	Repl A/M CAPA Bumper cover	1	376.00	Incl.	2.8
46		S01	Overlap Major Non-Adj. Panel	0	0.00	0.0	-0.2
47		S01	Add for Three Stage	0	0.00	0.0	1.0
48		S01	Add for distance sens	0	0.00 m	0.4	0.0
49		S01	Drill for all sensors	0	0.00	0.5	0.0
50		S02	Repl Energy absorber	1	68.48	Incl.	0.0
51		S02	Repl Impact bar (BOR)	1	220.27	0.6	0.0
52	MISCELLANEOUS OPERATIONS						
53	**	S01	Repl A/M Cover Car	1	5.00	0.0	0.0
54	#	S01	Rpr Mask Jambs	0	0.00	0.3	0.0
55	#	S01	Repl Corrosion Protection	1	0.00	0.2	0.0
56	**	S01	Repl A/M Flex Additive	1	10.00	0.0	0.0
57	#	S02	Rpr Color Tint - major	0	0.00	0.0	1.0
58	**	S02	Repl A/M Clean and Retape Mouldings	1	2.00	0.3	0.0
59	#	S02	Subl Post-Diagnostic Scan	1	150.00	0.0	0.0
60	OTHER CHARGES						
61	#		E.P.C.	1	3.00		
SUBTOTALS					1,459.57	15.6	12.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,306.57
Body Labor	15.6 hrs @	\$ 58.00 /hr	904.80
Paint Labor	12.2 hrs @	\$ 58.00 /hr	707.60
Paint Supplies	12.2 hrs @	\$ 42.00 /hr	512.40
Miscellaneous			150.00
Other Charges			3.00
Subtotal			3,584.37
Sales Tax	\$ 2,529.57 @	7.0000 %	177.07
Total Cost of Repairs			3,761.44
Total Adjustments			0.00
Net Cost of Repairs			3,761.44

MyPriceLink Estimate ID / Quote ID: