

Claim #:
Workfile ID:

Estimate of Record

Insured: [REDACTED] Owner Policy #: [REDACTED] Claim #: [REDACTED]
Type of Loss: — Liability Date of Loss: 03/23/2019 12:00 PM Days to Repair: 2
Point of Impact: 06 Rear Deductible: [REDACTED]

Owner (Claimant): **Inspection Location:** **Appraiser Information:** **Repair Facility:**

[REDACTED]

VEHICLE

2013 FORD C-Max Hybrid SEL 4D H/B 4-2.0L Hybrid Electronic Fuel Injection White Platinum Trico

VIN: [REDACTED] Production Date: [REDACTED] Interior Color: [REDACTED]
License: [REDACTED] Odometer: 78808 Exterior Color: White Platinum Trico
State: NE Condition: [REDACTED]

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

Power Driver Seat

DECOR

Dual Mirrors

Console/Storage

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control

Parking Sensors

Home Link

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

Auxiliary Audio Connection

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

SEATS

Bucket Seats

Leather Seats

Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps

Traction Control

Stability Control

Rear Spoiler

Signal Integrated Mirrors

California Emissions

Power Trunk/Gate Release

Estimate of Record

2013 FORD C-Max Hybrid SEL 4D H/B 4-2.0L Hybrid Electronic Fuel Injection White Platinum Trico

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		QUARTER PANEL					
2	*	Rpr LT Quarter panel NOTE: Clean/polish scuff		0	0.00	0.1	<u>0.0</u>
3		LIFT GATE					
4	*	Rpr Lift gate NOTE: Clean/polish scuff		0	0.00	0.1	<u>0.0</u>
5		REAR BUMPER					
6	* <>	Repl RCY bumper assy +25%		1	319.75	1.0	2.8
7		Add for Clear Coat		0	0.00	0.0	1.1
8	**	Repl A/M CAPA Valance		1	115.00	0.4	0.0
9	*	R&I Park sensor		0	0.00	0.2	0.0
10		Repl RT Rear bracket outer		1	24.07	0.0	0.2
11		Add for Clear Coat		0	0.00	0.0	0.1
12		OTHER CHARGES					
13	#	E.P.C.		1	3.00		
SUBTOTALS					460.82	1.8	4.2

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			457.82
Body Labor	1.8 hrs @	\$ 58.00 /hr	104.40
Paint Labor	4.2 hrs @	\$ 58.00 /hr	243.60
Paint Supplies	4.2 hrs @	\$ 42.00 /hr	176.40
Other Charges			3.00
Subtotal			985.22
Sales Tax	\$ 880.82 @	7.0000 %	61.66
Total Cost of Repairs			1,046.88
Total Adjustments			0.00
Net Cost of Repairs			1,046.88

MyPriceLink Estimate ID / Quote ID: