# LIBERTY MUTUAL INSURANCE COMPANY 114 TURNPIKE ROAD WESTBORO, MA 01581-5103

REQUEST A SUPPLEMENT 24/7 AT WWW.SCA-APPRAISAL.COM OR AT \*\*PLEASE REVIEW ESTIMATE AND RENTAL INSTRUCTIONS LISTED BELOW\*\*

# \*\*\* ESTIMATE \*\*\*

07/19/2019 05:45 PM

Owner

Owner: Suzanne Corbett

Address:

City State Zip:

Email:

Home/Day: Work/Day: Cell:

**Control Information** 

Claim #: -0001

Loss Date/Time: 06/21/2019 07:00 AM

Deductible: \$250.00 File #:

Ins. Company: Liberty Mutual Company Contact: Liberty Mutual

Address:

Agent: n/a

Insured: Suzanne Corbett

Address:

City State Zip:

Email:

Claim Rep: MATTHEW STEIN

Address:

Insured Policy #:

Loss Type: Collision

Accounting #:

Work/Day:

Home/Day: Work/Day: Cell:

Work/Day:

Inspection

Inspection Date: 07/19/2019 05:40 PM **Inspection Location:** hunter auto body

Address: 8014 Gravois Rd.

City State Zip: Saint Louis, MO 63123

Primary Impact: Right Rear Side

Driveable: Yes

**Assigned Date/Time:** 

First Contact Date/Time:

**Inspection Type:** Independent Field

Contact: Work/Dav:

FAX:

Secondary Impact:

Rental Assisted:

Received Date/Time: 07/19/2019 05:32 PM Appointment Date/Time: 07/18/2019 07:00 AM

Appraiser Name: jason boschert Appraiser License #:

Address:

City State Zip: Burbank, CA 91505

Work/Day:

FAX:

Repairer

Repairer: hunter auto body

Address: 8014 Gravois Rd,

City State Zip: Saint Louis, MO 63123

Contact:

Work/Day:

FAX:

07/19/2019 05:54 PM Page 1 of 5

#### **Target Complete Date/Time:**

# Days To Repair: 3

### **Vehicle**

2017 Volkswagen Jetta 1.4T SE 4 DR Sedan 4cyl Gasoline Turbo 1.4 Automatic Tiptronic

Lic.Plate:
Lic Expire:
Prod Date:
Veh Insp#:
Condition: Good
Ext. Color: black
Ext. Refinish: Two-Stage

Lic State: MO
VIN:
Mileage: 23,261
Mileage Type: Actual
Code: 61663C

Int. Color: Int. Refinish:

#### **Options**

16 Inch Alloy Wheels 1st Row LCD Monitor(s) 2nd Row Head Airbags AM/FM CD Player Air Conditioning **Analog Gauges** Anti-Lock Brakes **Auxiliary Audio Input** Blind Spot Sensor Carpeting **Bucket Seats** Center Console Cross Traffic Alert Cruise Control Daytime Running Lights Digital Clock **Dual Airbags** Elect. Stability Control **Electric Steering** Emergency S.O.S. System Ext Mirror Turn Signals Full Size Spare Tire Halogen Headlights **Head Airbags Heated Power Mirrors** Heated W/S Wiper Washers **Heated Front Seats High Definition Radio IPOD Control** Intermittent Wipers Keyless Access System Keyless Entry System Keyless Ignition System **LED Brakelights** Leather Steering Wheel Lighted Entry System Overhead Console Power Brakes MP3 Decoder Power Door Locks Power Moonroof **Power Windows** Pwr Accessory Outlet(s) Rear Collisn Mitigation Rear View Camera Rear Window Defroster Rem Trunk-L/Gate Release Side Airbags SiriusXM Satellite Radio Split Folding Rear Seat Strg Wheel Radio Control Tilt & Telescopic Steer Theft Deterrent System **Tinted Glass** Tire Pressure Monitor Touch Screen Display Traction Control System **Trip Computer** Vehicle Tracking Service USB Audio Input(s) Vinyl Seats Wireless Audio Streaming Wireless Phone Connect

| Damages |
|---------|
|         |

| Line   | Ор          | Guide     | MC          | Description                     | MFR.Part No.   | Price | ADJ% B% | Hours | R  |
|--------|-------------|-----------|-------------|---------------------------------|----------------|-------|---------|-------|----|
|        |             |           |             |                                 |                |       |         |       |    |
| Rear D | <u>oors</u> |           |             |                                 |                |       |         |       |    |
| 1      | I           | 420       |             | Door Shell,Rear RT              | Repair         |       |         | 1.0*  | SM |
| 2      | L           | 420       | 10          | Door Shell,Rear RT              | Refinish       |       |         | 1.4*  | RF |
|        |             |           |             | >> time reduced to paint within |                |       |         |       |    |
| 3      | RI          | 324       |             | Mldg,Rear Door Belt RT          | R & I Assembly |       |         | INC   | SM |
| 4      | RI          | 328       |             | Pnl,Inner Door Trim RT          | R & I Assembly |       |         | 0.4   | SM |
| 5      | RI          | 355       |             | Channel, Rear Glass Run RT      | R & I Assembly |       |         | 1.4   | SM |
| 6      | RI          | 306       |             | Handle,RR Door Outer RT         | R & I Assembly |       |         | 0.3   | SM |
|        |             |           |             |                                 |                |       |         |       |    |
| Quarte | r And       | Rocker Pa | <u>anel</u> |                                 |                |       |         |       |    |
| 7      | BR          | 48        | 13          | Panel,Bodyside Otr Upr RT       | Blend Refinish |       |         | 1.9   | RF |
| 8      | - 1         | 495       |             | Panel,Quarter RT                | Repair         |       |         | 3.0*  | SM |

07/19/2019 05:54 PM Page 2 of 5

| 2017 Volkswagen Jetta 1.4T SE 4 DR Claim #: | Sedan   |                               |   |                |          |       |                                | 07/19/    | 2019 05:45 PI |
|---|---|-------------------------------|---|----------------|----------|-------|--------------------------------|-----------|---------------|
| 9 L 495                                     | •   |                               |   |                | Refinish |       |                                |           | RF            |
|   | >> time reduced to paint within the panel with full clearcoat |                               |   |                |          |       |                                |           |               |
| 10 RI 397                                   | Door,Fuel Fill  | er RT                         | R & I As                                  | R & I Assembly |          |       |                                | 0.3       | SM            |
| Rear Bumper<br>11 N 566                     | Rear Bumper   | Additional Labor              |   |                |          |       | 1.3                            | SM        |               |
| Rear Body, Lamps And                        |   | 0, 57                         | D 0 1 1                                   |                |          |       |                                | 11.10     | 01.4          |
| 12 RI 534                                   | Taillamp Asse   | R & I As                      | R & I Assembly                            |                |          |       | INC                            | SM        |               |
| Manual Entries  13 SB M60  14 N  14 Items   | Hazardous W pre/post collis                                   |                               | Sublet Repair \$3.00*<br>Additional Labor |                |          |       | 1.5*                           | SM<br>ME* |               |
|   | MC N  | lessage                       |   |                |          |       |                                |           |               |
|   | 13 IN   | NCLUDES AUDA<br>NCLUDES 0.6 H |   |                |          |       | VANCE                          |           |               |
| Estimate Total & Entri                      | es  |                               |   |                |          |       |                                |           |               |
| Paint & Materials Parts & Material Total    | 4.8 Hours @ \$34.00 \$163.20                                  |                               |   |                |          | 63.20 | ¢402.20                        |           |               |
| Tax on Parts & Material                     |   |                               | @ 7.730%                                  |                |          |       | \$163.20<br>\$12.62            |           |               |
| Labor                                       | Rate  | Replace Rep                   | air Hrs 1                                 | otal Hrs       |          |       |                                |           |               |
| Sheet Metal (SM)                            | \$62.00   | 2.4                           | 5.3                                       | 7.7            | \$477.4  |       |                                |           |               |
| Mech/Elec (ME)                              | \$85.00   |                               | 1.5                                       | 1.5            | \$127.5  | 0     |                                |           |               |
| Frame (FR)<br>Refinish (RF)                 | \$62.00<br>\$62.00  | 4.8                           |   | 4.8            | \$297.6  | 0     |                                |           |               |
| Labor Total                                 |   |                               | 14.0 Hours                                |                |          | _     | \$902.50                       |           |               |
| Sublet Repairs                              |   |                               |   |                | 9        | 3.00  |                                |           |               |
| Gross Total<br>Less: Deductible             |   |                               |   |                |          |       | <b>\$1,081.32</b><br>\$250.00- |           |               |

\$831.32

Alternate Parts Y/00/00/00/00/00 CUM 00/00/00/00 Zip Code: 91507 Geo 91507 Recycled Parts NOT REQUESTED Rate Name Default

**Net Total** 

Audatex Estimating 8.0.643 ES 07/19/2019 05:54 PM REL 8.0.643 DT 07/01/2019 DB 07/15/2019 © 2019 Audatex North America, Inc.

1.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.

REPAIRER: THIS IS NOT A REPAIR AUTHORIZATION. AUTHORIZATION CAN ONLY COME FROM VEHICLE OWNER AFTER THE INSURANCE CO HAS ACCEPTED THE ESTIMATE AND HAS AGREED TO PAY. DO NOT ORDER PARTS OR START REPAIRS UNTIL A TEARDOWN OR FULL DAMAGE ASSESSMENT IS DONE. IF ADDITIONAL DAMAGE IS SEEN NOT INCLUDED IN THIS ESTIMATE OR YOU DO NOT AGREE WITH ANY ENTRIES, DO NOT START REPAIRS OR ORDER ANY PARTS UNTIL APPRAISER HAS WRITTEN A SUPPLEMENT, THE INSURER HAS ACCEPTED AND AGREED

07/19/2019 05:54 PM Page 3 of 5

### TO PAY SUPPLEMENT AND THE VEHICLE OWNER HAS GIVEN AUTHORIZATION TO PROCEED.

ALL COMPLETED APPRAISALS ARE SUBJECT TO INSURANCE COMPANY REVIEW AND APPROVAL PRIOR TO THE COMPANY ACCEPTING THE APPRAISAL AS A REPAIR AGREEMENT.ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH THE PREPARATION OF THIS ESTIMATE MAY HAVE BEEN BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. THERE ARE WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS.

THESE WARRANTIES ARE PROVIDED BY THE MANAFACTURER AND/OR DISTRIBUTOR OF THE PARTS RATHER THAN BY THE ORIGINAL MANUFACTURER OF YOUR VEHICLE. THIS IS NOT AN AUTHORIZATION TO REPAIR, AUTHORIZATION MUST COME FROM THE VEHICLE OWNER. PRESENT THIS APPRAISAL TO THE REPAIRING SHOP BEFORE REPAIRS BEGIN. WE RESERVE THE RIGHT TO INSPECT ANY ADDITIONAL DAMAGE BEFORE CONSIDERING PAYMENT OF SUPPLEMENTAL CHARGES. NO SUPPLEMENT WILL BE HONORED UNLESS AUTHORIZED.

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD ANY INSURANCE COMPANY OR OTHER PERSON FILES AN APPLICATION FOR COMMERCIAL INSURANCE OR A STATEMENT OF CLAIM FOR ANY COMMERCIAL OR PERSONAL INSURANCE BENEFITS CONTAINING ANY MATERIALLY FALSE INFORMATION, OR CONCEALS FOR THE PURPOSE OF MISLEADING, INFORMATION CONCERNING ANY FACT MATERIAL THERETO, AND ANY PERSON WHO, IN CONNECTION WITH SUCH APPLICATION OR CLAIM, KNOWINGLY MAKES OR KNOWINGLY ASSISTS, ABETS, SOLICITS OR CONSPIRES WITH ANOTHER TO MAKE A FALSE REPORT OF THE THEFT, DESTRUCTION, DAMAGE OR CONVERSION OF ANY MOTOR VEHICLE TO A LAW ENFORCEMENT AGENCY, THE DEPT OF MOTOR VEHICLES OR AN INSURANCE COMPANY, COMMITS A FRAUDULENT INSURANCE ACT, WHICH IS A CRIME, AND SHALL ALSO BE SUBJECT TO A CIVIL PENALTY AS ALLOWED BY THE ACTUAL STATE MANDATED LAW AND OR AS DIRECTED BY THE ACTUAL STATE DOI REGULATIONS AND THE VALUE NOT TO EXCEED THE VALUE OF THE SUBJECT MOTOR VEHICLE OR STATED CLAIM FOR EACH VIOLATION.

# RENTAL

IF YOU HAVE RENTAL COVERAGE OR ARE ENTITLED TO A RENTAL DUE TO THIS LOSS, RENTAL WILL BE ALLOWED FOR THE REASONABLE PERIOD NECESSARY TO REPAIR YOUR VEHICLE, SUBJECT TO ANY APPLICABLE POLICY PROVISIONS, LAWS OR REGULATIONS. IF A RENTAL VEHICLE HAS NOT BEEN PRE-AUTHORIZED OR YOU HAVE ANY QUESTIONS REGARDING YOUR RENTAL COVERAGE OR ELIGIBILITY, PLEASE CONTACT YOUR ADJUSTER PRIOR TO SECURING A RENTAL VEHICLE.

ADDITIONAL RENTAL COSTS OFFERED THROUGH THE RENTAL AGENCY ARE NOT COVERED.

### **Op Codes**

= User-Entered Value EC = Replace Economy ET = Partial Replace Labor TE = Partial Replace Price = Refinish TT = Two-Tone

BR = Blend Refinish CG = Chipquard

AA = Appearance Allowance

E = Replace OEM

OE = Replace PXN OE Srpls

EP = Replace PXN

PM= Replace PXN Reman/Reblt PC = Replace PXN Reconditioned

SB = Sublet Repair

I = Repair

RI = R & I Assembly

RP = Related Prior Damage

NG = Replace NAGS

UE = Replace OE Surplus

EU = Replace Recycled

UM= Replace Reman/Rebuilt

UC = Replace Reconditioned

N = Additional Labor

IT = Partial Repair

P = Check

07/19/2019 05:54 PM Page 4 of 5



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

# © 2019 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

Solero

07/19/2019 05:54 PM Page 5 of 5